

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21009771/GVY3E2

Date: 15/09/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29138567ATM		
Claimant Vehicle No :	SMW2350B	Insured Vehicle No :	SKZ265K		
Date of Loss:	17/09/2021	Nature of Claim:	TP	Claim No:	638047

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW2350B	Engine No:	27091031925211
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Chassis No:	WDC1569422J670195
Reg. Date:	10/11/2020 (Man. Year: 2019)	Odometer:	12684 km
Colour:	Red		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,298.10	11,586.40	2,711.70	18.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,680.00	980.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,958.10	13,266.40	3,691.70	21.77
+ GST 7.00/7.00% (S\$)	1,187.07	928.65	258.42	21.77
Nett Amount (S\$)	18,145.17	14,195.05	3,950.12	21.77

INSPECTION

Date of Assignment:	20/09/2021	
Date Inspected:	20/09/2021	Inspected At: Vin's Auto Pte Ltd (Vin's Auto) Sin Ming AutoCity,, 160 Sin Ming Drive #03-03 Singapore 575722
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2022)

Parts: M1-SUV MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMW2350B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,711.00 FL	*1,711.00 FL
2	1		*REAR TAILGATE EMBLEM	Necessary	43.00 FL	*43.00 FL
3	1		*REAR TAILGATE GLA 180 EMBLEM	Necessary	81.00 FL	*81.00 FL
4	1		*REAR TAILGATE LH REFLECTOR	Cut	475.00 FL	*475.00 FL
5	1		*REAR TAILGATE RUBBER	Twisted	202.00 FL	*202.00 FL
6	1		*REAR TAILGATE LOCK	Damaged	256.00 FL	*256.00 FL
7	1		*REAR LH TAILLAMP	Cracked	645.00 FL	*645.00 FL
8	1		*REAR BUMPER	Deformed	932.00 FL	*932.00 FL
9	1		*REAR BUMPER TOP CHROME MOULDING	Deformed	190.00 FL	*190.00 FL
10	1		*REAR BUMPER CENTRE PAD	Distorted	510.00 FL	*510.00 FL
11	1		*REAR BUMPER LOWER PAD	Distorted	730.00 FL	*730.00 FL
12	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	20.00 FL	*- FL
13	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	20.00 FL	*- FL
14	1		*REAR BUMPER INNER CENTRE BRACKET	Bent	63.00 FL	*63.00 FL
15	1		*REAR BUMPER RH SIDE BRACKET	Not Necessary	57.00 FL	*- FL
16	1		*REAR BUMPER LH SIDE BRACKET	Cracked	57.00 FL	*57.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	532.00 FL	*532.00 FL
18	10		*REAR BUMPER CLIPS	Necessary	700.00 FL	*40.00 FL
19	1		*REAR END PANEL	Repair	1,147.00 FL	*- FL
20	1		*REAR END PANEL TOP TRIM	Deformed	90.00 FL	*90.00 FL
21	1		*REAR EXHAUST SILENCER	Bent	1,100.00 FL	*1,100.00 FL
22	1		*REAR EXHAUST SILENCER RH CHROME	Not Necessary	244.00 FL	*- FL
23	1		*REAR EXHAUST SILENCER LH CHROME	Bent	244.00 FL	*244.00 FL
24	1		*REAR EXHAUST SILENCER RH CHROME BRACKET	Not Necessary	95.00 FL	*- FL
25	1		*REAR EXHAUST SILENCER LH CHROME BRACKET	Bent	95.00 FL	*95.00 FL
26	1		*REAR EXHAUST SILENCER LH RUBBER BUSH	Bent	35.00 FL	*35.00 FL
27	1		*REAR EXHAUST SILENCER HEAT SHIELD	Buckled	116.00 FL	*116.00 FL
28	1		*REAR LH FENDER INNER SHIELD	Cut	165.00 FL	*165.00 FL
29	10		*REAR LH FENDER INNER SHIELD CLIPS	Necessary	700.00 FL	*30.00 FL
30	1		*REAR LH LOWER ARM	Bent	185.00 FL	*185.00 FL
31	1		*REAR AXLE	Bent	3,100.00 FL	*3,100.00 FL
32	1		*REAR BUMPER PARKING SENSOR	Damaged	280.00 FS	*200.00 FS
33	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*50.00 FS
34	2		*REAR BUMPER BRACKET	Bent	116.00 FL	*116.00 FL
35	1		*REAR BUMPER TOP BRACKET	Bent	63.00 FL	*63.00 FL
36	1		*REAR WINDSCREEN WITH MOULDING	Necessary	790.00 FL	*790.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,849.00	12,846.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,550.90	1,259.60
Total Parts (\$\$)	14,298.10	11,586.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
2	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
3	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	280.00	200.00
4	TO REPAIR DAMAGES	New	880.00	500.00
5	TO SPRAY PAINTING	New	1,200.00	800.00
Gross Labour Cost (\$)			2,660.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >