

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21009772/R1VCN2**Date:** 29/10/2021**REFERENCE**

Insured/Claimant: HPC BUILDERS PTE LTD Policy No: DMPCSNW00150792001

Date of Loss: 06/09/2021

Nature of Claim: OD

Claim No: SNM21D205059/C1/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJP9088K**

Make & Model: PORSCHE PANAMERA, 3.6 PDK (A)

Engine No: 023902

Reg. Date: 07/11/2018 (Man. Year: 2018)

Chassis No: WP0ZZZ97ZJL117689

Colour: White

Odometer: 20296 km

Engine Capacity: 2995 cc

Market Value/New Car Price: S\$373,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35ZR21

Rear Tyre Size:

275/35ZR21

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,626.20	5,598.70	3,027.50	35.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,070.00	3,860.00	2,210.00	36.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,696.20	9,458.70	5,237.50	35.64
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	12,696.20	7,458.70	5,237.50	41.25
+ GST 7.00/7.00% (S\$)	888.73	522.11	366.62	41.25
Nett Amount (S\$)	13,584.93	7,980.81	5,604.12	41.25

INSPECTION

Date of Assignment: 19/09/2021

Date Inspected: 22/09/2021 Inspected At:

Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)

27A Tanjong Penjuru

Singapore 609042

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2021)
Parts:	144	PORSCHE PANAMERA 3.6 PDK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP9088K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	2,237.60 FS	*2,237.60 FS
2	1		*FRONT GRILLE CENTER	Scratched	308.50 FS	*308.50 FS
3	1		*FRONT GRILLE LH	Cracked	129.00 FS	*129.00 FS
4	1		*FRONT GRILLE LH OUTER TRIM	Scratched	99.30 FS	*99.30 FS
5	1		*FRONT GRILLE DISC SUPPORT LH	Serviceable	94.50 FS	*- FS
6	1		*FRONT GRILLE LH DISC	Scratched	127.70 FS	*127.70 FS
7	1		*HOUSING FOR CAMERA	Serviceable	43.00 FS	*- FS
8	6		*SENSOR	Serviceable	1,511.40 FS	*- FS
9	6		*SENSOR GASKET	Necessary	18.60 FS	*18.60 FS
10	1		*NUMBER PLATE BRACKET	Missing	85.00 FS	*85.00 FS
11	1		*HEADLIGHT BRACKET LH	Serviceable	85.80 FS	*- FS
12	1		*FRONT BUMPER RETAINER LH	Serviceable	38.80 FS	*- FS
13	2		*FIXING DEVICE	Necessary	27.40 FS	*27.40 FS
14	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,099.90 FS	*- FS
15	1		*FRONT BUMPER SPONGE	Serviceable	83.90 FS	*- FS
16	1		*ADDITIONAL HEADLAMP LH	Scratched	757.30 FS	*757.30 FS
17	1		*DISC CARRIER BLACK MAT	Cracked	854.20 FS	*854.20 FS
18	1		*AIR DUCT	Cracked	414.90 FS	*414.90 FS
19	2		*ANTENNA	Necessary	449.20 FS	*449.20 FS
20	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
21	1		*FRONT LICENCE PLATE WITH CASING	Cracked	70.00 FS	*70.00 FS
22	1		*SUPPORT BRACKET FOR CAMERA	Serviceable	40.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,626.20	5,598.70
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/REPLACE FRONT BUMPER,REINFORCEMENT & ALL DAMAGED BODY PARTS.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,120.00	1,560.00
2	TO RESPRAY FRONT BUMPER	New	1,500.00	1,300.00
3	TO TRANSFER THE FRONT SENSORS	New	300.00	150.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
6	TO TRANSFER THE FRONT CAMERA	New	300.00	100.00
Gross Labour Cost (S\$)			6,070.00	3,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >