1000V

GX80697. 2004 Sept. Tojota Liteace. 2184 cc

CR425010555

Front Bumper Deformed 30.(SN) Frant Burger Clips. Her 32.50 X Front Bunger Side Holder Ltt 166.80 Headlesp Garrish LH. at 188.80 Front LH Signal Lamp. Cut 592.30 Front LH Fender Dented New 167.40 X Front LH Fender Inner Shield Front 2H Fender Inner Shield Clips Mr 30 (SN) X. Front LH Mudflap. Lt. 75.90 First LH Door Repis New New First LH Door Company Detail Stideer. Bo(SN)

151590 S.N: 60.

GX8069R.

Parel Beating.

Spray Painting

Wiring

To transfer front door Littings

1030

4694.30

total: 223682-04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1.8K