



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 8069R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	492.10	492.10
1	FRONT BUMPER SIDE HOLDER LH (CONSISTENT)	NOT NECESSARY	32.50	-
1	HEADLAMP GARNISH LH (CONSISTENT)	CUT	166.80	166.80
1	FRONT LH SIGNAL LAMP (CONSISTENT)	CUT	188.80	188.80
1	FRONT LH FENDER (CONSISTENT)	DENTED	592.30	592.30
1	FRONT LH FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	167.40	-
1	FRONT LH MUDFLAP (CONSISTENT)	CUT	75.90	75.90
1	FRONT LH DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,268.50	-
	LESS 25% DISCOUNT		-	-378.98
			2,984.30	1,136.92
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT LH FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT LH DOOR COMPANY DETAIL STICKER (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			100.00	70.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR.		800.00	500.00
	SPRAY PAINTING.		600.00	500.00
	WIRING.		50.00	30.00
	TO TRANSFER FRONT DOOR FITTINGS.	NOT NECESSARY	150.00	-
			1,600.00	1,030.00
	GRAND TOTAL		4,684.30	2,236.92



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	-----------------

Report Ref No. CS/ASM21009774/Avce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.