

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009775/VRS3Q2**Date:** 19/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800063102-03
Claimant Vehicle No :	SHD3744B	Insured Vehicle No :	SMA2041J
Date of Loss:	17/09/2021	Nature of Claim:	TP
		Claim No:	2222477711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3744B		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2G75061
Reg. Date:	28/02/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FUX03091159
Colour:	Blue	Odometer:	161578 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,511.72	848.67	663.05	43.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,331.72	1,478.67	853.05	36.58
+ GST 7.00/7.00% (S\$)	163.22	103.51	59.71	36.58
Nett Amount (S\$)	2,494.94	1,582.18	912.76	36.58
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$126.47/day) (S\$)		379.41		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,113.59		

INSPECTION

Date of Assignment:	20/09/2021	
Date Inspected:	20/09/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	458.60 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	318.80 FL	*- FL
3	1		*REAR BUMPER LOWER COVER-BLACK	Scratched	552.60 FL	*552.60 FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REAR BUMPER TOW COVER	Scratched	82.70 FL	*82.70 FL
6	1		*REVERSE SENSOR	Cut	135.70 FS	*135.70 FS
7	1		*REAR BUMPER MAT	Serviceable	50.00 FS	*- FS
8	2		*REAR FENDER ADV.STICKER RH/LH	Necessary	200.00 FS	*200.00 FS
9	1		*REAR BUMPER ADV.STICKER	Necessary	50.00 FS	*20.00 FS
					Sub Total (\$\$)	1,870.401,013.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	358.68164.33
					Total Parts (\$\$)	1,511.72848.67

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (S\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >