

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21009779/UEA3Q2  
**Date:** 29/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800145583
<b>Claimant Vehicle No :</b>	SMY4018M	<b>Insured Vehicle No :</b>	SMG1297M
Date of Loss:	17/09/2021	Nature of Claim:	TP
		Claim No:	9131603368SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMY4018M</b>	Engine No:	P520452248
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8H0159728
Reg. Date:	16/06/2017 (Man. Year: 2017)	Odometer:	112838 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,561.00	5,214.40	8,346.60	61.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	2,290.00	1,010.00	30.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,861.00</b>	<b>7,504.40</b>	<b>9,356.60</b>	<b>55.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		

## Adjuster Report

(S\$)	16,861.00	6,000.00	10,861.00	64.41
<b>+ GST 7.00/7.00% (S\$)</b>	1,180.27	420.00	760.27	64.41
<b>Nett Amount (S\$)</b>	<b>18,041.27</b>	<b>6,420.00</b>	<b>11,621.27</b>	<b>64.41</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>7,122.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,120.00</b>		

INSPECTION

Date of Assignment: 20/09/2021

Date Inspected: 20/09/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	1,255.80 F	*1,248.30 FL
2	1		*BOOTLID REAR LOGO	Necessary	65.80 F	*65.80 FL
3	1		*BOOTLID MAZDA EMBLEM	Necessary	52.00 F	*52.00 FL
4	1		*BOOTLID 3 EMBLEM	Necessary	45.00 F	*45.00 FL
5	1		*BOOTLID SKYACTIVE EMBLEM	Necessary	68.00 F	*68.00 FL
6	2		*BOOTLID REFLECTORS	Serviceable	1,350.00 F	*- FL
7	1		*BOOTLID INNER LOCK	Twisted	288.20 F	*164.60 FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	291.40 F	*188.20 FL
9	1		*REAR BUMPER	Dented	1,215.10 F	*1,061.30 FL
10	2		*REAR BUMPER TOW COVERS	Missing	50.00 F	*50.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Dented	745.20 F	*537.30 FL
12	2		*REAR BUMPER REFLECTORS	Cracked	150.00 F	*97.00 FL
13	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR BUMPER LICENCE PLATE LAMP	Not Necessary	108.00 F	*- FL
16	2		*TAILLAMPS	Cracked	2,500.00 F	*1,830.00 FL
17	1		*REAR END PANEL	Dented	635.00 F	*435.70 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	366.50 F	*262.30 FL
19	2		*REAR FENDER INNER TRIMS	Not Necessary	610.00 F	*- FL
20	2		*REAR FENDERS	Repair	2,310.00 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	415.00 F	*- FL
22	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
24	1		*REAR LICENCE PLATE	Scratched	50.00 FS	*40.00 FS
25	1		*SET REAR REVERSE CAMERA	Serviceable	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,561.00</b>	<b>6,445.50</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	1,231.10
<b>Total Parts (\$)</b>	<b>13,561.00</b>	<b>5,214.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	100.00
5	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	100.00	80.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	800.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,300.00</b>
				<b>2,290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >