

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / (P) WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: *SMY 4018M*  
 at Workshop m/s *M.*  
 of \_\_\_\_\_  
 Insured: *SMG 1287M*  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: *SMY 4018M* Yr Regn: *16/6/17*  
 Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or *CA /*  
 Make: *Mazda* 3 c.c. *1496*  
 Colour: *Grey* A/C: *Insured / Std / NI / NA*  
 Sp. Reading: *112838* T/Radio: *Insured / Std / NI / NA*  
 Eng/No: \_\_\_\_\_  
 C/No: *YM6BN22A8H0159728*  
 Gen. Cond: *Good* / Fair / Poor / Burnt  
 Steering: *In order* / Jammed / Leaked / Burnt or  
 Brake: *In order* / Jammed / Leaked / Burnt or  
 Modi: *Nil* / S/Rim / STD A/Rim or  
 Tyre Size: F: *225/45ZR18*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or *habilead*  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. *6* mm R/Bal. *6* mm  
 L/Bal. *6* mm L/Bal. *6* mm  
 D.O.A. *17/9/21* D.O.I. *20/9/21*  
 Survey held at \_\_\_\_\_  
 Des. of Damages: *Rear* / Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Bal. or Market Value: *\$56*  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: *5* days Res.: Yes or No  
 Lum Sum: *20* % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS \_\_\_\_\_  
 Date: \_\_\_\_\_ Person Contacted: *035C* Vehicle: IN / OUT

Date / Time Action / Instruction *Dep 200*  
*BI involved 2. PPL LTA \$3583*  
*have video of folder*  
*have G14*  
*28/9/21 L/S \$6000 confirmed with Alan.*

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair:  
 Resurvey No. of Trip:

Survey Fee:	
Transportation:	
) ___S + RS ___SI	
) Photos	
) Others	
TOTAL	

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Report Format :  
 Lump Sum / I.B.I.: (\$ )

**FASTECH AUTO PTE LTD**  
**1 Kaki Bukit Ave 6 #01-48 Autobay**  
**Singapore 417883**  
**Tel No: 67452063/ 67467158 Fax No: 67458520**  
**Tax Reg No : 200006262D**

Luke Asch:

Und Auto Consultants hence notify the Repairer of the following:  
 • The survey is for a spray painting  
 • The survey is for damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Not Audited  
 20/9/21

VEHICLE No: SMY 4018M

2/58 6000 5 days

1PC	BOOTLID	DD/Ref	1248.30	\$1,255.80	/
1PC	BOOTLID REAR LOGO	Ref		\$65.80	/
1PC	BOOTLID 'MAZDA' EMBLEM	Ref		\$52.00	/
1PC	BOOTLID '3' EMBLEM	Ref		\$45.00	/
1PC	BOOTLID 'SKYACTIVE' EMBLEM	Ref		\$68.00	/
2PCS	BOOTLID REFLECTORS @\$650.00	See		\$1,350.00	X
1PC	BOOTLID INNER LOCK	TW1	164.60	\$288.20	/
1PC	BOOTLID WEATHERSTRIP	TW1	188.20	\$291.40	/
1PC	REAR BUMPER	DD	1061.30	\$1,215.10	/
2PCS	REAR BUMPER TOW COVERS @\$25.00	M/S		\$50.00	/
1PC	REAR BUMPER REINFORCEMENT	DD	537.30	\$745.20	/
2PCS	REAR BUMPER REFLECTORS @\$75.00	CR	48.50 x 2 = 97	\$150.00	/
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11		\$130.00	X
1SET	REAR BUMPER CLIPS	Ref		\$50.00	/
1PC	REAR BUMPER LICENCE PLATE LAMP	11		\$108.00	X
2PCS	TAILLAMPS @\$1250.00	CR	915 x 2 = 1830	2570.00	/
1PC	REAR END PANEL	DD	435.70	\$635.00	/
1PC	REAR END PANEL TOP GARNISH	TW1	262.30	\$366.50	/
2PCS	REAR FENDER INNER TRIMS @\$305.00	11		\$610.00	X
2PCS	REAR FENDERS @\$1155.00	R		\$2,310.00	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$415.00	X
				<b>\$10,451.00</b>	

1SET	S.NETT				
1SET	REAR BUMPER REVERSE SENSOR	Shunk		\$280.00	200
1PC	REAR END PANEL SEALANT	Ref		\$50.00	/
1PC	REAR LICENCE PLATE	SCR		\$50.00	40
1SET	REAR REVERSE CAMERA	SWC		\$480.00	X

	TO CHECK WIRING			\$50.00	20
	TO DISMANTLE & REPLACED REVERSE SENSOR			\$80.00	50
	TO TRANSFER BOOTLID MECHANISM			\$100.00	60
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$120.00	100
	TO RESET & REPROGRAMME 'DIAGNOSIS SYSTEM			\$150.00	80
	TO SPRAY RUST PROOFING			\$100.00	80
	LABOUR FOR PANEL BEATING & REPLACED PARTS			\$1,200.00	800
	TO PUTTY & SPRAY PAINTING			\$1,500.00	1100
	<b>TOTAL</b>			<b>\$14,611.00</b>	

P-6144-5  
 20%  
 45244  
 7504.4