12/29/21. 8:59 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21009780/VEA3Q2

Date:

29/12/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

0999993712

Claimant Vehicle No:

SHB8081H 20/09/2021 Insured Vehicle No:

Nature of Claim:

GBK730U TP

Claim No:

2647459264SG

KNAGM414MF5642480

D4FDFH314182

507634 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB8081H

Make & Model: KIA OPTIMA, 1.7 D (A)

Reg. Date: 13/11/2015 (Man. Year: 2015)

Colour: Silver

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: Rear Left Side:

205/65 R16

Front Left Side: West Lake 5 mm Front Right Side: West Lake 5 mm

Rear Right Side:

West Lake 5 mm West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,481.10	714.70	766.40	51.75
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,570.00	1,140.00	430.00	27.39
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,051.10	1,854.70	1,196.40	39.21
	Approved Total (Overridden) (S\$)		1,450.00		

(S\$)	3,051.10	1,450.00	1,601.10	52.48
+ GST 7.00/7.00% (S\$)	213.58	101.50	112.08	52.48
Nett Amount (S\$)	3,264.68	1,551.50	1,713.18	52.48
+ Loss of Use (2.5 x S\$40.00/day) (S\$)		100.00		
+ Car Rental (2.5 x S\$67.41/day) (S\$)		168.53		
+ D0	oc/Search Fee (S\$)	7.45		
Nett Liability (S\$)		1,827.48		

INSPECTION

Date of Assignment: 20/09/2021

Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Date Inspected: Inspected At: 20/09/2021

Singapore 486443

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No. Q	y Part No.	Particulars	Condition	Repairer's	Amount
1 1		*N/S MIRROR ASSY	Missing	590.00 FL	*590.00 FL
2 1		*FRONT N/S DOOR	Repair	796.00 FL	*- FL
3 1		*FRONT N/S DOOR OUTER HANDLE	Missing	44.00 FL	*44.00 FL
4 1		*FRONT N/S DOOR HANDLE OUTER COVER (SMALL)	Necessary	10.00 FL	*10.00 FL
5 1		*FRONT N/S DOOR HANDLE BASE ASSY	Necessary	39.00 FL	*39.00 FL
6 1		*SET O/S DOOR STICKERS	Necessary	100.00 FS	*100.00 FS
7 1	C-CN-#	*SUNDRY	Serviceable	50.00 FS	*-FS
r-rianch	se part. S=SpcNett	. L-Listitembisc.	Sub Total (S\$)	1,629.00	783.00
			- List Item Discount on L Items 10.00/10.00% (S\$)	147.90	68.30
			Total Parts (S\$)	1,481.10	714.70
		Report was unsu	bmitted during this print-out.		

12/29/21, 8:59 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT N/S DOOR INTO NEW SHELL DOOR	New	150.00	60.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE REAR N/S DOOR ETC	New	600.00	450.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT N/S FENDER ,FRONT N/S DOOR ,REAR N/S DOOR ,N/S MIRROR COVER	New	700.00	600.00
4	TO APPLY RUSTPROOFING ON REPAIRED PANELS	New	120.00	30.00
	Gross L	abour Cost (S\$)	1,570.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >