

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009781/EVCN2**Date:** 06/10/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00105062101

**Claimant Vehicle No :** GBA9488M **Insured Vehicle No :** GBJ8362B

Date of Loss: 14/09/2021 Nature of Claim: TP Claim No: SNM21D205215/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA9488M**

Make & Model: SUZUKI EVERY, 660cc GA (M) Engine No: K6A7270492

Reg. Date: 14/04/2008 (Man. Year: 2007) Chassis No: DA64V248615

Colour: Silver Odometer: 328851 km

Engine Capacity: 658 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 155R13 Rear Tyre Size: 155R13

Front Left Side: Double King 5 mm Rear Left Side: Double King 5 mm

Front Right Side: Double King 5 mm Rear Right Side: Double King 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,301.80	2,236.40	65.40	2.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,000.00	1,080.00	51.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,381.80</b>	<b>3,236.40</b>	<b>1,145.40</b>	<b>26.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,381.80</b>	<b>2,600.00</b>	<b>1,781.80</b>	<b>40.66</b>

INSPECTION

Date of Assignment: 20/09/2021

Date Inspected: 20/09/2021 Inspected At: Xinya Auto Services Pte Ltd (HQ)  
Blk 1002, #01-75, Bukit Merah Lane 3  
Singapore 159719

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 06 Oct 2021)	
<b>Parts:</b>	N/A	SUZUKI EVERY 660cc GA (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBA9488M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	596.75 FL	*540.00 FL
2	1		*REAR BUMPER RETAINER	Broken	20.15 FL	*20.15 FL
3	1		*REAR BUMPER LAMP	Broken	170.65 FL	*170.65 FL
4	1		*TAIL DOOR	Dented	868.95 FL	*868.95 FL
5	1		*TAIL DOOR RUBBER	Torn	124.50 FL	*124.50 FL
6	1		*TAIL DOOR LOCK	Bent	181.10 FL	*181.10 FL
7	1		*TAIL DOOR SUZUKI LOGO	Necessary	23.00 FL	*23.00 FL
8	1		*REAR WINDSCREEN GLASS	Broken	458.05 FL	*458.05 FL
9	4		*REAR WINDSCREEN CLIPS	Necessary	20.00 FL	*20.00 FL
10	1		*TAIL DOOR STICKER 70KM	Necessary	10.00 FS	*10.00 FS
11	1		*TAIL DOOR STICKER 5 PAX	Necessary	10.00 FS	*10.00 FS
12	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
13	1		*REAR TAILGATE WIPER MOTOR	Bent/Jammed	314.10 FL	*314.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,857.25</b>	<b>2,780.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	555.45	544.10
<b>Total Parts (\$\$)</b>	<b>2,301.80</b>	<b>2,236.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE REAR BUMPER, TAILGATE, ENFORCEMENT AND TO PANEL BEAT END PANEL & ALIGN	New	800.00	400.00
2	TO PUTTY & SPRAY PAINT REAR BUMPER, TAILGATE INNER & OUTER, END PANEL AND OTHER AFFECTED AREA	New	800.00	400.00
3	TO CHECK & RECTIFY WIRING	New	80.00	30.00
4	TO TRANSFER DOOR MECHANISM TO NEW DOOR	New	280.00	50.00
5	TO FIT NEW WINDSCREEN GLASS & CHECK FOR WATER TIGHT	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,080.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >