



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2465T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N)	CUT	571.90	571.90
1	FRONT RH BUMPER RETAINER (N)	NOT NECESSARY	181.90	-
10	FRONT BUMPER CLIP (N)	NECESSARY	50.00	50.00
1	FRONT RH SIDE STEP (N)	CRACKED	67.50	67.50
1	FRONT RH MUDFLAP (N)	CUT	105.50	105.50
1	RH "A" PILLAR (N) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR RH (N)	TO REPAIR SEE LABOUR	1,071.40	-
1	FRONT RH FENDER (N) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT RH UPPER ARM (N)	NOT NECESSARY	377.90	-
1	FRONT RH LOWER ARM (N)	NOT NECESSARY	228.40	-
1	FRONT RH ABSORBER (N)	BENT	140.20	140.20
2	FRONT RH ABSORBER RUBBER STOPPER (N)	BENT	40.00	40.00
1	FRONT RH ABSORBER BRACKET (N) (NPA)	NOT NECESSARY	-	-
1	FRONT RH KUNCKLE ARM (N)	NOT NECESSARY	315.20	-
1	FRONT RH WHEEL HUB (N)	NOT NECESSARY	453.00	-
1	FRONT RH WHEEL BEARING (N)	JAMMED	231.00	231.00
1	TIE ROD END RH (N)	NOT NECESSARY	142.00	-
1	TIE ROD RH (N)	NOT NECESSARY	98.00	-
1	FRONT RH ABS SENSOR (N)	BROKEN	397.00	397.00
1	FRONT RH BRAKE CALIPER HOSE (N)	CUT	67.90	67.90
1	WHEEL RIM COVER (N)	CUT	161.50	161.50
1	FRONT RH TYRE RIM 15 INCH (N)	CUT	237.50	237.50
1	SIDE STEP PANEL RH (N) (ADDITIONAL)	DISTORTED	120.00	120.00
	LESS 10% DISCOUNT		-505.78	-219.00
			4,552.02	1,971.00
<u>SPECIAL NETT ITEMS</u>				
1	COMPANY DECAL STICKER (SN)	NECESSARY	20.00	20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TYRE 195R15C (SN) LABOUR TOWING CHARGES FROM ACCIDENT AREA INTO W/SHOP. LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF RH "A" PILLAR, FRONT DOOR RH AND FRONT RH FENDER. TO REMOVE & INSTALL RHF UNDERCARRIAGE PARTS. TO REMOVE & INSTALL RHF RIM INCLUDING TYRE BALANCING. MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH & RECTIFY CHASSIS TO RECOMMENDED SPECIFICATION. TO CONDUCT COMPUTERISED WHEEL ALIGNMENT. TO RESET & RE-PROGRAM WARNING LIGHT ON. TO APPLY ANTI RUST COATING. TO SPRAY PAINTING ON AFFECTED AREAS.	PUNCTURE	200.00	90.00
			220.00	110.00
			150.00	110.00
			800.00	600.00
			200.00	150.00
			20.00	20.00
			1,800.00	100.00
			80.00	60.00
			120.00	80.00
			80.00	40.00
800.00	700.00			
			4,050.00	1,860.00
GRAND TOTAL			8,822.02	3,941.00
RECOMMENDED COST OF REPAIRS				3,941.00

Report Ref No. CS/BSH21009782/Guf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.