

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 4209X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEEP CUT / TORN	1,145.20	913.70
1	REAR BUMPER SIDE RETAINER N/S (CONSISTENT)	BENT	66.50	38.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER SPLASH SHIELD N/S (CONSISTENT)	NOT NECESSARY	121.30	-
1	SET REAR BUMPER SPLASH SHIELD CLIPS N/S (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	981.20	-
1	REAR FENDER LOWER STICKER N/S (CONSISTENT)	NECESSARY	38.00	38.00
1	REAR SPORT RIM N/S (CONSISTENT)	WARPED	950.00	680.00
1	REAR SHOCK ABSORBER N/S (CONSISTENT)	SERVICEABLE	322.00	-
1	REAR WHEEL HUB BEARING N/S (CONSISTENT)	DAMAGED	485.00	320.00
1	REAR AXLE BEAM (CONSISTENT)	NOT NECESSARY	1,655.00	-
	LESS 20% DISCOUNT		-	-407.94
			5,844.20	1,631.76
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		120.00	80.00
	TO SPRAY RUST PROOFING .	NOT NECESSARY	60.00	-
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE.		380.00	120.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S .		680.00	400.00
	TO PUTTY & SPRAY PAINTING.		900.00	400.00
			2,390.00	1,150.00
	GRAND TOTAL		8,234.20	2,781.76

Report Ref No. CC4/ASM21009783/Upa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM21009783/Upa3q2

CHUA KANG SENG
Licensed Appraiser