

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009788/UGS3Q2**Date:** 14/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100358862-07
Claimant Vehicle No :	SMV690M	Insured Vehicle No :	SKL7224G
Date of Loss:	18/09/2021	Nature of Claim:	TP
		Claim No:	1065522587SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV690M		
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Engine No:	LEB1439447
Reg. Date:	14/11/2018 (Man. Year: 2018)	Chassis No:	GP51332948
Colour:	Black	Odometer:	71889 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,994.80	2,665.44	2,329.36	46.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	870.00	870.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,734.80	3,535.44	3,199.36	47.50
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	6,734.80	2,800.00	3,934.80	58.42
+ GST 7.00/7.00% (S\$)	471.44	196.00	275.44	58.43
Nett Amount (S\$)	7,206.24	2,996.00	4,210.24	58.42
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,198.00		
Global Sum Settlement (S\$)		3,150.00		

INSPECTION

Date of Assignment:	20/09/2021		
Date Inspected:	20/09/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	821.90 F	*821.90 FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Cracked	65.50 F	*35.50 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	387.80 F	*- FL
5	1		*FRONT BUMPER FOG LAMP N/S	Cracked	366.50 F	*287.80 FL
6	1		*FRONT BUMPER FOG LAMP GARNISH N/S	Torn	381.90 F	*245.50 FL
7	1		*HEADLAMP LED N/S	Cracked	1,815.20 F	*1,550.20 FL
8	1		*HEADLAMP LOWER BRACKET N/S	Cracked	66.80 F	*48.20 FL
9	1		*FRONT FENDER N/S	Repair	455.20 F	*- FL
10	1		*FRONT FENDER HYBRID EMBLEM N/S	Necessary	98.50 F	*98.50 FL
11	1		*FRONT FENDER INNER SHIELD N/S	Torn	166.20 F	*166.20 FL
12	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	39.00 F	*39.00 FL
13	1		*FRONT FENDER INNER ARCH PANEL N/S	Repair	291.30 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,994.80	3,331.80
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	666.36
Total Parts (\$)	4,994.80	2,665.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	120.00	50.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	500.00
Gross Labour Cost (\$)			1,740.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >