

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21009792/KTCE2

Date: 10/12/2021

REFERENCE

Insured/Claimant: REGAL CONSTRUCTION PTE LTD Policy No: DMCVSNW00057842103
Date of Loss: 05/09/2021 Nature of Claim: OD Claim No: SNM21D205132/C01/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP3004P
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M) Engine No: 4P10C04816
Reg. Date: 27/05/2016 (Man. Year: 2016) Chassis No: FEB21EA20505
Colour: White Odometer: 294585 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$44,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)
Front Left Side: KOMENDO 9 mm Rear Left Side: KOMENDO 9/9 mm
Front Right Side: KOMENDO 9 mm Rear Right Side: KOMENDO 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,495.00	25,979.00	12,516.00	32.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,259.40	1,031.40	2,228.00	68.36
Paintwork Labour	556.39	220.48	335.91	60.37
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,310.79	27,230.88	15,079.91	35.64
Approved Total (Overridden) (S\$)		21,750.00		
- Excess (S\$)	0.00	550.00	-550.00	
(S\$)	42,310.79	21,200.00	21,110.79	49.89
+ GST 7.00/7.00% (S\$)	2,961.76	1,484.00	1,477.76	49.89
Nett Amount (S\$)	45,272.55	22,684.00	22,588.55	49.89

INSPECTION

Date of Assignment: 21/09/2021 Present Location: Ding Auto Pte Ltd (HQ)
Date Inspected: 21/09/2021 Inspected At: Ding Auto Pte Ltd (HQ)
Estimated Period of Repair: 10.0 days Blk 10 #01-20 Sin Ming Ind Est Sec C
Singapore 575645

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Dec 2021)	
Parts:	N/A	mitsubishi canter 3.0 D FEB21 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP3004P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		29,175.00 F	*12,569.00 F
2	1		*R/STEEL BODY TRUNK REAR STEEL BODY	Bent	-	*4,000.00 FS
Supplementary #1						
3	1		*NEW FULL FIX CANOPY WITH FRONT FULL COVER & REAR HALF-SIDE WITH CANVAS - INCLUDE REMOVE & INSTALL CANOPY, SPRAY PAINT & FITTING	Bent	3,500.00 F	*3,500.00 FS
Supplementary #2						
4	1		*ENGINE FAN COVER/SHROUD	Cracked	250.00 F	*250.00 F
5	1		*CABIN STAND	Bent	280.00 F	*280.00 F
6	1		*PROPELLAR BEARING HOUSING	Distorted	380.00 F	*380.00 F
7	1		*ENGINE MOUNTING RH	Cracked	180.00 F	*180.00 F
8	1		*ENGINE MOUNTING LH	Cracked	180.00 F	*180.00 F
9	1		*GEARBOX MOUNTING X 2PCS	Cracked	90.00 F	*180.00 F
10	1		*ENGINE BRACKET RH	Bent	480.00 F	*480.00 F
11	1		*STEERING BOX BRACKET	Bent	190.00 F	*190.00 F
12	1		*SPEED METER SENSOR	Dented	320.00 F	*320.00 F
13	1		*RADIATOR EXPANSION TANK	Cracked	195.00 F	*195.00 F
14	1		*POWER STEERING OIL TANK	Cracked	195.00 F	*195.00 F
15	1		*DOOR LOCK ASSY RH	Bent	280.00 F	*280.00 F
16	1		*EXHAUST CATALYST	Bent	2,800.00 F	*2,800.00 F
Total Parts (\$\$)						38,495.00 25,979.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	428.40	142.80
2	Total Paint Materials	New	127.99	77.68
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	3,259.40	1,031.40
Gross Labour Cost (\$\$)			3,815.79	1,251.88

Report was unsubmitted during this print-out.

< END OF ESTIMATES >