### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/GRB21009794/GVF3E2

**Date:** 05/01/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle SBB3838X Insured Vehicle No: SLS9851J

No:

Date of Loss: 13/09/2021 Nature of Claim: TP Claim No: MFL2021D0004015

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SBB3838X

Make & Model: HONDA CIVIC, 2.0 3DRS TYPE R (A) Engine No: K20Z42003330

Reg. Date: 18/12/2009 (Man. Year: 2008) Chassis No: SHHFN23608U300158

Colour: Purple Odometer: 185834 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm
Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,550.74	2,233.95	6,316.79	73.87
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,420.00	1,550.00	870.00	35.95
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,970.74	3,783.95	7,186.79	65.51
	Approved Total (Overridden) (S\$)		3,000.00		
	Nett Amount (S\$)	10,970.74	3,000.00	7,970.74	72.65

**INSPECTION** 

Date of Assignment: 20/09/2021

Date Inspected: 21/09/2021 Inspected At: Blk 7 Woodland Rd # 01-397D Yew Tee

Estimated Period of Repair: 5.0 days

Repairer: John Auto Services

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jan 2022)

Parts: 143 HONDA CIVIC 2.0 3DRS TYPE R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBB3838X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Repair	1,298.20 F	*- FL
2	1		*REAR TAIL GATE LOCK	Not Necessary	255.20 F	*- FL
3	1		*REAR TAIL GATE GARNISH ASSY H	Cut	850.30 F	*282.70 FL
4	1		*REAR LH TAIL GATE LAMP ASSY	Cut	358.10 F	*358.10 FL
5	1		*REAR LH TAIL LAMP ASSY	Cut	332.30 F	*332.30 FL
6	1		*REAR RH TAIL GATE LAMP ASSY	Not Necessary	358.10 F	*- FL
7	1		*REAR RH TAIL LAMP ASSY	Not Necessary	332.30 F	*- FL
8	1		*REAR CIVIC EMBLEM	Necessary	38.64 F	*38.64 FL
9	1		*REAR TYPE R EMBLEM	Necessary	88.70 F	*53.00 FL
10	1		*REAR BOOT RUBBER	Cut	188.30 F	*150.80 FL
11	1		*REAR END PANEL	Repair	551.10 F	*- FL
12	1		*REAR END PANEL GARNISH	Deformed	166.30 F	*122.80 FL
13	1		*REAR BUMPER	Repair	1,198.20 F	*- FL
14	1		*REAR BUMPER BEAM	Bent	255.60 F	*255.60 FL
15	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
16	1		*REAR BUMPER LOWER	Cracked	886.40 F	*388.00 FL
17	1		*SET REAR WINDSCREEN RUBBER	Not Necessary	253.40 F	*- FL
18	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
19	1		*REAR NO PLATE	Cut	45.00 FS	*40.00 FS
20	1		*REAR BOOT TRIM BOARD CLIP	Necessary	60.00 FS	*20.00 FS
21	1		*REAR TAIL GATE LOWER GARNISH	Cracked	502.30 F	*422.00 FL
22	1		*REAR LOWER GARNISH BLACK COVER	Cut	412.30 F	*276.00 FL
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	8,550.74	2,769.94
	- List Item Discount on L Items 0.00/20.00% (S\$)				0.00	535.99

Report was unsubmitted during this print-out.

**Total Parts (S\$)** 

8,550.74

2,233.95

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

Particulars	Lab.Type	Repairer's	Amount
our Items			
WIRING FEE	New	40.00	30.00
ANTI RUST	New	60.00	0.00
TO SPRAY PAINTING	New	1,000.00	800.00
TO REMOVE & REFIT REAR SPOILER	New	80.00	20.00
TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
TO REPAIR REAR ACCIDENT DAMAGE AREAS	New	1,000.00	700.00
TO REAR EXHAUST REPAIR	New	120.00	0.00
	Gross Labour Cost (S\$)	2,420.00	1,550.00
	OUR Items  WIRING FEE  ANTI RUST  TO SPRAY PAINTING  TO REMOVE & REFIT REAR SPOILER  TO REMOVE & REFIT REAR WINDSCREEN  TO REPAIR REAR ACCIDENT DAMAGE AREAS	WIRING FEE New ANTI RUST New TO SPRAY PAINTING New TO REMOVE & REFIT REAR SPOILER New TO REMOVE & REFIT REAR WINDSCREEN New TO REPAIR REAR ACCIDENT DAMAGE AREAS New TO REAR EXHAUST REPAIR New	Our Items           WIRING FEE         New         40.00           ANTI RUST         New         60.00           TO SPRAY PAINTING         New         1,000.00           TO REMOVE & REFIT REAR SPOILER         New         80.00           TO REMOVE & REFIT REAR WINDSCREEN         New         120.00           TO REPAIR REAR ACCIDENT DAMAGE AREAS         New         1,000.00           TO REAR EXHAUST REPAIR         New         120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >