

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009796/UVCN2**Date:** 05/11/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00058402100

Claimant Vehicle No : SJQ5128A**Insured Vehicle No :** SJP5790S

Date of Loss: 16/09/2021

Nature of Claim: TP

Claim No: SNM21D205284/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJQ5128A**

Make & Model: SUBARU IMPREZA, 1.5 R AWD 4AT ABS AIRBAG (A) Engine No: EL15D616940

Reg. Date: 14/05/2009 (Man. Year: 2008) Chassis No: JF1GE3KS59G003693

Colour: Red Odometer: 228472 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17 Rear Tyre Size: 225/45ZR17

Front Left Side: Cencotive 6 mm Rear Left Side: Cencotive 6 mm

Front Right Side: Cencotive 6 mm Rear Right Side: Cencotive 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,284.64	1,605.12	1,679.52	51.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,030.00	470.00	31.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,784.64	2,635.12	2,149.52	44.93
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	4,784.64	2,100.00	2,684.64	56.11
+ GST 7.00/7.00% (S\$)	334.92	147.00	187.92	56.11
Nett Amount (S\$)	5,119.56	2,247.00	2,872.56	56.11

INSPECTION

Date of Assignment: 20/09/2021

Date Inspected: 25/10/2021 Inspected At:

Progressive Car Care Pte Ltd (HQ)

Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Nov 2021)

Parts: 143 SUBARU IMPREZA 1.5 R AWD 4AT ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJQ5128A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed/Torn	654.30 FL	*654.30 FL
2	10	*FRONT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
3	1	*FRONT BUMPER SIDE HOLDER-LH/RH	N/s Bent/O/s Not Necessary	38.00 FL	*19.00 FL
4	1	*FRONT BUMPER FOG LAMP-LH	Not Necessary	304.50 FL	*- FL
5	1	*FRONT BUMPER FOAM	Not Necessary	126.50 FL	*- FL
6	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	288.30 FL	*- FL
7	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	85.30 FL	*- FL
8	1	*FRONT FENDER-LH	Bent/Buckled	270.50 FL	*270.50 FL
9	1	*FRONT FENDER COWLING-LH	Torn	110.30 FL	*110.30 FL
10	10	*FRONT FENDER COWLING CLIPS-LH	Necessary	39.00 FL	*39.00 FL
11	1	*FRONT FENDER LAMP-LH	Not Necessary	30.80 FL	*- FL
12	1	*FRONT SIDE MIRROR OUTER COVER-LH (CUT)	Not Consistent With The Impact	50.70 FL	*- FL
13	1	*FRONT TYRE RIM-LH	Repair	800.30 FL	*- FL
14	1	*HEADLAMP-LH	Scratched	874.30 FL	*874.30 FL
15	1	*HEADLAMP LOWER RETAINER-LH	Not Necessary	44.00 FL	*- FL
16	1	*TYRE-LF	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,035.80	2,006.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	751.16	401.28
Total Parts (\$\$)	3,284.64	1,605.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS,LH FRONT DOOR,REMOVE,REPLACE ACCIDENT PARTS	New	500.00	400.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	500.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO 4 WHEEL ALIGNMENT	New	100.00	80.00
5	TO REMOVE,REPLACE TYRE RIM & BALANCING TYRE	New	50.00	0.00
6	TO TUFF-KOTE	New	30.00	30.00
Gross Labour Cost (\$)			1,500.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >