

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21009800/UUF3E2

Date: 22/10/2021

REFERENCE

Insured/Claimant:	TAN MIN PIN ADRIAN	Policy No:	MPC21P00182900	Claim No:	DMPC2100324H
Date of Loss:	16/09/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8751Y	Engine No:	L15B72451259
Make & Model:	HONDA CIVIC, 1.5 (A)	Chassis No:	MRHFC1660HT000070
Reg. Date:	19/05/2017 (Man. Year: 2017)	Odometer:	37568 km
Colour:	Blue		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40ZR18	Rear Tyre Size:	235/40ZR18
Front Left Side:	Habilead 7 mm	Rear Left Side:	Habilead 7 mm
Front Right Side:	Habilead 7 mm	Rear Right Side:	Habilead 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	7,523.40	-7,523.40	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	3,990.00	-3,990.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	11,513.40	-11,513.40	
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	0.00	9,200.00	-9,200.00	
+ GST 7.00/7.00% (S\$)	0.00	644.00	-644.00	
Nett Amount (S\$)	0.00	9,844.00	-9,844.00	

INSPECTION

Date of Assignment:	20/09/2021 Present Location:	Automobile Integrated Management Pte Ltd (HQ) Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Date Inspected:	21/09/2021 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2021)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8751Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT SUPPORT PANEL ASSY (WCP)	Cracked	-	*507.00 F
2	1		*FRT WHEELHOUSE MEMBER RH (WCP)	Repair	-	*- F
3	1		*FRT WHEELHOUSE EXTENSION RH (WCP)	Repair	-	*- F
4	1		*FRT FENDER RH (WCP)	Buckled	-	*208.00 F
5	1		*FRT FENDER BRACKET RH (WCP)	Cracked	-	*33.00 F
6	1		*FRT FENDER ENCLOSURE RH (WCP)	Not Necessary	-	*- F
7	1		*FRT FENDER INNERSHIELD RH (WCP)	Torn	-	*59.00 F
8	1		*FRT BONNET (WCP)	Repair	-	*- F
9	1		*RR CHASSIS PANEL LH (WCP)	Repair	-	*- F
10	1		*RR SPARE TYRE PANEL EXTENSION LH (WCP)	Repair	-	*- F
11	1		*RR END PANEL (WCP)	Repair	-	*- F
12	1		*RR END PANEL STIFFENER LH (WCP)	Repair	-	*- F
13	1		*RR TAILLAMP PANEL LH (WCP)	Dented / Bent	-	*59.00 F
14	1		*RR FENDER GUTTER PANEL LH (WCP)	Repeated	-	*- F
15	1		*RR FENDER LH (WCP)	Distorted	-	*624.00 F
16	1		*RR FENDER AIR DUCT LH (WCP)	Cracked	-	*11.00 F
17	1		*RR FUEL FILLER COVER (WCP)	Bent	-	*98.00 F
18	1		*RR FUEL FILLER COVER LOCK ACTUATOR (WCP)	Jammed	-	*85.00 F
19	1		*RR FUEL FILLER ADAPTER (WCP)	Cracked	-	*50.00 F
20	1		*RR FUEL FILLER CAP (WCP)	Not Necessary	-	*- F
21	1		*RR FUEL TANK ASSY (WCP)	Not Necessary	-	*- F
22	1		*RR WINDSCREEN (WCP)	Not Necessary	-	*- F
23	1		*RR WINDSCREEN MOULDING (WCP)	Necessary	-	*33.00 F
24	3		*RR WINDSCREEN INNER SEAL (WCP)	Necessary	-	*78.00 F
25	1		*RR QUARTER GLASS ASSY LH (WCP)	Not Necessary	-	*- F
26	1		*RR DOOR LH (WCP)	Dented	-	*624.00 F
27	1		*RR DOOR WEATHERSTRIP LH (WCP)	Necessary	-	*72.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*RR DOOR LOW SEAL LH (WCP)	Necessary	-	*10.00 F
29	1		*RR DOOR HINGE UPP LH (WCP)	Not Necessary	-	*- F
30	1		*RR DOOR HINGE LOW LH (WCP)	Not Necessary	-	*- F
31	1		*RR DOOR CHECKER LH (WCP)	Not Necessary	-	*- F
32	1		*RR DOOR STOPED (WCP)	Not Necessary	-	*- F
33	1		*RR BOOTLID (WCP)	Not Necessary	-	*- F
34	1		*RR BOOTLID TOP SPOILER (WCP)	Not Necessary	-	*- F
35	1		*RR BOOTLID OUTER GARNISH (WCP)	Not Necessary	-	*- F
36	1		*RR BOOTLID LOCK (WCP)	Not Necessary	-	*- F
37	1		*RR BOOTLID LOCK CATCHER (WCP)	Not Necessary	-	*- F
38	1		*RR BOOTLID WEATHERSTRIP (WCP)	Not Necessary	-	*- F
39	1		*RR BOOTLID STOPED (WCP)	Not Necessary	-	*- F
40	1		*RR BOOTLID STOPED LOW (WCP)	Not Necessary	-	*- F
41	1		*RR BOOTLID DRAIN PLUG (WCP)	Not Necessary	-	*- F
42	1		*RR DOOR INNER TRIM BOARD LH (WCP)	Not Necessary	-	*- F
43	1		*RR FENDER INNER TRIM LH (WCP)	Deformed	-	*52.00 F
44	1		*RR BOOTLID LOGO (WCP)	Not Necessary	-	*- F
45	1		*RR BOOTLID VTEC TURBO EMBLEM (WCP)	Not Necessary	-	*- F
46	1		*RR BOOTLID CIVIC EMBLEM (WCP)	Not Necessary	-	*- F
47	1		*RR FUEL FILLER CAUTION STICKER (WCP)	Necessary	-	*8.00 F
48	1		*RR DOOR BLACK STICKER LH (RR) (WCP)	Necessary	-	*26.00 F
49	1		*RR DOOR OUTER MLDG LH (WCP)	Not Necessary	-	*- F
50	1		*RR DOOR OUTER UPP MLDG LH (WCP)	Not Necessary	-	*- F
51	1		*RR FENDER INNERSHIELD LH (WCP)	Torn	-	*59.00 F
52	1		*LH ROCKER PANEL GARNISH LH (WCP)	Not Necessary	-	*- F
53	1		*FRT GRILLE BASE (WCP)	Scratched	-	*91.00 F
54	1		*FRT GRILLE LOGO (WCP)	Not Necessary	-	*- F
55	1		*FRT GRILLE CHROME MLDG (WCP)	Not Necessary	-	*- F
56	1		*FRT GRILLE CHROME MLDG RH (WCP)	Scratched	-	*78.00 F
57	1		*FRT GRILLE TOP SEAL (WCP)	Not Necessary	-	*- F
58	1		*FRT BUMPER (WCP)	Distorted	-	*299.00 F
59	1		*FRT BUMPER RETAINER RH (WCP)	Cracked	-	*12.00 F
60	1		*FRT BUMPER BRACKET RH (WCP)	Bent	-	*26.00 F
61	1		*FRT BUMPER TOP CENTRE RETAINER (WCP)	Not Necessary	-	*- F
62	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	-	*299.00 F
63	1		*FRT BUMPER FOG LAMP COVER RH (WCP)	Scratched	-	*20.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*FRT BUMPER LOW CENTRE GRILLE (WCP)	Not Necessary	-	*- F
65	1		*RR BUMPER (WCP)	Distorted	-	*338.00 F
66	1		*RR BUMPER LOW (WCP)	Not Necessary	-	*- F
67	1		*RR BUMPER SIDE RETAINER LH (WCP)	Cracked	-	*16.00 F
68	1		*RR BUMPER BRACKET LH (WCP)	Cracked	-	*7.00 F
69	1		*RR BUMPER GARNISH LH (WCP)	Scratched	-	*13.00 F
70	1		*RR BUMPER REFLECTOR LH (WCP)	Not Necessary	-	*- F
71	1		*RR BUMPER FINISHER LH (WCP)	Distorted	-	*13.00 F
72	1		*RR BUMPER REINFORCEMENT (WCP)	Not Necessary	-	*- F
73	1		*FRT HEADLAMP RH (WCP)	Cracked	-	*1,014.00 F
74	1		*FRT SIGNAL LAMP RH (WCP)	Cracked	-	*33.00 F
75	1		*FRT FOG LAMP RH (WCP)	Cracked	-	*208.00 F
76	1		*RR TAILLAMP LH (WCP)	Broken	-	*221.00 F
77	1		*RR BOOTLID LAMP LH (WCP)	Not Necessary	-	*- F
78	1		*FRT WIPER WASHER TANK (WCP)	Not Necessary	-	*- F
79	1		*FRT WIPER WASHER PUMP (WCP)	Not Necessary	-	*- F
80	1		*FRT WIPER WASHER TANK NECK (WCP)	Not Necessary	-	*- F
81	1		*FRT WHEEL BEARING RH (WCP)	Not Necessary	-	*- F
82	1		*FRT WHEEL BEARING HUB RH (WCP)	Not Necessary	-	*- F
83	1		*FRT KNUCKLE RH (WCP)	Not Necessary	-	*- F
84	1		*FRT LOW ARM RH (WCP)	Not Necessary	-	*- F
85	1		*FRT LOW ARM BALL JOINT RH (WCP)	Not Necessary	-	*- F
86	1		*FRT STABILIZER LINK RH (WCP)	Not Necessary	-	*- F
87	1		*FRT ABS SENSOR RH (WCP)	Not Necessary	-	*- F
88	1		*FRT SHOCK ABSORBER RH (WCP)	Not Necessary	-	*- F
89	1		*FRT SHOCK ABSORBER TOP MOUNTING RH (WCP)	Not Necessary	-	*- F
90	1		*FRT TIE ROD RH (WCP)	Not Necessary	-	*- F
91	1		*FRT STEERING RACK END RH (WCP)	Not Necessary	-	*- F
92	1		*RR WHEEL BEARING LH (WCP)	Damaged	-	*176.00 F
93	1		*RR KNUCKLE LH (WCP)	Bent	-	*169.00 F
94	1		*RR LOW ARM 1 LH (WCP)	Bent	-	*72.00 F
95	1		*RR LOW ARM 2 LH (WCP)	Bent	-	*52.00 F
96	1		*RR UPP ARM LH (WCP)	Bent	-	*169.00 F
97	1		*RR TRAILING ARM LH (WCP)	Bent	-	*72.00 F
98	1		*RR STABILIZER LINK LH (WCP)	Not Necessary	-	*- F
99	1		*RR ABS SENSOR LH (WCP)	Not Necessary	-	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
100	1		*RR SHOCK ABSORBER LH (WCP)	Twisted	-	*182.00 F
101	1		*RR SHOCK ABSORBER TOP MOUNTING LH (WCP)	Not Necessary	-	*- F
102	10		*FRT BUMPER CLIP	Necessary	-	*30.00 FS
103	10		*FRT GRILLE CLIP	Not Necessary	-	*- FS
104	6		*FRT SUPPORT GARNISH CLIP	Not Necessary	-	*- FS
105	10		*FRT FENDER INNERSHIELD CLIP	Necessary	-	*30.00 FS
106	1		*FRT RIM RH	Not Necessary	-	*- FS
107	1		*FRT TYRE RH	Not Necessary	-	*- FS
108	1		*RR RIM LH	Not Necessary	-	*- FS
109	1		*RR TYRE LH	Serviceable	-	*- FS
110	10		*RR BUMPER CLIP	Necessary	-	*30.00 FS
111	10		*RR FENDER INNERSHIELD CLIP	Not Necessary	-	*- FS
112	6		*RR FENDER INNER TRIM CLIP	Not Necessary	-	*- FS
113	6		*RR END PANEL TOP GARNISH CLIP	Not Necessary	-	*- FS
114	6		*RR BOOTLID INSULATOR CLIP	Not Necessary	-	*- FS
115	1		*RR WINDSCREEN SEALANT	Necessary	-	*40.00 FS
116	1		*RR WINDSCREEN SOLAR FILM	Not Necessary	-	*- FS
117	1		*RR QUARTER GLASS SEALANT	Necessary	-	*30.00 FS
118	1		*RR QUARTER GLASS SOLAR FILM	Not Necessary	-	*- FS
119	1		*FRT SRS CRASH SENSOR RH (WCP)	Damaged	-	*137.00 F
120	1		*RR EXHAUST SILENCER BOX LH (WCP)	Repair	-	*- F
121	2		*RR TAILLAMP CLIP (WCP)	Necessary	-	*12.00 F
122	1		*RR BUMPER REVERSE SENSOR (WCP)	Cracked	-	*128.00 F
123	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS (WCP)	Cracked	-	*115.00 F
124	1		*RR DOOR BLACK STICKER LH (FRT) (WCP)	Necessary	-	*26.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	0.00	6,854.00
+ Margin on L,N Items 0.00/10.00% (\$\$)	0.00	669.40
Total Parts (\$\$)	0.00	7,523.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS (FRONT)	New	-	500.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BONNET, FRT BUMPER, FRT FENDER RH, SUPPORT (FRONT)	New	-	600.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT (FRONT)	New	-	0.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR (FRONT)	New	-	20.00
5	TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS (FRONT)	New	-	0.00
6	TO CONDUCT 4 WHEEL ALIGNMENT (FRONT)	New	-	80.00
7	TO CONDUCT RESET OF ENGINE LIGHT ON (FRONT)	New	-	0.00
8	TO REFOCUS HEADLAMP (FRONT) (REPEATED)	New	-	0.00
9	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS (REAR)	New	-	1,200.00
10	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, RR BOOTLID, RR BUMPER, RR END PANEL, RR FENDER LH, RR DOOR LH, LH ROCKER PANEL (REAR)	New	-	1,000.00
11	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT (REAR)	New	-	0.00
12	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR (REAR)	New	-	20.00
13	REMOVE AND REFIX SEAT CUSHION / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS (REAR)	New	-	80.00
14	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST (REAR)	New	-	40.00
15	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST (REAR)	New	-	0.00
16	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID (REAR)	New	-	0.00
17	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE (REAR)	New	-	0.00
18	TO APPLY DOOR SEALANT TO DOOR (REAR)	New	-	60.00
19	REMOVE AND REPLACE LHR UNDER CARRIAGE PARTS (REAR)	New	-	150.00
20	TO REMOVE AND REFIT FUEL TANK TO FACILITATE ACCIDENT REPAIR (REAR)	New	-	60.00
21	TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER (REAR)	New	-	120.00
22	TO REMOVE AND REFIX REAR QUARTER GLASS (REAR)	New	-	60.00
Gross Labour Cost (\$\$)			0.00	3,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >