

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009802/TQCN2**Date:** 05/05/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNA00006252102

Claimant Vehicle No : SML8096D **Insured Vehicle No :** PC6341X

Date of Loss: 17/09/2021 Nature of Claim: TP Claim No: SNM21D205300/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML8096D**

Make & Model: JAGUAR XE 2.0 I4D TSS, 2.0 D (A) Engine No: 151103W0350204DTD

Reg. Date: 16/02/2016 (Man. Year: 2015) Chassis No: SAJAB4AN1GA933427

Colour: Black Odometer: 59639 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45R18 Rear Tyre Size: 225/45R18

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,736.63	8,679.71	4,056.92	31.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,280.00	760.00	37.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,776.63	9,959.71	4,816.92	32.60
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	14,776.63	7,900.00	6,876.63	46.54
+ GST 7.00/7.00% (S\$)	1,034.36	553.00	481.36	46.54
Nett Amount (S\$)	15,810.99	8,453.00	7,357.99	46.54

INSPECTION

Date of Assignment: 04/10/2021

Date Inspected: 24/09/2021 Inspected At: VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #03-03
SIN MING AUTO CITY
SINGAPORE 575722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 May 2022)	
Parts:	N/A	JAGUAR XE 2.0 I4D TSS 2.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML8096D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH HEADLAMP	Cracked	3,667.30 FL	*3,277.62 FL
2	1		*FRONT BUMPER	Deformed	2,180.00 FL	*2,180.00 FL
3	1		*FRONT BUMPER LH SIDE RETAINER	Deformed	68.00 FL	*68.00 FL
4	1		*FRONT LH FENDER	Repair	920.00 FL	*- FL
5	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	410.20 FL	*- FL
6	10		*FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	27.00 FL	*- FL
7	1		*FRONT LH WHEEL SPORT RIM	Cut	2,271.40 FL	*1,254.00 FL
8	1		*FRONT LH WHEEL SHOCK ABSORBER	Not Necessary	693.10 FL	*- FL
9	1		*FRONT LH WHEEL KNUCKLE ARM	Bent	2,048.90 FL	*2,048.90 FL
10	1		*FRONT LH WHEEL KNUCKLE ARM BEARING	Bent	815.60 FL	*815.60 FL
11	1		*FRONT LH WHEEL LOWER ARM	Not Necessary	739.20 FL	*- FL
12	1		*FRONT LH WHEEL TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,120.70	9,644.12
- List Item Discount on L Items 10.00/10.00% (\$)	1,384.07	964.41
Total Parts (\$)	12,736.63	8,679.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
2	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	280.00	150.00
3	TO DIAGNOSE ELECTRICAL COMPONENTS	New	180.00	50.00
4	TO REPAIR DAMAGES	New	680.00	500.00
5	TO SPRAY PAINTING	New	780.00	500.00
			Gross Labour Cost (\$)	2,040.00
				1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >