

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21009814/T1RA3Q2  
**Date:** 05/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100418989
<b>Claimant Vehicle No :</b>	GBD4061C	<b>Insured Vehicle No :</b>	SKT9303G
Date of Loss:	18/09/2021	Nature of Claim:	TP
		Claim No:	1482010155SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBD4061C</b>		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30342354K
Reg. Date:	17/10/2014 (Man. Year: 2014)	Chassis No:	JN1SC2F24Z0856564
Colour:	Silver	Odometer:	16785 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

11/5/21, 5:16 PM

Adjuster Report

Date of Assignment: 23/09/2021

Date Inspected: 24/09/2021 Inspected At:

Yeow Koon Motor Spray Painting (HQ)  
BLK 9002 TAMPINES ST 93 #01-34 TAMPINES IND PARK A  
Singapore 528836

Estimated Period of Repair: 6.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Torn	0.00 F	*- F
2	1		*FRT BUMPER BRACKET	Necessary	0.00 F	*- F
3	1		*FRT HEADLAMP LH	Cracked	0.00 F	*- F
4	1		*FRT HEADLAMP LOWER GARNISH LH	Deformed	0.00 F	*- F
5	1		*FRT CORNER PANEL LH	Bent	0.00 F	*- F
6	1		*FRT LH WING MIRROR STAY	Bent	0.00 F	*- F
7	1		*FRT LH WING MIRROR BIG	Missing	0.00 F	*- F
8	1		*FRT LH WING MIRROR CIRCLE	Cracked	0.00 F	*- F
9	1		*FRT LH WING MIRROR STAY GARNISH	Deformed	0.00 F	*- F
10	1		*FRT LH DOOR	Repair	0.00 F	*- F
11	1		*FRT LH STEP GARNISH	Cracked	0.00 F	*- F
12	1		*FRT LH DOOR PILLAR	Repair	0.00 F	*- F
13	1		*FRT LH DOOR COMPANY STICKER	Necessary	0.00 F	*- F

F=Franchise part.

**Total Parts (\$\$)**
**0.00**
**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**