

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR21009820/Euf3e2	
	60 WOODLANDS I SINGAPORE 7577	NDUSTRIAL PARK E4 05		Date:	23/09/2021	
				Code:	SMR	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 1955H	Veh. Inspected	i l	FBM 7681X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/09/21/2035	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		21/09/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. S1000 XR	c.c		999	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WB10D0304GZ444579	Colour		RED	
	Odometer	28096 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/70Z R17	MICHELIN		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	190/55Z R17	MICHELIN		4 mm	
	L/H Rear Tyre				mm	
4.	. Description of Damages					
	THE VEHICLE SUS	E VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5.	General Information					
	Accident Date	16/09/2021	Inspect Date /	Time	22/09/2021 (09:54 AM)	
	Survey held at	Survey held at 20 Bukit Batok Crescent #01-19				
	Repairer	PRIMERO RACING				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. ITHE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/SMR21009820/Euf3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser