

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21008552/GVF3E2-1

Date: 20/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SKW6830E **Insured Vehicle No :** SLH4457E
Date of Loss: 14/08/2021 Nature of Claim: TP Claim No: MFL2021D0003440

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW6830E**
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4022824
Reg. Date: 11/11/2015 (Man. Year: 2015) Chassis No: RU11102817
Colour: Maroon Odometer: 120999 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,990.50	9,386.88	27,603.62	74.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,060.00	3,290.00	2,770.00	45.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,050.50	12,676.88	30,373.62	70.55
Approved Total (Overridden) (S\$)		10,150.00		
Nett Amount (S\$)	43,050.50	10,150.00	32,900.50	76.42

INSPECTION

Date of Assignment: 21/09/2021
Date Inspected: 16/08/2021 Inspected At: Celebrity Auto (HQ)
Singapore 575642
Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW6830E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,020.00 F	*- FL
2	2		*BONNET HINGE	Repair	120.00 F	*- FL
3	1		*BONNET LATCH	Serviceable	128.00 F	*- FL
4	1		*BONNET LEADING EDGE SEAL RUBBER	Serviceable	70.80 F	*- FL
5	1		*HEADLAMP N/S	Serviceable	1,759.40 F	*- FL
6	1		*FRONT BUMPER COVER	Damaged	997.00 F	*880.00 FL
7	2		*FRONT BUMPER SIDE RETAINER	Cracked	132.00 F	*120.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Damaged	452.00 F	*321.00 FL
9	1		*RADIATOR LOWER SUPPORT FRAME	Repair	538.00 F	*- FL
10	1		*FRONT BUMPER UPPER WEATHERSTRIP	Necessary	72.00 F	*72.00 FL
11	1		*FRONT GRILLE ASSY	Damaged	617.00 F	*345.00 FL
12	1		*FRONT GRILLE CHROME MOULDING	Serviceable	114.00 F	*- FL
13	1		*FRONT GRILLE HONDA LOGO	Necessary	65.00 F	*58.00 FL
14	1		*FRONT BUMPER LOWER GRILLE	Serviceable	162.00 F	*- FL
15	2		*FOG LAMP ASSY (NPA)	Serviceable	0.00 F	*- FL
16	2		*FOG LAMP TRIM COVER	Serviceable	110.00 F	*- FL
17	1		*SUPPORT PANEL	Repair	532.00 F	*- FL
18	1		*SUPPORT PANEL TOP GARNISH	Serviceable	125.00 F	*- FL
19	1		*FRONT FENDER (2PCS)	Damaged (1Pc Only)	1,176.00 F	*405.20 FL
20	2		*FRONT FENDER SPLASH SHIELD	Serviceable	311.00 F	*- FL
21	2		*FRONT FENDER ARCH GARNISH	Damaged	576.00 F	*315.20 FL
22	1		*FRONT SHOCK ABSORBER (2PCS)	Damaged (1Pc Only)	968.00 F	*360.70 FL
23	2		*FRONT SHOCK ABSORBER TOP MOUNT	Serviceable	166.00 F	*- FL
24	1		*FRONT LOWER ARM (2PCS)	Bent (1Pc Only)	710.00 F	*291.60 FL
25	1		*FRONT STEERING KNUCKLE (2PCS)	Warped (1Pc Only)	1,200.00 F	*249.90 FL
26	1		*FRONT STEERING KNUCKLE BEARING (2PCS)	Jammed (1Pc Only)	380.00 F	*141.80 FL
27	1		*FRONT STABILISER BAR	Serviceable	489.00 F	*- FL
28	2		*FRONT STABILISER LINK	Serviceable	356.00 F	*- FL
29	1		*FRONT SUSPENSION CROSS MEMBER	Serviceable	1,043.00 F	*- FL
30	1		*FRONT DRIVE SHAFT N/S	Damaged	1,496.00 F	*1,253.50 FL
31	1		*UNDERBODY TENSION FRAME	Serviceable	685.00 F	*- FL
32	1		*ENGINE SPLASH COVER	Serviceable	189.00 F	*- FL
33	1		*UNDERBODY SHIELD COVER	Torn	335.00 F	*250.00 FL
34	2		*FRONT BRAKE ROTOR SHIELD	Serviceable	310.00 F	*- FL
35	1		*STEERING RACK & PINION ASSY	Serviceable	1,850.00 F	*- FL
36	1		*TIE ROD END (2PCS)	Bent (1Pc Only)	276.00 F	*75.20 FL
37	1		*FRONT BUMPER LOWER LIP	Damaged	232.00 F	*232.00 FL
38	1		*FRONT BUMPER LOWER COWLING	Serviceable	139.00 F	*- FL
39	1		*RADIATOR ASSY	Damaged	1,250.00 F	*987.90 FL
40	2		*RADIATOR FRONT AIR FLAP	Serviceable	298.00 F	*- FL
41	1		*AIRCON CONDENSER	Damaged	768.00 F	*768.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*A PILLAR LOWER O/S	Repair	543.00 F	*- FL
43	1		*FRONT DOOR N/S	Damaged	1,185.00 F	*855.50 FL
44	1		*REAR DOOR N/S	Damaged	955.00 F	*955.00 FL
45	1		*ROCKER PANEL N/S (NPA)	Repair	0.00 F	*- FL
46	1		*ROCKER PANEL OUTER GARNISH N/S	Damaged	389.00 F	*389.00 FL
47	1		*FRONT DOOR HINGE LOWER N/S	Bent	144.00 F	*52.00 FL
48	1		*FRONT DOOR CHECKER N/S	Damaged	63.00 F	*48.00 FL
49	1		*FRONT DOOR HARNESS BOOT N/S	Serviceable	55.00 F	*- FL
50	2		*REAR FENDER	Repair	2,370.00 F	*- FL
51	2		*REAR FENDER ARCH GARNISH	Damaged	302.00 F	*302.00 FL
52	2		*REAR FENDER SPLASH SHIELD	Serviceable	351.00 F	*- FL
53	1		*REAR BUMPER	Serviceable	760.50 F	*- FL
54	2		*REAR BUMPER RETAINER	Serviceable	72.00 F	*- FL
55	2		*TAILLAMP LOWER COVER	Damaged	337.60 F	*337.60 FL
56	2		*TAILLAMP	Serviceable	892.20 F	*- FL
57	1		*REAR AXLE	Serviceable	1,254.00 F	*- FL
58	1		*REAR AXLE WHEEL HUB (2PCS)	Damaged (1Pc Only)	502.00 F	*201.00 FL
59	1		*REAR AXLE WHEEL HUB BEARING (2PCS)	Jammed (1Pc Only)	363.00 F	*134.00 FL
60	10		*BONNET INSULATOR CLIPS	Serviceable	50.00 FS	*- FS
61	12		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
62	8		*FRONT SUPPORT TOP PANEL GARNISH CLIPS	Serviceable	40.00 FS	*- FS
63	1		*FRONT LICENCE PLATE & FRAME	Damaged	65.00 FS	*40.00 FS
64	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
65	1		*ALLOY WHEEL 16 (4PCS)	Damaged (2Pcs Only)	1,800.00 FS	*500.00 FS
66	1		*TYRE 215/60R16 (4PCS)	Cut (2Pcs Only)	1,120.00 FS	*216.00 FS
67	1		*FRONT FENDER ARCH GARNISH CLIPS (12PCS)	Necessary	60.00 FS	*20.00 FS
68	1		*REAR FENDER ARCH GARNISH CLIPS (12PCS)	Necessary	60.00 FS	*20.00 FS
69	10		*FRONT DOOR INNER TRIM BOARD N/S CLIPS	Necessary	50.00 FS	*20.00 FS
70	10		*REAR DOOR INNER TRIM BOARD N/S CLIPS	Necessary	50.00 FS	*20.00 FS
71	8		*FRONT GRILLE ASSY CLIPS	Necessary	40.00 FS	*20.00 FS
72	1		*FRONT FENDER SPLASH SHIELD CLIPS (16PCS)	Necessary	80.00 FS	*30.00 FS
73	16		*REAR FENDER SPLASH SHIELD CLIPS	Serviceable	80.00 FS	*- FS
74	12		*ENGINE SPLASH COVER CLIPS	Serviceable	60.00 FS	*- FS
75	1		*UNDERBODY SHIELD COVER CLIPS (16PCS)	Necessary	80.00 FS	*30.00 FS
76	8		*FRONT BUMPER LOWER COWLING CLIPS	Necessary	40.00 FS	*20.00 FS
77	8		*ROCKER PANEL OUTER GARNISH N/S CLIPS	Necessary	40.00 FS	*30.00 FS
78	12		*REAR BUMPER CLIPS	Serviceable	60.00 FS	*- FS
79	12		*TAILLAMP LOWER COVER CLIPS	Necessary	60.00 FS	*30.00 FS
80	4		*AUTO TRANSMISSION FLUID (4L)	Serviceable	200.00 FS	*- FS
81	1		*SUNDRIES	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,990.50	11,467.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,080.22
Total Parts (\$\$)	36,990.50	9,386.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	2,400.00	800.00
2	TO DISCONNECT WIRE HARNESSSES OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS & TAILLAMPS	New	120.00	30.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT & REAR AFFECTED AREA / PANEL	New	2,000.00	1,800.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	150.00	80.00
5	TO REMOVE AND REPLACE A/C CONDENSER. TO RECHARGE SYSTEM & CHECK A/C FUNCTIONALITY	New	180.00	60.00
6	TO REMOVE AND REPLACE RADIATOR. TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY	New	180.00	60.00
7	TO REMOVE AND REPLACE ALL TYRES AND RIMS. TO PERFORM TYRE BALANCING	New	160.00	20.00
8	TO REMOVE AND REFIT FRONT & REAR UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	400.00	300.00
9	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
10	TO RESET ECU PROGRAMMING	New	200.00	0.00
11	TOWING CHARGES	New	150.00	80.00
Gross Labour Cost (\$\$)			6,060.00	3,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >