

CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009

Fax: 62874788

Tel: 62856178

INVOICE


GLOBALEE SDN BHD
C/o Kaki Bukit Autohub
2 Kaki Bukit Avenue 2, #01-17
Singapore 417921

Invoice No: CLM13040TP/T

Date: 9th April 2016

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: BJN 8800</u> Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc*** (photographs - 214 copies)			\$1,494.00
			Total:	\$1,494.00

We thank you for the opportunity to serve you and assure you of our best at all times


PATRICK NG
Automotive Engineer Assessor
MIMI, MITE, LCGI, I ENG, LAE, CGLI FTC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CLM13040TP/T

1 REFERENCE			
Date of request	: 22nd October 2015		
Requested by	: GLOBALEE SDN BHD C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17 Singapore 417921		
Type of claim	: Third party		
Workshop	: M/S Twincar Automotive Pte Ltd Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17 Singapore 417921		
Date of survey	: 22nd October 2015		
Accident date	: 19th October 2015		
2 DETAILS OF VEHICLE			
Registration No.	: BJN 8800		
Make & Model	: Scania R124 (RB/EPB ACH)		
Engine No.	: DC1201L016155513		
Chassis No.	: XLER6X20004466028		
Year of Registration	: 10th September 2007		
Transmission	: Manual		
Colour	: White		
3 STATIC CHECK			
Steering	: see annex(es)	Paintwork	: Good
Footbrake	: see annex(es)	Modification	: Nil
Handbrake	: see annex(es)	General condition	: Good
4 TYRE CONDITION			
	<u>Nearside/Make</u>	<u>Offside/Make</u>	<u>Size</u>
Front axle	: 10mm/Copartner	10mm/Copartner	: 295/80 R22.5
2nd axle	: 10mm/Copartner	10mm/Copartner	: 295/80 R22.5
3rd axle	: 10mm/Copartner	10mm/Copartner	: 295/80 R22.5
Rear axle	: 10mm/Copartner	10mm/Copartner	: 295/80 R22.5
5 POINT OF IMPACT			
See Annex(es) and Motor Accident Reports			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Report No.

CLM13040TP/T

Vehicle No. BJN8800

Parts and Labour Assesment**PARTS**

Description of part	Repairer's Qty	Qty	Condition	Repairer's estimate	Our adjustment
HOT LINE SPAD (STICKER)	2	2	NECESSARY	12.00	✓ 12.00
MALAYSIA SPEED LIMIT STICKER	2	2	NECESSARY	12.00	✓ 12.00
REAR BOGIE AXLE	1	1	DISTORTED/CRACKED	12,800.00	4000 ✓ 12,800.00
REAR BOGIE AXLE BRAKE DRUM RH	1	1	SHIFTED/JAMMED	1,680.00	✓ 1,680.00
REAR BOGIE AXLE WHEEL BEARING (INNER) RH	1	1	DISTORTED/JAMMED	198.00	✓ 198.00
REAR BOGIE AXLE WHEEL BEARING (OUTER) RH	1	1	DISTORTED/JAMMED	198.00	✓ 198.00
REAR BOGIE AXLE WHEEL BEARING	1	1	NECESSARY	35.00	✓ 35.00
Lock WASHER RH	1	1	NECESSARY	35.00	✓ 35.00
REAR BOGIE AXLE WHEEL BEARING	1	1	LEAKED	40.00	✓ 40.00
OIL SEAL	1	1	BUCKLED	5,800.00	2600 ✓ 5,800.00
REAR CRASH GUARD ASSY	1	1	DISTORTED/SLACK	980.00	X 980.00
REAR LEAVE SPRING ASSY L/R <i>None new</i>	2	2	DISTORTED/JAMMED	3,900.00	X 3,900.00
REAR LEAVE SPRING EQUALIZER ASSY RH <i>None new</i>	1	1	DISTORTED/JAMMED	3,900.00	X 3,900.00
REAR LEAVE SPRING EQUALIZER BRACKET CROSS MEMBER <i>None new</i>	1	1	CRACKED/BENT	1,800.00	X 1,800.00
REAR LEAVE SPRING U CLAMP L/R <i>RH Bent</i>	4	4	BENT	500.00	250 ✓ 500.00
REAR LEAVE SPRING U CLAMP SEAL <i>RH new</i>	2	2	CRACKED	248.00	124 ✓ 248.00
GUIDE L/R	2	2	NECESSARY	140.00	60 ✓ 140.00
REAR REFLECTIVE STICKER	1	1	CRACKED	85.00	✓ 85.00
REAR RH MARKER LAP	1	1	CUT	120.00	✓ 120.00
REAR RH MUDFLAP	1	1	DENTED/BENT	560.00	✓ 560.00
REAR RH MUDGUARD	1	1	DENTED/BENT	35.00	✓ 35.00
REAR RH NUMBER PLATE	1	1	CRACKED	2,300.00	X 2,300.00
REAR RH SIDE BOARD <i>Repis</i>	1	1	CUT/LEAKED	880.00	502 ✓ 880.00
REAR RH TYRE (INNER)	1	1	CUT/LEAKED	880.00	500 ✓ 880.00
REAR RH TYRE (OUTER)	1	1	WARPED	1,850.00	X 1,850.00
REAR RH WHEEL RIM (INNER) <i>None new</i>	1	1	DENTED/BENT/CUT	1,850.00	900 ✓ 1,850.00
REAR RH WHEEL RIM (OUTER)	1	1	BENT	899.00	✓ 899.00
REAR TORQUE ROD BRACKET RH	1	1	BENT	490.00	✓ 490.00
REAR TORQUE ROD RH	1	1	BENT/JAMMED	60.00	✓ 60.00
SIDE BOARD CHAIN LOCK	1	1	BENT/SHIFTED	840.00	X 840.00
SIDE BOARD HINGES <i>None new</i>	4	4	BENT/SHIFTED	840.00	X 840.00
TAIL BOARD ANGLE IRON LOCK BEAM	1	1	DENTED/BENT	300.00	200 ✓ 300.00
TAIL BOARD ASSY	1	1	CRACKED/BENT	2,100.00	✓ 2,100.00

1800.

TAIL BOARD CHAIN LOCK HOOK	2	2	BENT	120.00	80 120.00
TAIL BOARD HINGES <i>2 pieces bent</i>	4	4	BENT	840.00	300 840.00
TAIL BOARD SUPORT PILLAR RH	1	1	DENTED/BENT	680.00	350 680.00
TAILLAMP PANEL RH	1	1	BENT	128.00	✓ 128.00
TAILLAMP RH (LOWER)	1	1	CRACKED	250.00	✓ 250.00
TAILLAMP RH (TOP)	1	1	CRACKED	210.00	✓ 210.00
Subtotal before discount				S\$ 43,820.00	S\$ 43,820.00
Percentage discount 0% and 0%				S\$ 0.00	S\$ 0.00
Sub-total				S\$ 43,820.00	S\$ 43,820.00
Parts-total				S\$ 43,820.00	S\$ 43,820.00

16676

LABOUR

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,100.00	1500 1,800.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,800.00	1800 2,100.00
To spray anti rust undercarriage coating.	250.00	✓ 200.00
To remove, replace rear axle housing, rear half shaft, oil seal, u bolt, clamp, rear leave spring and etc	1,800.00	800 1,200.00
To check wiring system and light.	120.00	30 60.00
Labour Total		S\$ 7,070.00 S\$ 5,360.00
Parts & Labour Total		S\$ 50,890.00 S\$ 49,180.00

74330

Results of inspection of the accident vehicle are as shown above,

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 41,800.00
and the recommended number of working days for the repairs is within 10 day(s).


PATRICK (SURVEYOR)
Automotive Appraiser

total: 21006

L/S: 16.8/10

09 days