CARLINK CONSULTANCY

60 Hillside Drive Singapore 549009 Tel: 62856178

Fax:

62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CLM13040TP/T

REFERENCE

Date of request Requested by

: 22nd October 2015

: GLOBALEE SDN BHD

C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17

Singapore 417921

Type of claim

: Third party

Workshop

: M/S Twincar Automotive Pte Ltd

Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-17

Singapore 417921

Date of survey

: 22nd October 2015

Accident date

: 19th October 2015

2 DETAILS OF VEHICLE

Registration No.

: BJN 8800

Make & Model

: Scania R124 (RB/EPB ACH)

Engine No. Chassis No.

: DC1201L016155513

: XLER6X20004466028

Year of Registration

: 10th September 2007

Transmission

: Manual : White

3 STATIC CHECK

Steering

Colour

: see annex(es)

Paintwork

: Good

Footbrake

: see annex(es)

Modification

: Nil

Handbrake

: see annex(es)

General condition : Good

4 TYRE CONDITION

Nearside/Make

Offside/Make

Size

Front axle 2nd axle

: 10mm/Copartner : 10mm/Copartner 10mm/Copartner : 295/80 R22.5 10mm/Copartner : 295/80 R22.5

295/80 R22.5

3rd axle Rear axle : 10mm/Copartner : 10mm/Copartner 10mm/Copartner 10mm/Copartner

295/80 R22.5

5 POINT OF IMPACT

See Annex(es) and Motor Accident Reports

6 REMARK

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.

Report No. CLM13040TP/T Vehicle No. BJN8800

Parts and Labour Assesment

PARTS

Danairer's			Repairer's	Our
Qty	Qty		estimate	adjustment
2	2			12.00
2	2			12.00
1	I	DISTORTED/CRACKED	12,800.00	12,800.00
1	1	SHIFTED/JAMMED	1,680.00	1,680.00
1	1	DISTORTED/JAMMED	198.00	198.00
1	1	DISTORTED/JAMMED	198.00	198.00
1	1	NECESSARY	35.00	35.00
1	1	LEAKED	40.00	40.00
1	1	BUCKLED	5,800.00	5,800.00
2	2	DISTORTED/SLACK	980.00	980.00
1	1	DISTORTED/JAMMED	3,900.00	3,900.00
1	1	CRACKED/BENT	1,800.00	1,800.00
4	4	BENT	500.00	500.00
2	2	CRACKED	248.00	248.00
		NECESSARY	140.00	140.00
1	1	CRACKED	85.00	85.00
1	1	CUT	120.00	120.00
1	1	DENTED/BENT	560.00	560.00
1	1	DENTED/BENT	35.00	35.00
I	1	CRACKED	2,300.00	2,300.00
1	1	CUT/LEAKED	880.00	880.00
ì	1	CUT/LEAKED	880.00	880.00
1	1	WARPED	1,850.00	1,850.00
I	1	DENTED/BENT/CUT	1,850.00	1,850.00
1	1	BENT	899.00	899.00
1	1	BENT	490.00	490.00
1	1	BENT/JAMMED	60.00	60.00
4	4	BENT/SHIFTED	840.00	840.00
1	1	DENTED/BENT	300.00	300.00
1	1	CRACKED/BENT	2,100.00	2,100.00
	2 2 1 1 1 1 1 2 2 1 1 1 1 1 1 1 1 1 1 1	Qty 2 2 2 2 2 1	Qty Qty Condition 2 2 NECESSARY 1 1 DISTORTED/CRACKED 1 1 DISTORTED/JAMMED 1 1 DISTORTED/JAMMED 1 1 DISTORTED/JAMMED 1 1 BUCKLED 2 2 DISTORTED/JAMMED 1 1 DISTORTED/JAMMED 1 1 CRACKED/BENT 4 4 BENT 2 2 CRACKED 1 1 CUT/LEAKED 1 1 CUT/LEAKED 1 1 DENTED/BENT/CUT 1 1 DENTED/BENT/CUT 1 1 BENT/JAMMED 4 4 BENT/SHI	Qty Condition estimate 2 2 NECESSARY 12.00 1 1 DISTORTED/CRACKED 12,800.00 1 1 SHIFTED/JAMMED 1,680.00 1 1 DISTORTED/JAMMED 198.00 1 1 DISTORTED/JAMMED 198.00 1 1 NECESSARY 35.00 1 1 LEAKED 40.00 1 1 BUCKLED 5,800.00 2 2 DISTORTED/JAMMED 3,900.00 1 1 DISTORTED/JAMMED 3,900.00 1 1 CRACKED/BENT 1,800.00 4 4 BENT 500.00 4 4 BENT 500.00 2 2 CRACKED 248.00 2 2 CRACKED 248.00 2 2 NECESSARY 140.00 1 1 CUT 120.00 1 1 CUT 120.00

TAIL BOARD CHAIN LOCK HOOK	2		2	BENT	120.00	120.00
TAIL BOARD HINGES	4		4	BENT	840.00	840.00
TAIL BOARD SUPORT PILLAR RH	1		1	DENTED/BENT	680.00	680.00
TAILLAMP PANEL RH	1		1	BENT	128.00	128.00
TAILLAMP RH (LOWER)	1		1	CRACKED	250.00	250.00
TAILLAMP RH (TOP)	1		1	CRACKED	210.00	210.00
				Subtotal before discount	S\$ 43,820.00	S\$ 43,820.00
Pero	centage discount	0% and	0%		S\$ 0.00	S\$ 0.00
				Sub-total	S\$ 43,820.00	S\$ 43,820.00
				Parts-total	S\$ 43,820.00	S\$ 43,820.00
LABOUR						
Γο re-spray painting on the change boo Γο ravide labour, workmanship to ch					2,100.00	1,800.00
iligi, oody structure, body alignments					2,800.00	2,100.00
To spray anti rust undercarriage coatin					250.00	200.00
To remove, replace rear axle housing,		seal.u bolt	t,clamp	rear leave spring and etc	1,800.00	1,200.00
To check wiring system and light.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				120.00	60.00
				Labour Total	S\$ 7,070.00	S\$ 5,360.00
				Parts & Labour Total	S\$ 50,890.00	S\$ 49,180.00

Results of inspection of the accident vehicle are as shown above,

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is: \$\\$\ 41,800.00 \\
\text{ind the recommended number of working days for the repairs is within 10 day(s).}

Automotive Appraiser























Company Reg No: 201403586G

50 PlayFair Road Noel Building #04-01 Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

VEHICLE DAMAGE ASSESSMENT REPORT

To:

48 Changi south street 1 Singapore 486130

REFERENCES

Appraisal VP Ref No

: VPA-2015/00662

Date of Report

: 26/10/2015

Claim Type

: Third Party Claim

Date of Request

: 21/10/2015

Third party vehicle

: BJN8800

Date of Accident

: 19/10/2015

Insured Vehicle

: YM4716C

Date of Inspection

: 21/10/2015

Your Reference No. Report Requested By : PLS ADVISE

: ISAAC

DAMAGED VEHICAL PARTICULARS

Registration Plate No

: BJN8800

: SCANIA R124

Engine Modification Pre-accident damage

: NIL : NIL

Colour

: BLUE : 10/09/2007 General Condition

: Good

Manufacturing Year Engine No

Model / Make

: DC1201L200044662028

General Paint Work

: Good : Serviceable

Engine Capacity

: 11700

Steering

: Serviceable

Chassis No

: XLER6X200004466028

Handbrake Footbrake

: Serviceable

Odometer No Transmission

: NIL

: MANAUL

TYRES CONDITION

Front Right

: 5mm

Rear Left

: 5mm

Make

: COPARTNER

Make

: COPARTNER

Size

: 295/80 R22.5

Size

: 295/80 R22.5

Front Left

: 6mm

Rear Right

Make

: COPARTNER

: 6mm

Size

: 295/80 R22.5

Make Size

COPARTNER : 295/80 R22.5

VEHICAL REPAIR COST

Descriptions	Repairer (\$\$)	Difference (S\$)	Adjuster (S\$)
Parts	0.00	0.00	0.00
Labour	0.00	0.00	0.00
Calculated Cost (S\$):	0.00	0.00	0.00

Recommended Lump sum Repair Cost (S\$)

Estimate Repair Duration

0.00

Survery Inspection At Survery Inspection Address

TwinCar Automotive Pte Ltd 2 Kaki Bukit Ave 2

#01-18 Singapore 417921

This survey was conducted by Appraisal VP Pte Ltd without prejudice basis and we do not authorized repair. Report by Appraisal VP Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehical. All findings and recommendations are listed accordingly and final decision of settlement to your goodselves. Any disclosure or publications of it or parts thereof shall be the responsibility of such person No liability shall be attached to VP Appraisal VP Pte Ltd therefore



Company Reg No: 201403586G

50 PlayFair Road Noel Building #04-01 Singapore 367995 | Tel: +65 98511914 | Email: mail@xpappraisal.com

VEHICLE DAMAGE ASSESSMENT REPORT

Reference No

: VPA-2015/00662

Vehicle No

: BJN8800

ACCIDENT BRIEF

From documents sighted, the Insured's vehicle and Third Party's vehicle were involved in a rear to head collision along west coast highway clementi road along west coast highway after pasir panjang wholesale market.

On site survey inspection revealed that the damage noted are consistent with the accident as reported.

Damage at the Rear panel, rear taillamp, rear signal lamp wooden tailgate, and etc.

ADVICE

Twincar automotive pte ltd did not submitted the estimate during the inspection and we are unable to adjust the repair costs.

We are pleased to submit our inspection survey report and photographs for your kind attention. All survey and inspection work was carried out to the best of our ability, knowledge and experience.

Jaclyn/Loh/ Appraiser

Appraisal VP Pte Ltd

Disclaimer:


This survey was conducted by Appraisal VP Pte Ltd without prejudice basis and we do not authorized repair. Report by Appraisal VP Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle. All findings and recommendations are listed accordingly and final decision of settlement to your good selves. Any disclosure or publications of it or parts thereof shall be the responsibility of such person. No liability shall be attached to Appraisal VP Pte Ltd therefore.
































Company Reg No: 201403586G

50 PlayFair Road Noel Building #04-01 Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

VEHICLE DAMAGE ASSESSMENT REPORT

To:

First Capital Insurance Limited

36 Robinson Road #16-01 City House Singapore 068877

REFERENCES

Appraisal VP Ref No

: VPA-2021/0021 : RE APPRAISAL Date of Report

: 15/01/2021

Claim Type

Date of Request

: 21/10/2015

Third party vehicle

: BJN8800

Date of Accident

Insured Vehicle

: YM4716C

: 19/10/2015

Your Reference No.

: D15011774MFCV

Report Requested By

: Esther

DAMAGED VEHICAL PARTICULARS

Registration Plate No

: BJN8800

Engine Modification

: NIL

Model / Make

: Scania R124

Pre-accident damage

: NIL

Colour

: BLUE

General Condition

: Good : Good

Manufacturing Year

: 10/09/2007 : DC1201L016155513

General Paint Work Steering

: Serviceable

Engine No **Engine Capacity**

: N/A

Handbrake

: Serviceable

Chassis No

: XLER6X20004466028

Footbrake

: Serviceable

Odometer No Transmission

: N/A

: MANUAL

TYRES CONDITION

Front Right

: 5mm

Rear Left

Make

: COPARTNER

Make

: 5mm

Size

: 295/80 R22.5

Size

: COPARTNER : 295/80 R22.5

Front Left

: 6mm

Rear Right

: 6mm

Make Size

: COPARTNER : 295/80 R22.5

Make

Size

: COPARTNER : 295/80 R22.5

VEHICAL REPAIR COST

	Repairer (S\$)	CarLink Consultancy	Our Adjuster (S\$)
Descriptions			
Parts	43,820.00	34,729.10	9,090.90
Labour	7,070.00	1,710.00	5,360.00
Calculated Cost (S\$):	50,890.00	36,439.10	14,450.90

Recommended Lump sum Repair Cost (S\$)

Estimate Repair Duration

Survery Inspection At Survery Inspection Address 9,200.00

8 days

Twincar Automotive Pte Ltd

2 Kaki Bukit Ave 2

#01-18 Singapore 417921

<u>Disclaimer:</u>
This survey was conducted by Appraisal VP Pte Ltd without prejudice basis and we do not authorized repair. Report by Appraisal VP Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehical. All findings and recommendations are listed accordingly and final decision of settlement to your goodselves. Any disclosure or publications of it or parts thereof shall be the responsibility of such person.

No liability shall be attached to VP Appraisal VP Pte Ltd therefore.



50 PlayFair Road Noel Building #04-01 Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

ANNEX A

VEHICLE DAMAGE ASSESSMENT REPORT

Reference No : VPA-2021/0021 Vehicle No : BJN8800

Workshop Twincar Automotive Pte Ltd

List of Damaged Parts

S/No	Qty	Description	Repairer's Amount (S\$)	Carlink Consultancy (S\$)	Adjuster's Amount (S\$
1	2	Hot Line Spad (stciker)	12.00	12.00	12.00
2	2	Malaysia speed limit sticker	12.00	12.00	12.00
3	1	Rear bagie axle	12,800.00	12,800.00	0.00
4	1	Rear bogie axle brake drum rh	1,680.00	1,680.00	0.00
5	1	Rear bogie axle wheel bearing (inner) rh	198.00	198.00	0.00
6	1	Rear bogie axle wheel bearing (outer) rh	198.00	198.00	198.00
7	1	Rear bogie axle wheel bearing lock washer rh	35.00	35.00	35.00
8	1	Rear bogie axle wheel bearing oil seal	40.00	40.00	40.00
9	1	Rear crach guard assy	5,800.00	5,800.00	3,000.00
10	2	Rear leave spring assy I/r	980.00	980.00	0.00
11	1	Rear leave spring equalizer assy rh	3,900.00	3,900.00	0.00
		Rear leave spring equalizer bracket cross	0,000.00	3,900.00	0.00
12	1	member	1,800.00	1,800.00	0.00
13	4	Rear leave spring U clamp I/r	500.00	500.00	
14	2	Rear leave spring U clamp Seal guide L/r	248.00	248.00	0.00
15	2	Rear reflector sticker	140.00	The second second	0.00
16	1	Rear rh marker lap	85.00	140.00	70.00
17	1	Rear rh mudflap	120.00	85.00	85.00
18	1	Rear rh mudguard	560.00	120.00	120.00
19	1	Rear rh number plate	35.00	560.00	560.00
20	1	Rear rh side board		35.00	35.00
21	1	Rear rh tyre (inner)	2,300.00	2,300.00	1,000.00
22	1	Rear rh tyre(outer)	880.00	880.00	0.00
23	1	Rear rh wheel rim (inner)	880.00	880.00	880.00
24	1	Rear rh wheel rim (outer)	1,850.00	1,850.00	900.00
25	1	Rear torque rod bracket rh	1,850.00	1,850.00	0.00
26	1	Rear torque rod th	899.00	899.00	0.00
27	1	Side board chain lock	490.00	490.00	0.00
28	4	Side board hinges	60.00	60.00	60.00
29	1	Tailboard angle iron lock beam	840.00	840.00	0.00
30	1	Tailboard assy	300.00	300.00	300.00
31	2	Tailboard chain lock hook	2,100.00	2,100.00	1,470.00
32	4	Tailboard hinges	120.00	120.00	60.00
33	1	Tailboard support pillar rh	840.00	840.00	336.00
34	1	Taillamp panel rh	680.00	680.00	340.00
55	1	Taillamp rh (lower)	128.00	128.00	128.00
6	1	Taillamp rh (top)	250.00	250.00	250.00
	'	railiamp m (top)	210.00	210.00	210.00
		Sub Total	43,820.00	43,820.00	10,101.00
	- 1	Less 10%			1,010.10
	l	Total	43,820.00	43,820.00	9,090.90

FINAL TOTAL	43,820.00	43,820.00	9,090.90



Company Reg No: 201403586G

50 PlayFair Road Noel Building #04-01 Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

ANNEX B

VEHICLE DAMAGE ASSESSMENT REPORT

Reference No : VPA-2021/0021

Vehicle No : BJN8800
Workshop Twincar Automotive Pte Ltd

Labour Details

S/No	Description	Repairer's Amount (S\$)	Carlink Consultancy (S\$)	Adjustor's
1 2 3 4 5	To re-spray painting on the change bodyparts, repair portion, and To provide labour, workmanship to change the above damage To spray anti rust undercarriage coating To remove, replace rear axle housing, rear shaft shaft, oil seal, u To check wiring system and light	2,100.00 2,800.00 250.00 1,800.00 120.00	1,800.00 2,100.00 200.00 1,200.00 60.00	1,000.00 1,500.00 100.00 0.00 20.00
	Total Labour	7,070.00	5,360.00	2,620.00

ANNEX C

Repair Cost

S/No	Description	Repairer's Amount (S\$)	Carlink Consultancy (S\$)	Adjuster's	
1	Total Part Cost	43,820.00	43,820.00	9,090.90	
2	Total Repair and Labour Cost	7,070.00	5,360.00	-,	
	Total Repair Cost	50,890.00	49,180.00	11,710.90	

	Carlink Consultancy (S\$)	Adjustor's
Adjusted Repair Cost (Lump sum Repair)	\$41,800.00	\$9,200.00



Company Reg No: 201403586G

50 PlayFair Road Noel Building #04-01 Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

VEHICLE DAMAGE ASSESSMENT REPORT

Reference No

: VPA-2021/0021

Vehicle No

: BJN8800

ACCIDENT BRIEF

From documents sighted, the Insured's vehicle and Third Party's vehicle were involved in a rear to head collision along west coast highway clementi road along west coast highway after pasir panjang wholesale market.

On site survey inspection revealed that the damage noted are consistent with the accident as reported.

Damage at the Rear panel, rear taillamp, rear signal lamp wooden tailgate, and etc.

ADVICE

M/s Twincar Automotive Pte Ltd did not submit the estimate during the inspection and we are unable to adjust the repair costs in 21/10/2015

Based on our re-appraisal of the repaired vehicle, we opine the repairs generally were carried out satisfactorily, except for following items disallowed on basis as stated.

Item recommended does not warrant replace but reuse: No photo evidence support

- Rear bagie axle
- Rear bogie axle brake drum rh
- Rear bogie axle wheel bearing (inner) rh
- Rear leave spring assy I/r/ equalizer assy rh/ bracket cross member
- Rear leave spring U clamp I/r /Seal guide L/r
- Rear rh tyre (inner)/
- Rear rh wheel rim (outer)
- Rear torque rod bracket rh
- Rear torque rod rh
- Side board hinges

For your understanding of our re-adjustment on the parts, the full details are reflected in Annex A of this re-appraisal report.

We would state the claim for the repairs to be considered at \$9,200.00. on a Lump Sum basis as fair and reasonable, with a repair period of 08 working days. A

We submit our re-appraisal report for your kind consideration and would add it was carried out to the best of our ability, knowledge and experience.

We are pleased to submit our inspection survey report and photographs for your kind attention. All survey and inspection work was carried out to the best of our ability, knowledge and experience.

Jaclyn Loh Appraiser

Appraisal VP Pte Ltd

nout prejudice basis and we do not authorized repair. Report by Appraisal VP Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle. All findings and ndations are listed accordingly and final decision of settlement to your good selves. Any disclosure or publications of it or parts thereof shall be the responsibility of such person No liability shall be attached to Appraisal VP Pte Ltd therefore

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999





20131013/2140

1 of 3

Report No. T/20151019/2140

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: Vide Report No.: 19/10/2015 18:35 D/20151019/0074			Station Diary No.: 96			
Informa	nt's Particu	lars				
	Informant: BIN ABDU	L RAHMAN	Address: 373 JLN RAJAWALI 13 TAM. JOHOR	AN WAWASAN 8100 KULAI		
ID Type / PASSPO	ID No.: RT / A3601	1907	Contact No.: Home/Office:	Mobile: 600177745443		
Nationality: MALAYSIAN			Email:			
Sex: Male	Age:	Date of Birth: 20/01/1982	Type of Informant: Driver			
Race: Malay			Language: Malay	Institution / School Name:		
Occupation: Trailer-truck driver			Driving Licence Information: Class: 4 Date of Expiry: 20/01/2017			

General Information	on of the Accident			
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 19/10/2015 14:20	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 WEST COAST HIGHWAY CLEMENTI ROAD ALONG WEST COAST HIGHWAY AFT PASIR PANJANG WHOLESALE MARKET				
Weather: Clear	Ro	oad Surface: ry	Roa	d Speed Limit:
Traffic Flow:	Tr	raffic Control:	Tra: Ligi	ffic Volume:
Type of Collision: Moving Vehicle Ag	gainst - Parked Vehicle			one conveyed by oulance:

Details of Ve	Details of Vehicle Involved					
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
BJN8800	Trailer				No Damage	0
YM4716C	Lorry				Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999





2 of 3

Report No. T/20151019/2140

CONTINUATION OF REPORT

Name	AZHAR BIN ABDUL RAHMAN		ID No		A36011907	
Related Vehicle	BJN8800 (Trailer)		Contact No.		600177745443	
Hospital/Clinic	NIL		Class Drivin Licent Expiry	g	Class: 4 Date of Expiry: 20/01/2017	
Date Treatment	NIL Date Dis		Date Disch	narge	NIL	•
No. of Days granted Medical Leave (MC) NIL			Degree of	Injury	NIL	

Brief Details.

On 19/10/2015 at about 1415hrs. I was driving my lorry with a trailer attached to it (T/WC 1761) along west coast highway. I was driving on the extreme left lane and stopped at the main road near the wholesale market entry. I turned on my hazard light and alighted from my vehicle to ask for directions as it was my first time at pasir panjang area.

While I was asking for directions, I heard a loud bang 5 mins later coming from my vehicle on my back. When I turned around, I saw a white Mitsubishi futso lorry (YM4716C) had already collided with my trailer's container rear right bumper and my right rear tyre. The said vehicle which collided onto my vehicle had bad damages on the front part of the lorry. However, no one was injured in the accident.

Shortly, the traffic police arrived at scene and advised both of us to lodge a accident report. I then left the scene.

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999





3 of 3

Report No. T/20151019/2140

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
SYED IBRAHIM SHAH BIN JAJAHAN Md Shahni bin Ahmad	
Signature Of Interpreter:	Date/Time:
Not applicable	19/10/2015 18:35
Officer In Charge Of Case:	Classification Of Case:
Esther Chong	
Contact No.: 65476368	
Authentication Stamp	

Police Station Of Origin:





1 of 3

Report No. T/20151019/2178

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/10/2015 22:01		Vide Report No.:	Station Diary No.: 86		
Informa	nt's Particu	lars			
Name of YIP SOC	Informant: ON FATT		Address: APT BLK 626 PASIR R	US DRIVE 3 #06-304 SINGAPORE 510626	
ID Type / ID No.: NRIC NO / S1803294E			Contact No.: Home/Office: Mobile: 90252126		
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Age: Date of Birth: Male 47 18/11/1967		Type of Informant: Driver			
Race: Chinese		Language:	Institution / School Name:		
Occupation: Trailer-truck driver		Driving Licence Informa Class:	ntion: Date of Expiry:		

Type of Accident:	Non-Injury Attended by Police		Drink Drive: No	Date/Time of Acciden 19/10/2015 14:15	t: Type of Location Straight Road	
Location: Along Road I WEST COAST HIGH						
Weather: Clear	. 11	Road St Dry	urface:	Ro	oad Speed Limit:	
Traffic Flow:	Traffic Control: Not Controlled				Traffic Volume: Moderate	
Dual Carriage Way Type of Collision:						

Details of Ve	hicle Involve	d			THE REAL SYSTEM	
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
BJN8800	Lorry				Slightly Damaged	2
YM4716C	Lorry				Seriously Damaged	0

	Certified True Copy
The second secon	RUISUBBLIO Son 70 -C.
	and the same of th

Yet Hwee Choo CSO Traffic Police Date: 1 9 SEP 2016 Police Station Of Origin: Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457 Tel No: 1800-5852999





2 of 3

Report No. T/20151019/2178

CONTINUATION OF REPORT

Manna	YUR OCCUPA				
Name	YIP SOON FATT		ID No		S1803294E
Related Vehicle	YM4716C (Lorry)		Contac	et No.	90252126
Hospital/Clinic NIL			Class of Drivin		Class: NIL Date of Expiry: NIL
			Licence Expiry	e &	Date of Expiry: NIL
Date Treatment	NIL	Date Disch		NIL	
No. of Days granted Medical Leave (MC) NIL		Degree of I		NIL	

Brief Details.

On 19 Oct 2015 at about 1418hrs, I was driving (YM4716C) along west coast highway on lane 3 when I met with an accident. I was driving when suddenly the vehicle in front of me (BJN880) pressed the brake. I tried to avoid it by pressing my brake but could not sop in time. I then tried to turn right going to lane 2 to avoid a collision but could not make it. My front left had hit onto his rear right.

After the accident, both of the vehicle remained on the spot. A passerby had called for police and soon traffic police came. The traffic police gave me a case card and ask me to lodge a police report.

I am unhurt and not injured. The other driver also is unhurt. My lorry had to be towed away but the other vehicle drove away. Damage done to my vehicle is dents and scratches in my front left side. The other vehicle also suffered scratches and dents on the rear right.

Certified True Copy pursuant to Sec. 78 of the Evidence Act, Cap 97.

Yet Hwee Choo CSO Traffic Police Date: Police Station Of Origin:

Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 51945 Tel No: 1800-5852999



3 of 3

Report No. T/20151019/2178

Yet Hwee Choo

CSO Traffic Police Date: 19 SEP 2016

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Mohamed Hazwan Bin Mohamed Yasin	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 19/10/2015 22:01
Officer In Charge Of Case: TP / GIT / MD ABDILLAH BIN PALIL Contact No.: 65476246	Classification Of Case: Certified True Copy pursuant to Sec. 78 of the Evidence Act Cap 97.
Authentication Stamp	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aloresalu.	
	ACCIDENT STATEMENT
Date Of Report	19/10/2015 17:58
Date Of Accident	19/10/2015 14:25
Exact Location Of Accident	ALONG WEST COAST PARK TO JURONG BEFORE CLEMENTI RD
Country/State of Loss	Singapore
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	YM4716C
Insured/Policyholder	
Name Of Registered Owner	STVE PTE LTD
Co Reg No	198703585C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90252126
Alternative Phone No	Office-90252126
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FUSO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Reporting Only
Vehicle Category	Commercial Vehicle
Insurance Company	
Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12O39930MFCV
Cover Note Number	NA
Driver	
Name of Driver	YIP SOON FATT
NRIC No	S1803294E
Date Of Birth	18/11/1967
Occupation	Outdoor
Date Of Driving Pass	30/06/1989
Driving Experience	26 Years And 3 Months
Gender	Male
Mobile Number	(Local) +65-90252126
Fax Number	(Local) +65-90252126
Contact Number	

NOEMAIL

Address NA NA Postcode NA Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

vn

Insurance Company of Driver's Own Vehicle

-

Other - HIRER

General Information of the Accident

Type Of Accident

Collision- Head to Side

Weather Conditions

Clear Dry

Other Information

Road Surface

Was any foreign vehicle involved in this accident?

Yes

Foreign Vehicle Registration Number

TWC1761A (Commercial Vehicle)

Was any body injured in the Accident?
Was any other material or property damaged?

Yes

Was there any video captured by Car Camera?

No

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

Yes

If Yes, Please state which Police Station

Police Station Name [Other]

HAD ADVISE TO FILE REPORT

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

I was travelling ALONG WEST COAST PARK TOWARD JURONG BEFORE CLEMENTI RD, there was 3 lane and I was on the third lane, I didn't see the front truck was stationary hazard light suddenly I swerved into the second lane, thus I hit the rear right portion on the other party vehicle.

Are accident photos available for attachment?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

TWC1761A SCANIA / TRELER

Details Of Properties

NIA

Name of Driver

AZHAR BIN ABDUL RAHMAN

NRIC/Passport Number

820120016933

Contact Number

0177745443

Address

NA

D . . .

NA

Postcode

NA

Insurance Company Name

NA

No. Of Passenger (Including Driver)

1

Details of Witness

Nature Of Damage

Name

NA

Phone Number

NA

Email Address

NA

SKEI VO FLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5 Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association. of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
- (ii) investigating the accident and/or my claims,
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' taw yers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes

Driver's Signature (# driver is not the policyholder) / Date Policyholder's Signature / Date & & Time

VERIFIED BY MARS OFFICER MUSTAOIM S8437701E

Witnessed by Reporting Centre Personnel

Sketch Plan

Time

Sketch Plan #2 Pg.1

ACCIDENT STATEMENT (2000 characters)

CLEMENTI RD, there was 3 lane an	ST PARK TOWARD JURONG BEFORE and I was on the third lane, I didn't see the front truck at I swerved into the second lane, thus I hit the rear ale.
Taxi Voucher No.:	
Are you claiming your own insurance policy for the repair of your vehicle?	No, Reporting only
DECLARATION	
I/We declare that the above particulars & information provided by MARS OFFICER - MUSTAQIM, S8437701E	rovided above are true in every aspect
MARS Officer	Registered Owner or Driver's Signature
lob Complete Date/Time	Date/Time:
19 October 2015 3:50 pm	19 October 2015 3:50 pm

Accident Photo



Accident Photo




Accident Photo

















Accident Photo






Accident Photo







Accident Photo









Driving License

