

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21009848/KPA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : XE6616Z **Insured Vehicle No :** GBH1716X

Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: MFL2021D0003805

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE6616Z**

Make & Model: MITSUBISHI FUSO, 10.7 D FV70HJA00064 (M) Engine No: 470912C0621067

Reg. Date: 03/08/2021 (Man. Year: 2021) Chassis No: FV70HJA10104

Colour: White/Blue Odometer: 3495 km

Engine Capacity: 10677 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Firenza 9 mm Rear Left Side: Firenza 9/9/9 mm

Front Right Side: Firenza 9 mm Rear Right Side: Firenza 9/9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,398.98	8,249.19	47,149.79	85.11
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	530.00	290.00	35.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	56,229.98	8,790.19	47,439.79	84.37
+ GST 7.00/7.00% (S\$)	3,936.10	615.31	3,320.79	84.37
Nett Amount (S\$)	60,166.08	9,405.50	50,760.58	84.37
+ Loss of Use (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,012.95		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment: 21/09/2021 Present Location: City Auto Pte Ltd (HQ)

Date Inspected: 22/09/2021 Inspected At: City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01., Sin Ming AutoCity,
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2022)	
Parts:	N/A	MITSUBISHI FUSO 10.7 D FV70HJA00064 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE6616Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DPD Assy	Serviceable	51,849.49 FL	*- FN
2	1		*Mud guard RH front	Bent	456.61 FL	*456.61 FN
3	1		*Inforcement	Bent	200.00 FL	*200.00 FN
4	1		*Exhaust muffler heatshield - MX926260	Dented	307.15 FL	*307.15 FN
5	1		*Exhaust muffler heatshield - MX917050	Dented	387.68 FL	*387.68 FN
6	1		*Exhaust temperature sensor	Shorted	662.46 FL	*662.46 FN
7	1		*Exhaust muffler NOX sensor - MX916501	Shorted	2,509.27 FL	*2,509.27 FN
8	1		*Exhaust muffler NOX sensor - MX917068	Shorted	2,509.10 FL	*2,509.10 FN
9	1		*ATS exhaust muffler harness	Torn	2,672.66 FL	*2,672.66 FN
					Sub Total (\$\$)	61,554.42
					- List Item Discount on L Items 10.00/0.00% (\$\$)	6,155.44
					- Nett Item Discount on N Items 0.00/15.00% (\$\$)	0.00
					Total Parts (\$\$)	55,398.98
						9,704.93
						8,249.19

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Labour to remove and realign side reinforcement	New	250.00	180.00
2	To replace DPF assy and reprogramme	New	450.00	250.00
3	To respray reinforcement	New	120.00	100.00
Gross Labour Cost (\$\$)			820.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >