

ASS REC BY: *marcus*

REF:

CCG/CT121009849/4053

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res: Yes or No

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S / Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal:

L/Bal:

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 9500

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) _ \$ + RS _ \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

4/10/21 1/5 @ 7200 Confirmed with Susan

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7523L210914

Estimate**Customer**

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower Singapore 079909

Date: 20-09-21

Vehicle No: GBE7523L

Model/Make: Toyota Hiace

Van Turbo 5 DR

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>3065.00</i>	\$ 1,956.20	
2	Tailgate Lock <i>7w/17m 359.00</i>	\$ 394.90	
3	Tailgate Rubber <i>7w/1 386.24</i>	\$ 455.00	
4	Tailgate <i>inner trim 11</i>	\$ 195.80	X
5	Tailgate Inner Trim Board Clips 1 set <i>11</i>	\$ 50.00	SN X
6	Tailgate Windscreen Moulding <i>NS</i>	\$ 219.00	X
7	Tailgate Windscreen Sealant <i>neu</i>	\$ 50.00	SN 40 s/n
8	Tailgate "Toyota Logo" Motif <i>neu 68.50</i>	\$ 167.00	
9	Tailgate "HIACE" Emblem <i>neu 50.00</i>	\$ 105.00	
10	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 15.00	SN 10 s/n
11	Tailgate "8 PAX" Sticker <i>neu</i>	\$ 15.00	SN 10 s/n
12	Tail Lamp 02 pcs (@ \$5365.10) <i>CNA</i>	\$ 730.20	
13	Tail Lamp Panel Lh <i>5.65.00 325.30</i>	\$ 435.20	
14	Corner Panel <i>lower LH 0.5</i>	\$ 376.50	
15	Corner Panel Bracket Lh <i>neu</i>	\$ 31.50	
16	Fender (Body Panel) Lh <i>3065.00/3uc</i>	\$ 1,308.10	
17	End Panel Outer <i>3065.00</i>	\$ 566.10	
18	End Panel Inner <i>3065.00 648.10</i>	\$ 936.20	
19	End Panel Sealant <i>neu</i>	\$ 50.00	SN s/n
20	Floor Panel Beam <i>cut</i>	\$ 189.00	
21	Floor Board (Plywood) <i>neu</i>	\$ 380.00	SN 280 s/n
22	Bumper <i>0.5 560.01</i>	\$ 599.50	
23	Bumper Clips 1 set <i>neu</i>	\$ 48.00	
24	<i>1 set</i> Bumper Reverse Sensor <i>showd</i>	\$ 220.00	SN 200 s/n
25	Bumper Bracket 02 pcs (@ \$578.10) <i>11</i>	\$ 156.20	X
26	<i>1 set</i> "Corporate" Advertisement & Artwork Sticker <i>neu</i>	\$ 300.00	SN 150 s/n
	To check all wiring & electrical component for proper function	\$ 50.00	30
	Remove and refix rear Bumper distance sensor	\$ 90.00	50
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 120.00	100
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	1500
	To putty & spray painting & including touch up paint on accident affected	\$ 1,200.00	800
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 5,236.90

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

M/s Liu's Bro Auto Engrg Wks

P-760472
282
570428

S.N-740
L-2620
806428