

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009850/BQCQ2**Date:** 14/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00037262102		
Claimant Vehicle No :	SGA6787K	Insured Vehicle No :	YJ9044R		
Date of Loss:	18/09/2021	Nature of Claim:	TP	Claim No:	SNM21D205305/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGA6787K		
Make & Model:	HONDA ODYSSEY, 2.4 EX-S (A)	Engine No:	K24W72460177
Reg. Date:	15/03/2019 (Man. Year: 2018)	Chassis No:	JHMRC1880KC200283
Colour:	Red	Odometer:	77198 km
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,288.60	2,838.24	3,450.36	54.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,360.00	1,590.00	53.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,238.60	4,198.24	5,040.36	54.56
Approved Total (Overridden) (\$\$)		3,350.00		
(\$\$)	9,238.60	3,350.00	5,888.60	63.74
+ GST 7.00/7.00% (\$\$)	646.70	234.50	412.20	63.74
Nett Amount (\$\$)	9,885.30	3,584.50	6,300.80	63.74

INSPECTION

Date of Assignment:	09/11/2021		
Date Inspected:	21/09/2021	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	7.0 days		

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2022)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 EX-S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGA6787K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	583.10 FL	*583.10 FL
2	1		*REAR BUMPER LH REVERSE SENSOR	Dislodged	267.80 FL	*200.00 FL
3	1		*REAR BUMPER LH CHROME MOULDING	Cut	187.00 FL	*187.00 FL
4	1		*REAR BUMPER LH REFLECTOR	Not Damaged	46.80 FL	*- FL
5	1		*REAR BUMPER LH SIDE RETAINER	Necessary	22.20 FL	*22.20 FL
6	1		*REAR BUMPER RH SIDE RETAINER	Necessary	22.20 FL	*22.20 FL
7	1		*REAR LH FENDER	Dented	1,060.70 FL	*1,060.70 FL
8	1		*REAR LH FENDER GLASS RUBBER SEAL	Necessary	19.80 FL	*19.80 FL
9	1		*REAR LH FENDER SPLASH SHIELD	Not Damaged	83.00 FL	*- FL
10	1		*REAR LH FENDER OUTER CHROME MOULDING	Not Damaged	213.00 FL	*- FL
11	1		*REAR LH FENDER INNER TRIM BOARD	Not Damaged	423.80 FL	*- FL
12	1		*LH TAILLAMP ASSY	Broken	893.50 FL	*857.40 FL
13	1		*LH TAILLAMP LOWER CORNER COVER	Cut	95.40 FL	*95.40 FL
14	1		*REAR LH SPORT RIM (ORIGINAL)	Cut	783.50 FL	*400.00 FL
15	1		*REAR LH LOWER ARM	Not Damaged	405.30 FL	*- FL
16	1		*REAR LH WHEEL BEARING	Not Damaged	271.80 FL	*- FL
17	1		*REAR LH UPPER ARM	Not Damaged	185.40 FL	*- FL
18	1		*REAR LH CONTROL ARM	Not Damaged	326.00 FL	*- FL
19	1		*REAR LH SHOCK ABSORBER	Not Damaged	284.80 FL	*- FL
20	1		*REAR LH TRAILING ARM	Not Damaged	311.70 FL	*- FL
21	1		*REAR LH KNUCKLE ARM	Not Damaged	455.20 FL	*- FL
22	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
23	1		*REAR LH FENDER GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
24	1		*REAR LH FENDER GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
25	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS
26	1		*REAR LH FENDER JOINT SEALANT	Not Necessary	70.00 FS	*- FS
27	1		*REAR LH TYRE	Not Damaged	350.00 FS	*- FS
28	1		*BRAKE FLUID	Not Damaged	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,677.00	3,527.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,388.40	689.56
Total Parts (\$\$)	6,288.60	2,838.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	500.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
5	REMOVE AND REPLACE REAR LH FENDER INNER TRIMS, GARNISH ,BOARDS SEATS AND ROOF LINING TO ASSIST REPAIR	New	300.00	0.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
7	REMOVE AND REPLACE REAR LH UNDERCARRIAGE TO ASSIST REPAIRS	New	280.00	0.00
8	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			2,950.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >