

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009851/BVCE2

Date: 04/03/2022

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00176732003

Claimant Vehicle  
No : SLT3810L

Insured  
Vehicle No : SJC7227H

Date of Loss: 18/09/2021

Nature of Claim: TP

Claim  
No: SNM21D205302/C02/TANKW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT3810L

Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)

Engine No: HIDDEN

Reg. Date: 26/10/2017 (Man. Year: 2017)

Chassis No: WAUZZZGA4HA060138

Colour: Yellow

Odometer: 67030 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's       | Difference       | Diff %       |
|------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                    | 53,787.23        | 27,657.86        | 26,129.37        | 48.58        |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00             |              |
| Labour                                   | 7,100.00         | 2,820.00         | 4,280.00         | 60.28        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00             |              |
| Towing                                   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>60,887.23</b> | <b>30,477.86</b> | <b>30,409.37</b> | <b>49.94</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>21,000.00</b> |                  |              |
| <b>(S\$)</b>                             | 60,887.23        | 21,000.00        | 39,887.23        | 65.51        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 4,262.11         | 1,470.00         | 2,792.11         | 65.51        |
| <b>Nett Amount (S\$)</b>                 | <b>65,149.34</b> | <b>22,470.00</b> | <b>42,679.34</b> | <b>65.51</b> |

### INSPECTION

Date of Assignment: 28/09/2021

Date Inspected: 23/09/2021 Inspected At:

Bifrost Auto Pte Ltd  
8 Kaki Bukit Avenue 4 #01-49 Premier @ Kaki  
Bukit  
Singapore 415875

Estimated Period of Repair: 18.0 days

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                       |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 03 Mar 2022)                                                                                                                                             |                                                                       |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | AUDI Q2 999cc 1.0 TFSI S TRONIC (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLT3810L)                                                                                                                                    |                                                                       |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                       |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                       |

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BONNET                                 | Dented        | 2,789.00 FL | *2,205.60 FL |
| 2   | 1   |          | *BONNET RH HINGE                        | Bent          | 61.10 FL    | *61.10 FL    |
| 3   | 1   |          | *BONNET LH HINGE                        | Bent          | 61.10 FL    | *61.10 FL    |
| 4   | 1   |          | *BONNET LOCK                            | Jammed        | 57.70 FL    | *57.70 FL    |
| 5   | 1   |          | *BONNET RH LOCK CABLE                   | Jammed        | 57.50 FL    | *57.50 FL    |
| 6   | 1   |          | *BONNET LH LOCK CABLE                   | Jammed        | 73.30 FL    | *73.30 FL    |
| 7   | 1   |          | *BONNET INSULATOR                       | Not Damaged   | 219.00 FL   | *- FL        |
| 8   | 1   |          | *BONNET RH RUBBER SEAL                  | Necessary     | 29.50 FL    | *29.50 FL    |
| 9   | 1   |          | *BONNET CENTRE RUBBER SEAL              | Necessary     | 34.50 FL    | *34.50 FL    |
| 10  | 1   |          | *BONNET LH RUBBER SEAL                  | Necessary     | 29.50 FL    | *29.50 FL    |
| 11  | 1   |          | *BONNET ABSORBER STAY                   | Not Damaged   | 213.50 FL   | *- FL        |
| 12  | 1   |          | *BONNET ABSORBER STAY BRACKET           | Not Damaged   | 34.80 FL    | *- FL        |
| 13  | 1   |          | *FRONT GRILLE                           | Broken        | 1,411.00 FL | *1,077.95 FL |
| 14  | 1   |          | *FRONT GRILLE CHROME MOULDING           | Broken        | 196.50 FL   | *196.50 FL   |
| 15  | 1   |          | *FRONT GRILLE LOWER GARNISH MESH        | Broken        | 298.50 FL   | *298.50 FL   |
| 16  | 1   |          | *FRONT NUMBER PLATE HOLDER              | Broken        | 78.40 FL    | *46.56 FL    |
| 17  | 1   |          | *FRONT BUMPER LOWER SPOILER             | Missing       | 298.50 FL   | *249.00 FL   |
| 18  | 1   |          | *FRONT BUMPER LOWER COVER               | Broken        | 155.80 FL   | *51.00 FL    |
| 19  | 1   |          | *FRONT RH BUMPER                        | Broken        | 893.50 FL   | *893.50 FL   |
| 20  | 1   |          | *FRONT RH BUMPER RETAINER               | Necessary     | 35.40 FL    | *35.40 FL    |
| 21  | 1   |          | *FRONT RH BUMPER AIR GRILLE             | Broken        | 169.00 FL   | *108.00 FL   |
| 22  | 1   |          | *FRONT RH BUMPER AIR GRILLE INNER COVER | Necessary     | 58.40 FL    | *58.40 FL    |
| 23  | 1   |          | *FRONT RH BUMPER PARKING SENSOR         | Short Circuit | 285.00 FL   | *150.00 FL   |
| 24  | 1   |          | *FRONT CENTRE COVER                     | Broken        | 147.50 FL   | *147.50 FL   |
| 25  | 1   |          | *FRONT LH BUMPER                        | Broken        | 893.50 FL   | *893.50 FL   |
| 26  | 1   |          | *FRONT LH BUMPER TOWING COVER           | No such part  | 38.60 FL    | *- FL        |
| 27  | 1   |          | *FRONT LH BUMPER RETAINER               | Necessary     | 35.40 FL    | *35.40 FL    |
| 28  | 1   |          | *FRONT LH BUMPER AIR GRILLE             | Broken        | 169.00 FL   | *108.00 FL   |
| 29  | 1   |          | *FRONT LH BUMPER AIR GRILLE INNER COVER | Necessary     | 58.40 FL    | *58.40 FL    |
| 30  | 1   |          | *FRONT LH BUMPER PARKING SENSOR         | Short Circuit | 285.00 FL   | *150.00 FL   |
| 31  | 1   |          | *FRONT BUMPER REINFORCEMENT             | Dented        | 723.00 FL   | *578.40 FL   |
| 32  | 1   |          | *FRONT BUMPER INNER SPONGE              | No such part  | 77.40 FL    | *- FL        |
| 33  | 1   |          | *RH HEADLAMP                            | Broken        | 4,915.00 FL | *3,320.00 FL |
| 34  | 1   |          | *RH HEADLAMP BRACKET                    | Broken        | 118.00 FL   | *43.00 FL    |
| 35  | 1   |          | *RH HEADLAMP WASHER COVER               | Not Damaged   | 57.20 FL    | *- FL        |
| 36  | 1   |          | *RH HEADLAMP WASHER NOZZLE              | Broken        | 142.00 FL   | *142.00 FL   |
| 37  | 1   |          | *LH HEADLAMP                            | Broken        | 4,915.00 FL | *3,320.00 FL |
| 38  | 1   |          | *LH HEADLAMP BRACKET                    | Broken        | 118.00 FL   | *43.00 FL    |
| 39  | 1   |          | *LH HEADLAMP WASHER COVER               | Not Damaged   | 57.20 FL    | *- FL        |
| 40  | 1   |          | *LH HEADLAMP WASHER NOZZLE              | Broken        | 142.00 FL   | *142.00 FL   |
| 41  | 1   |          | *RADIATOR ASSY (NO:1)                   | Dented        | 858.50 FL   | *772.80 FL   |
| 42  | 1   |          | *RADIATOR ASSY (NO:2)                   | Dented        | 879.50 FL   | *772.80 FL   |
| 43  | 1   |          | *RADIATOR FAN ASSY                      | Broken        | 1,265.00 FL | *1,199.00 FL |
| 44  | 1   |          | *AIRCON CONDENSER                       | Dented        | 950.50 FL   | *677.00 FL   |
| 45  | 1   |          | *SUPPORT PANEL                          | Bent          | 994.00 FL   | *994.00 FL   |
| 46  | 1   |          | *FRONT RH FENDER                        | Dented        | 1,147.00 FL | *917.60 FL   |

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|---------------|-------------|--------------|
| 47  | 1   |          | *FRONT RH FENDER SPLASH SHIELD           | Not Damaged   | 195.00 FL   | *- FL        |
| 48  | 1   |          | *FRONT RH FENDER ARCH MOULDING           | Broken        | 321.50 FL   | *210.00 FL   |
| 49  | 1   |          | *FRONT LH FENDER                         | Not Damaged   | 1,147.00 FL | *- FL        |
| 50  | 1   |          | *FRONT LH FENDER SPLASH SHIELD           | Not Damaged   | 195.00 FL   | *- FL        |
| 51  | 1   |          | *FRONT LH FENDER ARCH MOULDING           | Broken        | 321.50 FL   | *210.00 FL   |
| 52  | 1   |          | *WASHER TANK                             | Not Damaged   | 176.00 FL   | *- FL        |
| 53  | 1   |          | *WASHER TANK MOTOR                       | Not Damaged   | 124.50 FL   | *- FL        |
| 54  | 1   |          | *FRONT RH LOW TONE HORN                  | Short Circuit | 186.00 FL   | *100.00 FL   |
| 55  | 1   |          | *FRONT RH HIGH TONE HORN                 | Short Circuit | 186.00 FL   | *100.00 FL   |
| 56  | 1   |          | *FRONT NUMBER PLATE                      | Missing       | 70.00 FS    | *30.00 FS    |
| 57  | 1   |          | *SET BONNET INSULATOR CLIPS              | Not Necessary | 80.00 FS    | *- FS        |
| 58  | 1   |          | *SET FRONT BUMPER CLIPS                  | Necessary     | 70.00 FS    | *30.00 FS    |
| 59  | 1   |          | *RADIATOR COOLANT                        | Necessary     | 120.00 FS   | *40.00 FS    |
| 60  | 1   |          | *FRONT NUMBER PLATE                      | Repeated      | 70.00 FS    | *- FS        |
| 61  | 1   |          | *SET FRONT RH FENDER ARCH MOULDING CLIPS | Necessary     | 60.00 FS    | *30.00 FS    |
| 62  | 1   |          | *ENGINE OIL SUMP                         | Broken        | 1,353.00 FL | *1,353.00 FL |
| 63  | 1   |          | *ENGINE OIL SUMP GASKET                  | Necessary     | 137.00 FL   | *63.00 FL    |
| 64  | 1   |          | *FRONT CROSSMEMBER                       | Bent          | 1,378.00 FL | *1,378.00 FL |
| 65  | 1   |          | *FRONT RH LOWER ARM                      | Repeated      | 414.00 FL   | *- FL        |
| 66  | 1   |          | *FRONT RH SHOCK ABSORBER                 | Not Necessary | 455.80 FL   | *- FL        |
| 67  | 1   |          | *FRONT RH KNUCKLE ARM                    | Not Necessary | 708.00 FL   | *- FL        |
| 68  | 1   |          | *FRONT RH WHEEL BEARING                  | Not Necessary | 530.00 FL   | *- FL        |
| 69  | 1   |          | *FRONT RH LOWER ARM                      | Not Damaged   | 414.00 FL   | *- FL        |
| 70  | 1   |          | *FRONT RH SHOCK ABSORBER                 | Repeated      | 455.80 FL   | *- FL        |
| 71  | 1   |          | *FRONT RH KNUCKLE ARM                    | Repeated      | 708.00 FL   | *- FL        |
| 72  | 1   |          | *FRONT RH WHEEL BEARING                  | Repeated      | 530.00 FL   | *- FL        |
| 73  | 1   |          | *STEERING RACK AND PINION                | Not Damaged   | 4,546.00 FL | *- FL        |
| 74  | 1   |          | *FRONT RH DRIVE SHAFT                    | Not Damaged   | 2,211.00 FL | *- FL        |
| 75  | 1   |          | *FRONT LH DRIVE SHAFT                    | Not Damaged   | 2,085.00 FL | *- FL        |
| 76  | 1   |          | *TUNNEL CENTRE ENFORCEMENT               | Broken        | 203.00 FL   | *203.00 FL   |
| 77  | 1   |          | *FUEL TANK                               | Not Damaged   | 1,852.00 FL | *- FL        |
| 78  | 1   |          | *REAR AXLE BEAM                          | Bent          | 2,741.00 FL | *1,694.00 FL |
| 79  | 1   |          | *REAR RH SHOCK ABSORBER                  | Not Damaged   | 305.00 FL   | *- FL        |
| 80  | 1   |          | *REAR LH SHOCK ABSORBER                  | Not Damaged   | 305.00 FL   | *- FL        |
| 81  | 1   |          | *REAR RH WHEEL BEARING                   | Not Damaged   | 566.00 FL   | *- FL        |
| 82  | 1   |          | *REAR LH WHEEL BEARING                   | Not Damaged   | 566.00 FL   | *- FL        |
| 83  | 1   |          | *EXHAUST SILENCER                        | Dented        | 1,459.00 FL | *1,254.00 FL |
| 84  | 1   |          | *EXHAUST SILENCER HEAT SHIELD            | Distorted     | 251.00 FL   | *251.00 FL   |
| 85  | 1   |          | *EXHAUST CENTRE PIPE                     | Dented        | 1,673.00 FL | *1,673.00 FL |
| 86  | 1   |          | *EXHAUST CENTRE PIPE HEAT SHIELD         | Distorted     | 355.00 FL   | *225.00 FL   |
| 87  | 1   |          | *ENGINE OIL SUMP GASKET SEALANT          | Repeated      | 150.00 FS   | *- FS        |
| 88  | 5   |          | *LITRE ENGINE OIL                        | Necessary     | 180.00 FS   | *80.00 FS    |
| 89  | 1   |          | *ENGINE OIL FILTER                       | Dented        | 55.00 FS    | *55.00 FS    |
| 90  | 1   |          | *BRAKE FLUID                             | Not Necessary | 70.00 FS    | *- FS        |
| 91  | 1   |          | *SET FRONT LH FENDER ARCH MOULDING CLIPS | Necessary     | 60.00 FS    | *30.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                  |
|----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                  | <b>56,566.30</b> | <b>29,098.01</b> |
| <b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b> | 2,779.07         | 1,440.15         |
| <b>Total Parts (\$\$)</b>                                | <b>53,787.23</b> | <b>27,657.86</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                             | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                         |          |                 |                 |
| 1                              | LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS | New      | 1,800.00        | 800.00          |
| 2                              | SPRAY PAINTING ON AFFECTED PANELS                                                                                                       | New      | 1,500.00        | 800.00          |
| 3                              | CHECK WIRING AND LIGHTING SYSTEM                                                                                                        | New      | 150.00          | 50.00           |
| 4                              | APPLY RUST COATING CHEMICAL ON AFFECTED PANELS                                                                                          | New      | 100.00          | 0.00            |
| 5                              | MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH TO STRAIGHTEN AND REPAIR BOTH FRONT CHASSIS MEMBERS                                            | New      | 600.00          | 0.00            |
| 6                              | REMOVE AND REPLACE AIRCON CONDENSER, PIPES AND HOSES TO ASSIST REPAIR. TO REFILL AIRCON GAS                                             | New      | 220.00          | 0.00            |
| 7                              | REMOVE AND REPLACE RADIATORS ASSY, HOSES, PIPES AND FAN ASSY TO ASSIST REPAIR. TO REFILL COOLANT                                        | New      | 280.00          | 120.00          |
| 8                              | REMOVE AND REINSTALL ENGINE WITH GEARBOX ASSY TO ASSIST REPAIR                                                                          | New      | 500.00          | 0.00            |
| 9                              | RESET AND DIAGNOSE ELECTRONIC CONTROL UNIT AFTER REPAIRS                                                                                | New      | 320.00          | 250.00          |
| 10                             | REMOVE AND REPLACE ENGINE OIL SUMP AND CHECK FOR LEAKAGE                                                                                | New      | 280.00          | 80.00           |
| 11                             | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS                                                                                            | New      | 550.00          | 300.00          |
| 12                             | REMOVE AND REPLACE FUEL TANK, PIPES AND SENSOR TO ASSIST REPAIR                                                                         | New      | 120.00          | 60.00           |
| 13                             | REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS                                                                                             | New      | 480.00          | 280.00          |
| 14                             | REMOVE AND REPLACE EXHAUST SILENCER AND HEAT SHIELD TO ASSIST REPAIR                                                                    | New      | 200.00          | 80.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                         |          | <b>7,100.00</b> | <b>2,820.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >