

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009853/KTCN2**Date:** 23/11/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00002632101

**Claimant Vehicle
No :** SMQ3323E**Insured Vehicle
No :** SLH5531S

Date of Loss: 11/09/2021

Nature of Claim: TP

Claim
No: SNM21D205145/C03/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMQ3323E**

Make & Model: MERCEDES-BENZ C200 AMG LINE, 2.0 (A)

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: WDD2050422R307359

Colour: Metallic Grey

Odometer: 36205 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,145.00	8,007.19	9,137.81	53.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	1,740.00	3,010.00	63.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,895.00	9,747.19	12,147.81	55.48
+ GST 7.00/7.00% (S\$)	1,532.65	682.30	850.35	55.48
Nett Amount (S\$)	23,427.65	10,429.49	12,998.16	55.48

INSPECTION

Date of Assignment: 10/11/2021

Date Inspected: 06/10/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Cartimes Autolution Pte Ltd
160 Sin Ming Drive #02-04 Autocity,
Singapore 575722**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)

Parts: 143 MERCEDES-BENZ C200 AMG LINE 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ3323E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	2,340.00 FL	*1,831.00 FL
2	1		*REAR BUMPER RETAINER LHS	Serviceable	60.00 FL	*- FL
3	1		*REAR BUMPER RETAINER RHS	Serviceable	60.00 FL	*- FL
4	1		*REAR BUMPER LOWER	Cracked	330.00 FL	*330.00 FL
5	1		*REAR BUMPER DIFFUSER	Cracked	260.00 FL	*260.00 FL
6	1		*EXHAUST TIP LHS	Serviceable	540.00 FL	*- FL
7	1		*EXHAUST TIP RHS	Serviceable	540.00 FL	*- FL
8	1		*TAIL LAMP LHS	Cracked	630.00 FL	*630.00 FL
9	1		*TAIL LAMP RHS	Serviceable	630.00 FL	*- FL
10	1		*REAR BOOT	Bent	1,980.00 FL	*1,980.00 FL
11	1		*REAR BOOT HINGE LHS	Repair	310.00 FL	*- FL
12	1		*REAR BOOT HINGE RHS	Repair	310.00 FL	*- FL
13	1		*REAR BOOT CENTRE GARNISH (CHROME)	Warped	230.00 FL	*230.00 FL
14	1		*REAR BOOT LOCK ASSY	Dented	940.00 FL	*349.00 FL
15	1		*REAR BOOT INNER TRIM	Serviceable	270.00 FL	*- FL
16	1		*MERCEDES EMBLEM	Necessary	60.00 FL	*60.00 FL
17	1		*C200 EMBLEM	Necessary	110.00 FL	*68.00 FL
18	1		*REAR REINFORCEMENT	Bent	560.00 FL	*560.00 FL
19	1		*END PANEL	Bent	1,260.00 FL	*1,260.00 FL
20	1		*END PANEL TOP GARNISH	Distorted	130.00 FL	*130.00 FL
21	1		*SPARE TYRE PANEL	Cracked	550.00 FL	*550.00 FL
22	1		*AUTO TAILGATE	Serviceable	880.00 FL	*- FL
23	1		*REAR FENDER LHS	Repair	2,430.00 FL	*- FL
24	1		*REAR FENDER RHS	Repair	2,430.00 FL	*- FL
25	1		*REAR SENSORS	Shorted	200.00 FS	*200.00 FS
26	1		*CARPLATE W/HOLDER	Dented	60.00 FS	*45.00 FS
27	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
28	1		*REAR BOOT WEATHERSTRIP	Dented/Distorted	350.00 FL	*281.10 FL
29	20		*RIVETS	Necessary	50.00 FL	*50.00 FL
30	1		*SPARE TYRE TOP COVER	Serviceable	410.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,010.00	8,864.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,865.00	856.91
Total Parts (\$\$)	17,145.00	8,007.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT SPARE TYRE PANEL COMPONENTS	New	300.00	0.00
2	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	2,000.00	700.00
3	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	2,000.00	900.00
4	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	100.00	20.00
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	60.00
6	DIAGNOSTIC CHECK	New	100.00	0.00
7	TRANSFER REAR BOOT PARTS	New	150.00	60.00
Gross Labour Cost (\$\$)			4,750.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >