

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009856/BTCN2**Date:** 14/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00098382100

Claimant Vehicle No : SLF9164C**Insured Vehicle No :** GBL587L

Date of Loss: 18/09/2021

Nature of Claim: TP

Claim No: SNM21D205303/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLF9164C**

Make & Model: HONDA CIVIC, 1.5 (A)

Engine No: L15B71624686

Reg. Date: 15/09/2016 (Man. Year: 2016)

Chassis No: MRHFC1660GT000009

Colour: Blue

Odometer: 85749 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size: 225/45R17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,118.08	2,584.40	1,533.68	37.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,260.00	990.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,368.08	3,844.40	2,523.68	39.63
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	6,368.08	3,050.00	3,318.08	52.10
+ GST 7.00/7.00% (S\$)	445.77	213.50	232.27	52.11
Nett Amount (S\$)	6,813.85	3,263.50	3,550.35	52.10

INSPECTION

Date of Assignment: 05/10/2021

Date Inspected: 21/09/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2021)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF9164C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY RR BUMPER	Dented	717.20 FL	*617.20 FL
2	1		*SPACERR.RR BUMPER SIDE	Necessary	31.50 FL	*31.50 FL
3	1		*SPACERL.RR BUMPER SIDE	Necessary	31.50 FL	*31.50 FL
4	1		*GARNISHRR.BUMPER LOWER	Broken	35.30 FL	*35.30 FL
5	1		*GARNISHL.RR BUMPER SIDE	No such part	17.60 FL	*- FL
6	1		*GARNISHR.RR BUMPER SIDE	No such part	17.60 FL	*- FL
7	1		*COVERR.FINISHER	Not Damaged	21.90 FL	*- FL
8	1		*COVERL.FINISHER	Broken	21.90 FL	*21.90 FL
9	1		*REFLECTOR ASSYR.RR	Not Damaged	17.00 FL	*- FL
10	1		*REFLECTOR ASSYL.RR	Broken	17.00 FL	*17.00 FL
11	1		*BEAM COMPRR.BUMPER	Bent	199.00 FL	*199.00 FL
12	1		*TAILLIGHT ASSYR	Broken	253.80 FL	*253.80 FL
13	1		*TAILLIGHT ASSYL	Broken	253.80 FL	*253.80 FL
14	1		*BRACKETR.RR BUMPER SIDE	Broken	12.20 FL	*12.20 FL
15	1		*BRACKETL.RR BUMPER SIDE	Broken	12.20 FL	*12.20 FL
16	1		*TAILLIGHT ASSYL	Repeated	373.10 FL	*- FL
17	1		*TAILLIGHT ASSYR	Repeated	373.10 FL	*- FL
18	1		*BRACKETL.RR BUMPER SIDE	Repeated	12.20 FL	*- FL
19	1		*BRACKETR.RR BUMPER SIDE	Repeated	12.20 FL	*- FL
20	1		*LID COMP TRUNK	Dented	572.10 FL	*572.10 FL
21	1		*HINGE COMPR.TRUNK	Not Damaged	43.50 FL	*- FL
22	1		*HINGE COMPL.TRUNK	Not Damaged	43.50 FL	*- FL
23	1		*EMBLEM	Necessary	23.50 FL	*23.50 FL
24	1		*EMBLEM SETRR	Necessary	11.50 FL	*11.50 FL
25	1		*PANEL SETRR	Dented	436.00 FL	*436.00 FL
26	1		*OUTLET ASSYRR,AIR	No such part	27.80 FL	*- FL
27	1		*STIFFENER.R.RR PANEL SIDE	Not Damaged	126.00 FL	*- FL
28	1		*STIFFENER.L.RR PANEL SIDE	Not Damaged	126.00 FL	*- FL
29	1		*ACT RR SENSOR (4 Pcs)	Short Circuit	320.00 FL	*200.00 FL
30	1		*PANEL SETL.RR TRIM	Broken	368.80 FL	*176.00 FL
31	1		*PANEL SETR.RR TRIM	Broken	368.80 FL	*176.00 FL
32	1		*REAR FENDER TRIM CLIPS	Necessary	100.00 FS	*60.00 FS
33	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
34	1		*BOOTLID INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,097.60	3,200.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	979.52	616.10
Total Parts (\$\$)	4,118.08	2,584.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	0.00
2	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
3	TO RESPRAY UNDERCOATING	New	80.00	0.00
4	TO RESPRAY PAINTING AND ETC	New	1,000.00	600.00
5	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,000.00	600.00
Gross Labour Cost (\$)			2,250.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >