

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21009870/VRS3Q2
Date: 17/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070172820
Claimant Vehicle No :	SLN1684D	Insured Vehicle No :	GBE5706P
Date of Loss:	15/09/2021	Nature of Claim:	TP
		Claim No:	3388534674SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1684D		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	L13B1323022
Reg. Date:	25/04/2017 (Man. Year: 2016)	Chassis No:	GK31220028
Colour:	Silver	Odometer:	77801 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,999.85	1,562.82	1,437.03	47.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	890.00	1,720.00	65.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,609.85	2,452.82	3,157.03	56.28
Approved Total (Overridden) (S\$)		1,950.00		

(S\$)	5,609.85	1,950.00	3,659.85	65.24
+ GST 7.00/7.00% (S\$)	392.69	136.50	256.19	65.24
Nett Amount (S\$)	6,002.54	2,086.50	3,916.04	65.24
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,493.95		

INSPECTION

Date of Assignment: 21/09/2021

Date Inspected: 22/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934

Adjuster: Thevan Thomas Karthikesavan**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR PANEL RH	Deformed	1,211.98 FL	*915.20 FL
2	1		*FRONT DOOR HANDLE RH	Scratched	441.20 FL	*285.20 FL
3	1		*FRONT DOOR WEATHERSTRIP	Cut	102.30 FL	*102.30 FL
4	1		*FRONT DOOR TAPE	Necessary	51.80 FL	*51.80 FL
5	1		*REAR DOOR PANEL RH	Repair	1,011.80 FL	*- FL
6	1		*RH WING MIRROR ASSY	Broken	851.20 FL	*519.50 FL
7	1		*RH WING MIRROR COVER	Broken	79.53 FL	*79.53 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	3,749.811,953.53
					- List Item Discount on L Items 20.00/20.00% (\$\$)	749.96390.71
					Total Parts (\$\$)	2,999.851,562.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING SYSTEM	New	60.00	20.00
2	REMOVE & REFIT FRONT DOOR MECHANISM & TRIMS	New	200.00	40.00
3	REMOVE & REFIT REAR DOOR MECHANISM & TRIMS	New	200.00	0.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	400.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	400.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (S\$)			2,610.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >