



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 3380S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RIGHT	BENT	537.50	537.50
1	FRONT FENDER GARISH	SERVICEABLE	102.00	-
1	FRONT BUMPER	MTG CRACKED / BUCKLED	638.00	638.00
1	FRONT BUMPER RETAINER RIGHT	DISTORTED	48.00	48.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	235.60	-
1	FRONT FOG LAMP RIGHT	SERVICEABLE	250.20	-
1	HEAD LAMP HID	CRACKED	1,505.60	1,505.60
1	HEAD LAMP BRACKET	DISTORTED	96.00	96.00
1	FRONT BONNET	TO REPAIR SEE LABOUR	590.20	-
1	FRONT BONNET RUBBER	SERVICEABLE	101.30	-
1	FRONT GRILLE	MTG CRACKED	151.90	151.90
	LESS 20% DISCOUNT		-	-595.40
			4,256.30	2,381.60
	<u>LABOUR</u>			
	RUSTPROOFING.		100.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT BONNET.		980.00	500.00
	SPRAY PAINTING.		880.00	600.00
			1,960.00	1,130.00
	GRAND TOTAL		6,216.30	3,511.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS/AGI21009873/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.