



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2200774
3 ANSON ROAD #16-00	INV Date	14/02/2022
SPRINGLEAF TOWER	Reference	CC6/CTI21009879/Aes3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SMY 4426T
Insured Veh.	GBG 1070E
Claim No.	SNM21D205331/C03
Policy No.	DMCVSNW00115542100
Accident Date	19/09/2021
Inspection Date	21/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21009879/Aes3q2 Date: 14/02/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 1070E	Veh. Inspected	SMY 4426T
Policy No.	DMCVSNW00115542100	Coverage (\$)	0.00
Claim No.	SNM21D205331/C03	Excess (\$)	0.00
Assign From		Assign Date	21/09/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GB71098773	Colour	BLUE
Odometer	38535 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	6 mm
L/H Front Tyre	185/65 R15	DUNLOP	6 mm
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/09/2021	Inspection Date	21/09/2021
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 4426T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,050.40	-
2	FRONT BUMPER SIDE RETAINER @\$58.40	NOT NECESSARY	116.80	-
2	FRONT FENDER @\$322.00	TO REPAIR SEE LABOUR	644.00	-
2	FRONT FENDER EMBLEM @\$55.90	NECESSARY	111.80	58.00
1	FRONT FENDER MIRROR COVER LH	MISSING	168.40	168.40
1	FRONT FENDER MIRROR ASSY LH	DAMAGED	684.20	684.20
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	742.00	-
2	FRONT DOOR HINGE @\$90.00	NOT NECESSARY	180.00	-
1	FRONT DOOR CHECKER	NOT NECESSARY	103.00	-
1	FRONT DOOR LOCK	NOT NECESSARY	290.00	-
2	FRONT DOOR STICKER @\$70.00	NOT NECESSARY	140.00	-
1	FRONT DOOR WEATHERSTRIP	NOT NECESSARY	190.00	-
1	POWER WINDOW REGULATOR	NOT NECESSARY	420.00	-
1	POWER WINDOW MOTOR	NOT NECESSARY	380.00	-
	LESS 20% DISCOUNT		-1,044.12	-182.12
			4,176.48	728.48
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET HEADLAMP CLIPS (SN)	NOT NECESSARY	20.00	-
1	FRONT QUARTER GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
			80.00	-
<u>LABOUR</u>				
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER ,FRONT BUMPER AND FRONT DOOR LH .		1,400.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	700.00
	TUFF COAT.		120.00	30.00
	WIRING CHECK .		90.00	30.00
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	50.00	-

Report Ref No. CC6/CTI21009879/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX FRONT QUARTER GLASS.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX FRONT DOOR .	NOT NECESSARY	60.00	-
			3,200.00	960.00
GRAND TOTAL			7,456.48	1,688.48
RECOMMENDED COST OF REPAIRS				1,688.48

Report Ref No. CC6/CTI21009879/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 4426T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 4426T

RE-INSPECTION

