

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21009880/GUF3N2**Date:** 29/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070108998
<b>Claimant Vehicle No :</b>	SLR8481E	<b>Insured Vehicle No :</b>	SMU7088L
Date of Loss:	18/09/2021	Nature of Claim:	TP
		Claim No:	2342047766SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLR8481E</b>		
Make & Model:	TOYOTA COROLLA FIELDER, 1.5 HYBRID (A)	Engine No:	1NZ7979270
Reg. Date:	29/08/2017 (Man. Year: 2016)	Chassis No:	NKE1658037804
Colour:	Black	Odometer:	77423 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Rotalla 6 mm	Rear Left Side:	Rotalla 6 mm
Front Right Side:	Rotalla 6 mm	Rear Right Side:	Rotalla 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	22/09/2021	
Date Inspected:	22/09/2021 Inspected At:	Derrick Motor Works (HQ) 9002 Tampines St. 93, #01-72 Tampines Industrial Park A Singapore 528836
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$65,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Buckled	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*TAILGATE	Repair	0.00 F	*- F
12	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
13	1		*TAILGATE LOCK	Bent	0.00 F	*- F
14	1		*TAILGATE RUBBER	Dented	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >