

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21009884/BUCE2

**Date:** 13/10/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00146282000  
**Claimant Vehicle No :** JTV7085 **Insured Vehicle No :** SMT2183H  
Date of Loss: 20/09/2021 Nature of Claim: TP Claim No: SNM21D205340/C2/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JTV7085**  
Make & Model: HONDA VARIO, 149cc Engine No: KF29E8053577  
Reg. Date: 17/01/2020 (Man. Year: 2019) Chassis No: PMKKF3770KB008242  
Colour: Black Odometer: 17775 km  
Engine Capacity: 149 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 90/80/14 Rear Tyre Size: 100/80/14  
Front Left Side: Vee Rubber 6 mm Rear Left Side: Vee Rubber 6 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,296.50	1,771.53	3,524.97	66.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	830.00	530.00	38.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,656.50</b>	<b>2,601.53</b>	<b>4,054.97</b>	<b>60.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>(S\$)</b>	6,656.50	2,050.00	4,606.50	69.20
<b>+ GST 7.00/7.00% (S\$)</b>	465.96	143.50	322.46	69.20
<b>Nett Amount (S\$)</b>	<b>7,122.46</b>	<b>2,193.50</b>	<b>4,928.96</b>	<b>69.20</b>

### INSPECTION

Date of Assignment: 07/10/2021  
Date Inspected: 23/09/2021 Inspected At: Ms Car Auto Pte Ltd (HQ)  
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT  
Singapore 415875  
Estimated Period of Repair: 4.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 Oct 2021)	
<b>Parts:</b>	N/A	HONDA VARIO 149cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for JTV7085)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR RH	Cut	122.50 FL	*122.50 FL
2	1		*FRONT SIGNAL	Cut	125.80 FL	*96.00 FL
3	1		*HANDLE BAR	Not Damaged	195.00 FL	*- FL
4	1		*SET HANDLE BAR BALANCER	Not Necessary	60.00 FL	*- FL
5	1		*SET HANDLE BAR GRIP	Not Necessary	90.00 FL	*- FL
6	1		*BRAKE LEVER	Cut	85.40 FL	*85.40 FL
7	1		*STEERING CONE BEARING	Not Damaged	67.40 FL	*- FL
8	1		*STEERING CONE	Not Damaged	231.40 FL	*- FL
9	1		*HEADLAMP ASSY	Cut	475.00 FL	*385.00 FL
10	1		*FRONT FENDER	Cut	162.70 FL	*162.70 FL
11	1		*HEADLAMP COWLING	Cut	215.00 FL	*215.00 FL
12	1		*FORK ASSY	Not Damaged	712.50 FL	*- FL
13	1		*FORK STEM	Not Damaged	87.40 FL	*- FL
14	1		*FRONT SIDE FAIRING RH	Cut	345.00 FL	*345.00 FL
15	1		*REAR SIDE FAIRING RH	Cut	212.50 FL	*95.00 FL
16	1		*REAR SIGNA RH	Cut	118.60 FL	*118.60 FL
17	1		*RIDER FOOT REST GARNISH RH	Dented	114.50 FL	*114.50 FL
18	1		*SIDE STAND	Not Damaged	160.00 FL	*- FL
19	1		*ENGINE COVER	Not Damaged	183.70 FL	*- FL
20	1		*AIR DUCT ASSY	Not Damaged	212.40 FL	*- FL
21	1		*REAR FORK	Not Damaged	348.60 FL	*- FL
22	1		*EXHAUST GUARD	Not Damaged	86.70 FL	*- FL
23	1		*EXHAUST GASKET	Not Damaged	115.70 FL	*- FL
24	1		*EXHAUST ASSY	Not Damaged	745.20 FL	*- FL
25	1		*REAR RIM	Cut	180.80 FS	*180.80 FS
26	1		*REAR TYPE	Not Damaged	95.00 FS	*- FS
27	1		*HELMET	Not Necessary	250.00 FS	*- FS
28	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,823.80</b>	<b>1,945.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	527.30	173.97
<b>Total Parts (\$\$)</b>	<b>5,296.50</b>	<b>1,771.53</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WORKMANSHIP	New	600.00	400.00
2	SPRAY PAINTING	New	600.00	400.00
3	TO CHECK CHASSIS ALIGNMENT	New	100.00	0.00
4	TO CHECK WHEEL ALIGNMENT	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,360.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >