

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

	MS FIRST CAPITA	AL INSURANCE LTD	F	Ref:	CS3/FCI21009885/Evf3e2	
	36 ROBINSON RO	Γ	Date:	28/09/2021		
	SINGAPORE 0688	377				
				Code:		
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBD 3998G	Veh. Inspected		SKN 70T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D21002665MFCV	Excess (\$)		0.00	
	Assign From	RACHELWU LIMEI	Assign Date		22/09/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	VOLVO V40	c.c		1498	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	YV1MV28H0J2446701	Colour		BLUE	
	Odometer	50868 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	PIRELLI		4 mm	
	L/H Front Tyre	205/55 R16	PIRELLI		4 mm	
	R/H Rear Tyre	205/55 R16	PIRELLI		4 mm	
	L/H Rear Tyre	205/55 R16	PIRELLI		4 mm	
4.	Description of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE FRONT O/S PORTION.				
5.	General Information					
	Accident Date	19/07/2021	Inspect Date / Ti	ime	24/09/2021 (12:15 PM)	
	Survey held at	7A JALAN PAPAN				
	Repairer	THIAM HENG AUTO (S) PTE LTD				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$90,000.00					

Report Ref No. CS3/FCI21009885/Evf3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser