

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21009887/R1VCE2
Date: 04/10/2021

REFERENCE

Insured/Claimant: HILTOP MACHINERY PTE LTD Policy No: DMCVSNW00114112000
Date of Loss: 13/09/2021 Nature of Claim: OD Claim No: SNM21D205217/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD98M	Engine No:	6WG1438712
Make & Model:	ISUZU CYZ52K, 15.7 D (M)	Chassis No:	JALCYZ52KK7000008
Reg. Date:	18/11/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	15681 cc		
Market Value/New Car Price:	S\$209,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	Double Coin 0 mm	Rear Left Side:	Double Coin 8/8 mm
Front Right Side:	Double Coin 0 mm	Rear Right Side:	Double Coin 8/8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	2,000.00	-2,000.00	
Nett Amount (S\$)	0.00	-2,000.00	2,000.00	

INSPECTION

Date of Assignment:	22/09/2021	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	22/09/2021	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	0.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$209,000.00
OMV :	\$122,317.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$26,644.00
COE Rebate (2) :	\$24,391.00
Total Rebate (1) + (2) = :	\$24,391.00

The total amount incurred will be Market Value \$209,000.00 minus Total Rebate \$24,391.00 = \$184,609.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Oct 2021)	
Parts:	N/A	ISUZU CYZ52K 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD98M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >