

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21009890/UPA3Q2
Date: 21/11/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100365839
Claimant Vehicle No :	SLS6193U	Insured Vehicle No :	SFU106Y
Date of Loss:	09/09/2021	Nature of Claim:	TP
		Claim No:	0031303599SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6193U	Engine No:	1KD2707102
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Chassis No:	KDH2230031936
Reg. Date:	28/09/2017 (Man. Year: 2017)	Odometer:	257393 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,625.30	2,170.15	3,455.15	61.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	870.00	700.00	44.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,195.30	3,040.15	4,155.15	57.75
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	7,195.30	2,400.00	4,795.30	66.64
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	22/09/2021	
Date Inspected:	22/09/2021 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Grazed	545.20 F	*545.20 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*REAR FENDER (N/S)	Repair	1,465.10 F	*- FL
4	1		*REAR WHEEL HUB CAP N/S	Grazed	165.00 F	*165.00 FL
5	1		*REAR FENDER WINDSCREEN GLASS SEALANT (N/S)	Not Necessary	100.00 FS	*- FS
6	1		*REAR FENDER CORPORATE ADVERTISEMENT & ARTWORK (N/S)	Necessary	2,800.00 FS	*1,200.00 FS
7	1		*REAR BUMPER CORPORATE ADVERTISEMENT & ARTWORK (N/S)	Necessary	500.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,625.30	2,360.20
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	190.05
Total Parts (\$)	5,625.30	2,170.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	30.00	20.00
2	TO REMOVE & REINSTALL FENDER GLASS TO FACILITATE REPAIR	New	100.00	0.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	780.00	550.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	600.00	300.00
5	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	0.00
			Gross Labour Cost (\$\$)	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >