

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009898/NEA3Q2**Date:** 02/09/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SKV9021J **Insured Vehicle No :** SLU2419K
 Date of Loss: 22/09/2021 Nature of Claim: TP Claim No: MFL2021D0004119

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV9021J**
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4022698
 Reg. Date: 07/10/2015 (Man. Year: 2015) Chassis No: RU11102695
 Colour: Blue Odometer: 120058 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
 Front Right Side: Dunlop 9 mm Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,967.48	9,136.92	1,830.56	16.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,780.00	1,150.00	39.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,897.48	10,916.92	2,980.56	21.45
Approved Total (Overridden) (S\$)		8,750.00		
(S\$)	13,897.48	8,750.00	5,147.48	37.04
+ GST 7.00/7.00% (S\$)	972.82	612.50	360.32	37.04
Nett Amount (S\$)	14,870.30	9,362.50	5,507.80	37.04
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,069.95		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment: 22/09/2021
 Date Inspected: 23/09/2021 Inspected At: Twincar Automotive Pte Ltd - Kaki Bukit (HQ)
 2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT
 AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV9021J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR CLEANER RESONATOR	Cracked	180.50 FL	*180.50 FL
2	1		*FRONT AIRCON CONDENSER	Deformed	568.10 FL	*568.10 FL
3	1		*FRONT BONNET	Dented	892.30 FL	*854.10 FL
4	2		*FRONT BONNET HINGES L/R	Repair	97.00 FL	*- FL
5	2		*FRONT BONNET INNER RUBBER GUIDE STOPPER L/R	Serviceable	47.60 FL	*- FL
6	2		*FRONT BONNET INNER SIDE SEAL L/R	Necessary	75.00 FL	*75.00 FL
7	2		*FRONT BONNET INNER TOP SEAL L/R	Necessary	46.00 FL	*46.00 FL
8	1		*FRONT BONNET INSULATOR	Serviceable	122.30 FL	*- FL
9	1		*FRONT BONNET MECHANISM LOCK	Bent	95.00 FL	*95.00 FL
10	1		*FRONT BUMPER	Deformed	801.70 FL	*672.30 FL
11	1		*FRONT BUMPER LH FOGLAMP	Cracked	327.70 FL	*237.90 FL
12	1		*FRONT BUMPER LH FOGLAMP BRACKET	Cracked	49.00 FL	*49.00 FL
13	1		*FRONT BUMPER LH FOGLAMP GARNISH	Deformed	45.00 FL	*45.00 FL
14	1		*FRONT BUMPER LOWER GRILLE	Deformed	77.50 FL	*77.50 FL
15	1		*FRONT BUMPER LOWER LID GARNISH	Cracked	381.00 FL	*250.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Dented	321.00 FL	*321.00 FL
17	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Cracked / O/S Serviceable	41.20 FL	*20.60 FL
18	1		*FRONT FENDER ARCH GARNISH L/R	N/S Deformed / O/S Serviceable	440.00 FL	*150.00 FL
19	1		*FRONT GRILLE	Cracked	351.80 FL	*301.20 FL
20	1		*FRONT GRILLE LOGO EMBLEM	Necessary	23.40 FL	*23.40 FL
21	1		*FRONT GRILLE CENTER BRACKET	Cracked	76.00 FL	*76.00 FL
22	1		*FRONT GRILLE CHROME MOULDING L/R	N/S Scratched/ O/S Serviceable	110.00 FL	*55.00 FL
23	1		*FRONT GRILLE OUTER COVER	Deformed	421.00 FL	*300.00 FL
24	1		*FRONT GRILLE TOP GARNISH	Serviceable	85.00 FL	*- FL
25	2		*FRONT HEADLAMP L/R	Cracked	3,569.00 FL	*3,400.00 FL
26	2		*FRONT HEADLAMP LOWER BRACKET L/R	Cracked	70.00 FL	*70.00 FL
27	1		*FRONT HEADLAMP SIDE BRACKET L/R	N/S Cracked / O/S Serviceable	70.00 FL	*35.00 FL
28	1		*FRONT HORN	Cut	110.50 FL	*70.00 FL
29	1		*FRONT LH FENDER	Deformed	580.00 FL	*421.10 FL
30	1		*FRONT LH FENDER INNER SHIELD	Torn	130.00 FL	*130.00 FL
31	1		*FRONT OUTSIDE TEMPERATURE SENSOR	Serviceable	80.00 FL	*- FL
32	1		*FRONT OUTSIDE TEMPERATURE SENSOR BRACKET	Cracked	25.00 FL	*25.00 FL
33	1		*FRONT SUPPORT PANEL	Dented	576.20 FL	*526.90 FL
34	1		*FRONT WIPER GRILLE GARNISH	Cracked	240.00 FL	*240.00 FL
35	1		*RADIATOR (AUTO)	Deformed	1,376.60 FL	*1,242.70 FL
36	1		*RADIATOR SIDE GUIDE L/R	N/S Deformed / O/S Serviceable	63.20 FL	*31.60 FL
37	1		*BATTERY	Deformed	250.00 FS	*150.00 FS
38	1		*SET FRONT BONNET INSULATOR CLIPS	Necessary	50.00 FS	*50.00 FS
39	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

9/2/22, 2:13 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT BUMPER PARKING SENSOR	Deformed	250.00 FS	*180.00 FS
41	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
42	1		*SET FRONT LH FENDER ARCH GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
43	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
44	1		*FRONT NUMBER PLATE	Deformed	25.00 FS	*25.00 FS
45	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
46	1		*SET FRONT WIPER GRILLE GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
47	1		*RADIATOR COOLANT	Necessary	60.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					13,480.60	11,254.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,513.12	2,117.98
Total Parts (\$\$)					10,967.48	9,136.92
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS	New	150.00	100.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)	New	80.00	30.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	800.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	50.00
Gross Labour Cost (\$)			2,930.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >