



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 4805U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP RH	CUT / MTG CRACKED	743.14	743.14
1	FRT BUMPER RH	BENT	649.36	649.36
1	FRT BUMPER RETAINER RH	DISTORTED	89.64	89.64
1	FRT BUMPER COVER RH	SERVICEABLE	42.50	-
1	FRT FENDER RH	TO REPAIR SEE LABOUR	611.42	-
1	FRT BUMPER FOG LAMP	CRACKED	103.40	103.40
	LESS 20% DISCOUNT		-447.89	-
	LESS 25% DISCOUNT		-	-396.39
			1,791.57	1,189.15
	<u>SPECIAL NETT ITEMS</u>			
10	CLIPS,FENDER LINING @\$4.50 (SN)	NECESSARY	45.00	45.00
			45.00	45.00
	<u>LABOUR</u>			
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS,STRAIGHTEN CHASSIS MEMBER,REPAIR/RESHAPE DENTED BODY PANEL INACCORDANCE WITH FACTORY SPECIFICATIONS.REPLACE/REPOSITION DAMAGED PARTS,REFIT ALIGN INTO REFIT ALL NECESSARY COMPONENTS/ATTACHMENT. INCLUSIVE OF THE REPAIR OF FRT FENDER RH. TO SPRAY PAINTING.		600.00	350.00
	TO CHECK WIRING/PROPER FUNCTION ON LIGHT AND ETC.		50.00	20.00
			1,250.00	770.00
	GRAND TOTAL		3,086.57	2,004.15

Report Ref No. CS/SMR21009899/Kuf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00
---	--	--	----------

Report Ref No. CS/SMR21009899/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.