

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION REPORT		
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21009908/Nuce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date:	01/10/2021	
	ATTN: ANG YVON	NE	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 4492G	Veh. Inspected	FBS 1785M	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03H9E	Excess (\$)	0.00	
	Assign From	ANG YVONNE	Assign Date	22/09/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	YAMAHA AEROX	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	MH3SG4620LJ077986	Colour	RED	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	110/80 R14	IRC	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70 R14	IRC	4 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE O/S BODY AND FRONT			
5.	General Information				
	Accident Date	04/09/2021	Inspect Date / Time	23/09/2021 (04:31 PM)	
	Survey held at EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800				
5a.	. Remarks				
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLI	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			

Report Ref No. CS3/ASM21009908/Nuce2

Inspected By

MUHAMMAD NAZRIL BIN ABDULLAH

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser