

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008817/RGA3Q2-1**Date:** 11/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900092171
Claimant Vehicle No :	SKC9019S	Insured Vehicle No :	SKL1276X
Date of Loss:	21/08/2021	Nature of Claim:	TP
		Claim No:	6335439415SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC9019S	Engine No:	CHH279709
Make & Model:	SKODA SUPERB, 2.0 (A)	Chassis No:	TMBBD9NP0J7599465
Reg. Date:	24/08/2018 (Man. Year: 2018)	Odometer:	13827 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,057.49	5,780.84	8,276.65	58.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,320.00	8,700.00	5,620.00	39.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,377.49	14,480.84	13,896.65	48.97
+ GST 7.00/7.00% (S\$)	1,986.42	1,013.66	972.76	48.97
Nett Amount (S\$)	30,363.91	15,494.50	14,869.41	48.97
+ Car Rental (13.0 x S\$120.00/day + 7.00% GST) (S\$)		1,669.20		
Nett Liability (S\$)		17,163.70		

INSPECTION

Date of Assignment:	02/09/2021	
Date Inspected:	02/09/2021	Inspected At: Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR	Repair	3,445.79 FS	*- FS
2	1		*DOOR SEAL	Not Necessary	116.04 FS	*- FS
3	1		*PLUG	Not Necessary	0.47 FS	*- FS
4	1		*ALU-LAMIN INSULATION	Not Necessary	43.65 FS	*- FS
5	1		*CHECK ROD	Not Necessary	66.82 FS	*- FS
6	2		*FILLISTER HD SCREW WITH	Not Necessary	5.28 FS	*- FS
7	2		*OVAL HEXAGON SOCKET HEAD	Not Necessary	2.90 FS	*- FS
8	1		*PROTECTION	Necessary	445.50 FS	*436.83 FS
9	1		*PROTECTION	Necessary	493.55 FS	*479.79 FS
10	2		*LHF DOOR GROMMET	Not Necessary	3.00 FS	*- FS
11	2		*CLIP	Not Necessary	3.82 FS	*- FS
12	2		*OVAL HEXAGON SOCKET HEAD	Not Necessary	2.10 FS	*- FS
13	1		*FOIL	Necessary	82.96 FS	*82.96 FS
14	1		*SECTIONAL LHR FENDER	Bent	1,950.86 FS	*1,950.86 FS
15	1		*ROOF REINF	Not Necessary	47.30 FS	*- FS
16	1		*WATER DRAI	Not Necessary	319.20 FS	*- FS
17	1		*INSERT PLA	Not Necessary	177.22 FS	*- FS
18	1		*CONNECTING	Not Necessary	161.47 FS	*- FS
19	1		*HINGE REIN	Not Necessary	43.05 FS	*- FS
20	1		*BRACKET	Not Necessary	75.64 FS	*- FS
21	1		*INNER PANE	Not Necessary	323.29 FS	*- FS
22	1		*REINFORCEM	Not Necessary	495.64 FS	*- FS
23	1		*BRACKET	Not Necessary	46.32 FS	*- FS
24	1		*REINFORCEM	Not Necessary	743.40 FS	*- FS
25	1		*REINFORCEM	Not Necessary	570.55 FS	*- FS
26	1		*REINFORCEM	Not Necessary	167.53 FS	*- FS
27	1		*WELD STUD	Not Necessary	1.61 FS	*- FS
28	1		*UNBEKANNT	Not Necessary	100.72 FS	*- FS
29	1		*REINFORCEMENT	Not Necessary	130.40 FS	*- FS
30	1		*REINFORCEMENT	Not Necessary	130.40 FS	*- FS
31	1		*WHEEL HOUS	Not Necessary	566.63 FS	*- FS
32	1		*REINFORCEM	Not Necessary	463.98 FS	*- FS
33	1		*2K- INSERT FOAM	Necessary	162.95 FS	*162.95 FS
34	1		*SEALANT CAN BE SPRAYED	Necessary	66.64 FS	*66.64 FS
35	1		*ZINC SPRAY	Necessary	72.72 FS	*72.72 FS
36	1		*2K-BODY ADHESIVE	Necessary	468.68 FS	*468.68 FS
37	1		*ALLOY WHEEL	Scratched	2,045.00 FS	*2,045.00 FS
38	1		*RUBBER VALVE	Necessary	3.85 FS	*3.85 FS
39	4		*RIVETTED CAP NUT	Necessary	10.56 FS	*10.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,057.49** **5,780.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING	New	-	-
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	-	-
3	LABOUR	New	-	-
4	SPRAY PAINTING	New	-	-
5	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
6	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
7	LABOUR	New	5,040.00	4,200.00
8	SPRAY PAINTING	New	4,800.00	2,400.00
9	TRANSFER DOOR MECHANISM PROVIDE CONTRACTOR SERVICE FOR ACCIDENT REPAIR	New	840.00	0.00
10	R&R REAR LUGGAGE TRIM	New	840.00	420.00
11	R&R REAR SEAT	New	840.00	420.00
12	R&R UPHOLSTERY AIG DIRECT	New	840.00	420.00
13	ALIGNMENT	New	360.00	360.00
Gross Labour Cost (\$)			14,320.00	8,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >