

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009911/AUCE2**Date:** 14/10/2022**REFERENCE**

Insured/Claimant:	BENJAMIN CHOY KAI GHIT	Policy No:	7210035130	
Date of Loss:	20/09/2021	Nature of Claim:	OD	Claim No: 2626553387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN1691S	Engine No:	DGK002793
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZF0M2048930
Reg. Date:	26/04/2021 (Man. Year: 2020)	Odometer:	10112 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$220,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R21	Rear Tyre Size:	255/40 R21
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	206,126.31	111,085.95	95,040.36	46.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	72,144.00	48,519.00	23,625.00	32.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	278,270.31	159,604.95	118,665.36	42.64
Approved Total (Overridden) (S\$)		132,000.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	277,970.31	131,700.00	146,270.31	52.62
+ GST 7.00/7.00% (S\$)	19,457.92	9,219.00	10,238.92	52.62
Nett Amount (S\$)	297,428.23	140,919.00	156,509.23	52.62

INSPECTION

Date of Assignment:	23/09/2021	
Date Inspected:	22/09/2021	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	45.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,362.00 FS	*1,089.60 FS
2	1	*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	1	*FRONT BUMPER SECURING STRIP - LH / RH	N/S Cracked	76.00 FS	*31.28 FS
4	2	*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	222.00 FS	*- FS
5	1	*FRONT BUMPER GRILLE - CENTER	Not Necessary	402.00 FS	*- FS
6	2	*FRONT BUMPER PARKING AID SENSOR SUPPORT	Not Necessary	58.00 FS	*- FS
7	1	*FRONT BUMPER SPOILER - CENTER	Not Necessary	866.00 FS	*- FS
8	1	*FRONT BUMPER SPOILER - LH / RH	N/S Missing	452.00 FS	*180.80 FS
9	1	*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	421.00 FS	*- FS
10	1	*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Missing	534.00 FS	*213.60 FS
11	1	*FRONT BUMPER PARKING AID SENSOR SUPPORT - LH / RH	N/S Damaged	68.00 FS	*28.32 FS
12	1	*FRONT BUMPER TRIM - LH / RH	N/S Missing	322.00 FS	*135.20 FS
13	1	*FRONT RADIATOR GRILLE	Not Necessary	3,470.00 FS	*- FS
14	1	*QUATTRO EMBLEM	Not Necessary	106.00 FS	*- FS
15	1	*FRONT BUMPER STRIKER PLATE	Not Necessary	244.00 FS	*- FS
16	4	*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
17	4	*FRONT PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
18	1	*FRONT BUMPER REINFORCEMENT FOAM PIECE	Cracked	183.00 FS	*146.00 FS
19	1	*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	981.00 FS	*- FS
20	1	*FRONT BUMPER BRACKET - LH	Not Necessary	256.00 FS	*- FS
21	2	*FRONT BUMPER GUIDE SECTION - LH / RH	Damaged	78.00 FS	*60.96 FS
22	1	*FRONT BUMPER TOP COVER	Not Necessary	129.00 FS	*- FS
23	1	*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
24	1	*AIR CONDITIONER STICKER	Not Necessary	20.00 FS	*- FS
25	1	*HORN - LH	Not Necessary	195.00 FS	*- FS
26	1	*HORN - RH	Not Necessary	195.00 FS	*- FS
27	1	*BONNET	Distorted	4,058.00 FS	*3,246.40 FS
28	2	*BONNET HINGE - LH / RH	Not Necessary	322.00 FS	*- FS
29	1	*BONNET ATTACHMENT PARTS	Not Necessary	141.00 FS	*- FS
30	1	*BONNET IMPACT PROTECTOR - CENTER / LH / RH (3PCS)	Necessary	84.00 FS	*65.68 FS
31	2	*FRONT FENDER - LH / RH	Distorted	2,854.00 FS	*2,283.20 FS
32	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
33	2	*FRONT FENDER BRACKET - LH / RH	Bent	36.00 FS	*27.52 FS
34	2	*FRONT FENDER BRACE - LH / RH	Bent	450.00 FS	*359.20 FS
35	1	*FRONT FENDER CLOSING ELEMENT - RH	Damaged	105.00 FS	*83.60 FS
36	1	*FRONT FENDER MOUTING BRACKET - RH	Necessary	18.00 FS	*13.76 FS
37	1	*FRONT FENDER FILLER COVER - LH / RH	O/S Deformed	62.00 FS	*49.28 FS
38	1	*FRONT FENDER FILLER TOP COVER - LH / RH	O/S Deformed	80.00 FS	*62.88 FS
39	1	*FRONT FENDER FILLER COVER - OUTER LH / RH	O/S Necessary	156.00 FS	*124.64 FS
40	2	*S-LINE EMBLEM	Necessary	225.00 FS	*204.00 FS
41	2	*HEADLIGHT MOUNTING - LH / RH	Not Necessary	236.00 FS	*- FS
42	2	*FRONT RADIATOR BRACE - LH / RH	Not Necessary	114.00 FS	*- FS
43	1	*HEADLIGHT - LH / RH	N/S Cut	13,978.00 FS	*5,608.80 FS
44	2	*HEADLIGHT CYLINDER - LH / RH	Not Necessary	280.00 FS	*- FS
45	1	*WINDSHIELD WASHER HOSE	Not Necessary	125.00 FS	*- FS
46	1	*HEADLIGHT WASHER HOSE	Not Necessary	68.00 FS	*- FS
47	1	*HEADLIGHT WASHER PUMP	Not Necessary	155.00 FS	*- FS
48	1	*WASHER RESERVOIR	Deformed	235.00 FS	*188.00 FS
49	1	*WINDSHIELD WASHER PUMP	Not Necessary	125.00 FS	*- FS
50	1	*FRONT RADIATOR SUPPORT - LH	Not Necessary	53.00 FS	*- FS
51	1	*FRONT BUMPER SENSOR BRACKET	Not Necessary	16.00 FS	*- FS
52	1	*COOLANT (6PCS)	Necessary	266.00 FS	*212.64 FS
53	4	*FRONT RADIATOR AIR GUIDE - LH / RH / UPPER / LOWER	Not Necessary	192.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	1	*FRONT RADIATOR AIR GUIDE - CENTER	Not Necessary	42.00 FS	*- FS
55	2	*FRONT WHEEL HOUSING LINER - LH / RH	Deformed	528.00 FS	*421.60 FS
56	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	38.00 FS	*- FS
57	1	*FRONT WHEEL SPOILER - LH / RH	N/S Deformed	320.00 FS	*128.00 FS
58	2	*FRONT WHEEL COVER - LH / RH	Distorted	1,264.00 FS	*1,011.20 FS
59	1	*SIDE PANEL FRAME - RH	Distorted	6,944.00 FS	*5,555.20 FS
60	1	*FRONT WINDSCREEN	Necessary	1,561.00 FS	*1,248.80 FS
61	1	*FRONT WINDSHIELD RAIN SENSOR	Necessary	137.00 FS	*109.20 FS
62	1	*FRONT WINDSHIELD RAIN SENSOR SPRING	Necessary	21.00 FS	*16.56 FS
63	1	*FRONT WIPER - RH	Not Necessary	67.00 FS	*- FS
64	1	*PILLAR A REINFORCEMENT - RH OUTER	Dented	1,374.00 FS	*1,099.20 FS
65	1	*REAR SIDE WINDOW - RH	Necessary	832.00 FS	*665.20 FS
66	1	*FUEL FLAP	Dented	323.00 FS	*258.40 FS
67	1	*FUEL FILLING HOUSING	Cracked	155.00 FS	*123.60 FS
68	1	*FRONT DOOR - RH	Distorted	4,085.00 FS	*3,268.00 FS
69	1	*FRONT DOOR - OUTER SEAL RH	Necessary	205.00 FS	*164.00 FS
70	1	*BONDING AGENT	Not Necessary	49.00 FS	*- FS
71	1	*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
72	1	*APPLICATOR	Not Necessary	8.00 FS	*- FS
73	5	*GROMMET	Not Necessary	14.00 FS	*- FS
74	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	264.00 FS	*- FS
75	1	*FRONT DOOR CATCH - RH	Not Necessary	146.00 FS	*- FS
76	4	*FRONT DOOR HINGE - RH UPPER / LOWER	Damaged	184.00 FS	*145.60 FS
77	1	*FRONT DOOR SEAL - INNER RH	Not Necessary	205.00 FS	*- FS
78	1	*FRONT DOOR COVER - RH	Cut	790.00 FS	*632.00 FS
79	1	*FRONT SILL TRIM STRIP - RH	Necessary	591.00 FS	*472.80 FS
80	1	*DATA TAG	Necessary	462.00 FS	*369.60 FS
81	1	*TYRE PRESSURE DATA TAG	Necessary	38.00 FS	*29.84 FS
82	1	*FRONT DOOR HANDLE TRIM - RH	Distorted	128.00 FS	*102.40 FS
83	1	*LOCK CYLINDER WITH HOUSING	Damaged	540.00 FS	*432.00 FS
84	1	*FRONT DOOR HANDLE COVER TRANSPARENT - RH	Damaged	6.00 FS	*4.64 FS
85	1	*FRONT DOOR HANDLE SENSOR - RH	Damaged	228.00 FS	*182.40 FS
86	1	*FRONT DOOR HANDLE EXTERIOR - RH	Cracked	44.00 FS	*34.88 FS
87	2	*DOOR UNDERLAY - FRONT / REAR	Necessary	8.00 FS	*5.76 FS
88	1	*FRONT DOOR MOUNTING BAR	Damaged	164.00 FS	*130.80 FS
89	1	*FRONT WINDOW WITHOUT REGULATOR MOTOR - RH	Damaged	278.00 FS	*222.40 FS
90	1	*FRONT WINDOW WITH REGULATOR MOTOR - RH	Not Necessary	237.00 FS	*- FS
91	1	*FRONT DOOR CONTROL UNIT - RH	Not Necessary	751.00 FS	*- FS
92	1	*FRONT DOOR LOCK - RH	Damaged	535.00 FS	*428.00 FS
93	1	*FRONT DOOR STRIKER	Not Necessary	69.00 FS	*- FS
94	1	*WING MIRROR - RH	Distorted	1,749.00 FS	*1,399.20 FS
95	1	*WING MIRROR CAP - RH	Distorted	491.00 FS	*392.80 FS
96	1	*WING MIRROR GLASS - RH	Distorted	1,908.00 FS	*1,526.40 FS
97	1	*CONTACT HOUSING 16 PIN	Necessary	6.00 FS	*4.72 FS
98	1	*FRONT DOOR CONER TRIM - RH	Cracked	46.00 FS	*36.24 FS
99	1	*FRONT WINDOW TRIM STRIP - RH	Dented	340.00 FS	*272.00 FS
100	1	*FRONT WINDOW GUIDE - RH	Cut	488.00 FS	*390.00 FS
101	1	*FRONT WINDOW INNER SEAL - RH	Cut	113.00 FS	*90.00 FS
102	1	*FRONT DOOR SEAL - RH	Necessary	15.00 FS	*11.36 FS
103	1	*FRONT B PILLAR TRIM - RH	Cut	197.00 FS	*157.20 FS
104	1	*FRONT WINDOW SLOT SEAL - RH	Dented	616.00 FS	*492.40 FS
105	1	*FRONT DOOR WINDOW - RH	Shattered	298.00 FS	*238.00 FS
106	1	*FRONT DOOR TRIM - RH	Cut	2,310.00 FS	*1,848.00 FS
107	1	*FRONT DOOR WINDOW TRIM - RH	Cut	144.00 FS	*114.80 FS
108	1	*FRONT DOOR ARMREST - RH	Not Necessary	591.00 FS	*- FS
109	1	*FRONT DOOR HANDLE COVER - RH	Not Necessary	158.00 FS	*- FS
110	1	*FRONT DOOR TRIM INSERT ALUMINIUM - RH OUTER	Cut	629.00 FS	*503.20 FS
111	1	*SET FRONT DOOR WIRING	Not Necessary	577.00 FS	*- FS
112	1	*REAR DOOR - RH	Distorted	4,085.00 FS	*3,268.00 FS
113	1	*REAR DOOR - OUTER SEAL RH	Necessary	205.00 FS	*164.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
114	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
115	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
116	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
117	1		*REAR DOOR SEALING STRIP - RH	Necessary	17.00 FS	*12.96 FS
118	3		*GROMMET	Necessary	9.00 FS	*6.72 FS
119	1		*REAR DOOR ATTACHMENT PART	Not Necessary	222.00 FS	*- FS
120	1		*REAR DOOR CATCH	Necessary	146.00 FS	*116.40 FS
121	1		*REAR DOOR SEAL - INNER	Not Necessary	205.00 FS	*- FS
122	1		*SILL PANEL SEAL - RH	Necessary	253.00 FS	*202.00 FS
123	4		*REAR DOOR HINGE - RH UPPER / LOWER	Damaged	184.00 FS	*145.60 FS
124	1		*REAR DOOR COVER - RH	Cut	689.00 FS	*551.20 FS
125	1		*REAR DOOR HANDLE TRIM PLATE - RH	Distorted	275.00 FS	*219.60 FS
126	1		*REAR DOOR HANDLE HOUSING - RH	Damaged	18.00 FS	*14.16 FS
127	1		*REAR DOOR HANDLE COVER TRANSPARENT - RH	Necessary	6.00 FS	*4.64 FS
128	1		*REAR DOOR HANDLE SENSOR - RH	Not Necessary	228.00 FS	*- FS
129	1		*REAR DOOR HANDLE EXTERIOR - RH	Damaged	44.00 FS	*34.88 FS
130	1		*REAR DOOR MOUNTING BAR - RH	Not Necessary	164.00 FS	*- FS
131	1		*REAR WINDOW WITHOUT REGULATOR MOTOR - RH	Not Necessary	314.00 FS	*- FS
132	1		*REAR WINDOW WITH REGULATOR MOTOR - RH	Not Necessary	351.00 FS	*- FS
133	1		*REAR DOOR CONTROL UNIT - RH	Not Necessary	751.00 FS	*- FS
134	1		*REAR DOOR LOCK - RH	Not Necessary	661.00 FS	*- FS
135	1		*REAR DOOR STRIKER	Not Necessary	69.00 FS	*- FS
136	1		*REAR WINDOW GUIDE - RH	Not Necessary	488.00 FS	*- FS
137	1		*REAR WINDOW TRIM STRIP - RH	Cut	297.00 FS	*236.00 FS
138	1		*REAR WINDOW INNER SEAL - RH	Not Necessary	205.00 FS	*- FS
139	1		*REAR WINDOW SLOT SEAL - RH	Warped	616.00 FS	*516.00 FS
140	2		*REAR DOOR SEAL - RH	Necessary	30.00 FS	*22.72 FS
141	1		*REAR B PILLAR TRIM - RH	Cut	222.00 FS	*177.60 FS
142	1		*REAR C PILLAR TRIM - RH	Not Necessary	149.00 FS	*- FS
143	1		*REAR WINDOW GUIDE RAIL - RH	Not Necessary	72.00 FS	*- FS
144	1		*REAR DOOR WINDOW - RH	Not Necessary	298.00 FS	*- FS
145	1		*REAR DOOR - LH	Dented	4,085.00 FS	*3,268.00 FS
146	1		*REAR DOOR OUTER SEAL - LH	Necessary	205.00 FS	*164.00 FS
147	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
148	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
149	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
150	1		*REAR DOOR SEALING STRIP - LH	Necessary	17.00 FS	*12.96 FS
151	3		*GROMMET	Necessary	9.00 FS	*6.72 FS
152	1		*REAR DOOR ATTACHMENT PART	Not Necessary	222.00 FS	*- FS
153	1		*REAR DOOR CATCH - LH	Necessary	146.00 FS	*116.40 FS
154	1		*REAR DOOR COVER - LH	Deformed	689.00 FS	*551.20 FS
155	1		*REAR BUMPER - UPPER	Deformed	2,397.00 FS	*1,917.60 FS
156	1		*REAR BUMPER - LOWER	Not Necessary	1,182.00 FS	*- FS
157	1		*TAIL LIGHT - UPPER RH	Not Necessary	5,746.00 FS	*- FS
158	1		*TAIL LIGHT - LOWER RH	Not Necessary	699.00 FS	*- FS
159	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	1,166.00 FS	*932.80 FS
160	1		*ROOF TOP PANEL	Repair	4,646.00 FS	*- FS
161	1		*INNER ROOF RAIL	Not Necessary	1,836.00 FS	*- FS
162	6		*INNER ROOF RAIL NUT	Not Necessary	213.00 FS	*- FS
163	1		*HEAD AIRBAG UNIT - LH / RH	Activated	3,726.00 FS	*2,980.80 FS
164	1		*AIRBAG CONTROL UNIT	Activated	2,112.00 FS	*1,689.60 FS
165	1		*AIRBAG CRASH SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
166	1		*CENTRAL PROTECTION FUSE	Necessary	533.00 FS	*426.80 FS
167	2		*FRONT SEATBELT - LH / RH	Activated	2,234.00 FS	*1,787.20 FS
168	2		*FRONT SEATBELT ADJUSTER - LH / RH	Damaged	342.00 FS	*273.60 FS
169	1		*ROOF HEADLINER	Crumpled	3,660.00 FS	*3,083.20 FS
170	2		*FRONT ROOF HANDLE - RH / LH	Damaged	283.00 FS	*226.40 FS
171	2		*REAR ROOF HANDLE - RH / LH	Damaged	284.00 FS	*226.40 FS
172	2		*A-PILLAR TRIM - UPPER LH / RH	Deformed	474.00 FS	*379.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
173	2	*UPPER B-PILLAR TRIM - LH / RH	Not Necessary	602.00 FS	*- FS
174	2	*C-PILLAR TRIM - LH / RH	Not Necessary	628.00 FS	*- FS
175	2	*D-PILLAR TRIM - LH / RH	Not Necessary	408.00 FS	*- FS
176	1	*A-PILLAR TRIM - LOWER RH	Not Necessary	149.00 FS	*- FS
177	1	*B-PILLAR TRIM - LOWER RH	Not Necessary	234.00 FS	*- FS
178	1	*REAR WHEEL HOUSING TRIM - RH	Not Necessary	252.00 FS	*- FS
179	1	*REAR FENDER INNER TRIM - RH	Not Necessary	75.00 FS	*- FS
180	1	*DASHBOARD	Not Necessary	6,972.00 FS	*- FS
181	1	*DASHBOARD CENTER AIR VENT	Not Necessary	2,272.00 FS	*- FS
182	1	*DASHBOARD AIR VENT	Not Necessary	591.00 FS	*- FS
183	1	*STEERING WHEEL	Bent	2,374.00 FS	*1,899.20 FS
184	1	*FRONT SEAT - RH (NPA)	Cut	2,636.00 FS	*2,108.80 FS
185	1	*FRONT SEAT PADDING - RH (NPA)	Not Necessary	0.00 FS	*- FS
186	1	*FRONT SEAT COVER - RH (NPA)	Cut	2,096.00 FS	*1,676.80 FS
187	1	*FRONT CENTER CONSOLE	Not Necessary	815.00 FS	*- FS
188	1	*FRONT CENTER CONSOLE INSERT	Not Necessary	402.00 FS	*- FS
189	1	*FRONT CENTER CONSOLE TRIM	Cut	741.00 FS	*592.80 FS
190	1	*FRONT CENTER CONSOLE INSERT STOWAGE	Not Necessary	60.00 FS	*- FS
191	1	*FRONT CENTER CONSOLE STAWAGE COMPARTMENT	Not Necessary	144.00 FS	*- FS
192	1	*ASSEMBLY CARRIER	Bent	1,891.00 FS	*1,512.80 FS
193	1	*FRONT WISHBONE LINK - LH	Bent	539.00 FS	*430.80 FS
194	1	*FRONT SUSPENSION GUIDE - LH	Bent	943.00 FS	*754.40 FS
195	2	*UPPER SUSPENSION GUIDE - FRONT / REAR LH	Bent	720.00 FS	*576.00 FS
196	1	*WHEEL BEARING HOUSING - LH	Damaged	1,136.00 FS	*908.80 FS
197	1	*SWIVEL JOINT	Damaged	193.00 FS	*154.40 FS
198	1	*WHEEL HUB	Damaged	479.00 FS	*383.20 FS
199	1	*FRONT WHEEL BEARING	Damaged	246.00 FS	*196.80 FS
200	1	*SUSPENSION FORKS - LH	Bent	366.00 FS	*292.40 FS
201	1	*COUPLING ROD	Bent	127.00 FS	*101.20 FS
202	1	*FRONT ANTI - ROLL BAR	Not Necessary	433.00 FS	*- FS
203	1	*AXLE ASSEMBLY	Damaged	2,865.00 FS	*2,292.00 FS
204	1	*SHOCK ABSORBER	Bent	1,483.00 FS	*1,186.40 FS
205	1	*LEVEL SENSOR WITH POLES	Damaged	535.00 FS	*428.00 FS
206	1	*STEERING GEAR WITH TRACK ROD JOINT	Not Necessary	6,782.00 FS	*- FS
207	1	*TRACK ROD	Bent	134.00 FS	*106.00 FS
208	1	*TIE ROD END - LH	Bent	197.00 FS	*157.20 FS
209	1	*ROOF HEADER PANEL	Not Necessary	262.00 FS	*- FS
210	1	*INNER ROOF REINFORCEMENT	Not Necessary	247.00 FS	*- FS
211	1	*PACK ADHESIVE	Not Necessary	73.00 FS	*- FS
212	1	*ROOF PANEL BONDING ADHESIVE	Not Necessary	23.00 FS	*- FS
213	1	*PRIMER	Not Necessary	20.00 FS	*- FS
214	1	*FRONT DOOR COVER - LH	Deformed	790.00 FS	*632.00 FS
215	5	*STATIC MIXER	Necessary	56.00 FS	*44.40 FS
216	10	*BLINDER RIVET STUD	Necessary	62.00 FS	*49.60 FS
217	1	*FRONT NO PLATE (NPA)	Not Necessary	0.00 FS	*- FS
218	1	*FRONT 2 RIMS - LH / RH (3PCS)(NPA)	Cut	981.31 FS	*981.31 FS
219	1	*REAR RIM - LH (NPA)	Cut	0.00 FS	*- FS
220	2	*FRONT 2 TYRES - LH / RH (NPA)	Not Necessary	0.00 FS	*- FS
221	1	*REAR TYRE - LH (NPA)	Cut	510.00 FS	*510.00 FS
222	1	*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
223	1	*CRAVITY WAX	Necessary	140.00 FS	*140.00 FS
224	1	*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
225	1	*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
226	1	*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
227	1	*REAR 1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
228	1	*SUNDRIES	Necessary	1,500.00 FS	*395.28 FS
229	1	*LED LIGHT - RH FRONT (Supplementary)	Necessary	67.00 FS	*55.52 FS
230	1	*INNER ACTUATOR - RH (Supplementary)	Not Necessary	255.00 FS	*- FS
231	1	*TRAY - RH LOWER (Supplementary)	Cut	548.00 FS	*438.00 FS
232	1	*DASHBOARD ALUMINIUM TRIM - RH (Supplementary)	Not Necessary	447.00 FS	*- FS
233	1	*DASHBOARD ALUMINIUM TRIM - LH (Supplementary)	Not Necessary	1,068.00 FS	*- FS
234	1	*PADDING FOR SEAT DEPTH (Supplementary)	Not Necessary	142.00 FS	*- FS
235	1	*DISPLAY AND CONTROL PANEL WITH CU (A/C) (Supplementary)	Not Necessary	3,121.00 FS	*- FS
236	1	*DRIVE SHAFT SCREW (6PCS)(Supplementary)	Necessary	46.00 FS	*37.04 FS
237	1	*BRAKE HOSE - LH FRONT (Supplementary)	Damaged	72.00 FS	*56.96 FS
238	1	*ENGINE MOUNTING - LH (Supplementary)	Not Necessary	370.00 FS	*- FS
239	1	*SUBFRAME CONSOLE - LH (Supplementary)	Not Necessary	562.00 FS	*- FS
240	1	*FRONT DOOR PERIPHERAL LIGHT - RH	Damaged	72.00 FS	*57.28 FS
241	1	*SIGN - UNLEADED PETROL (Supplementary)	Necessary	30.00 FS	*24.00 FS
242	1	*7-SPEED DUAL CLUTCH GEARBOX (Supplementary)	Damaged	32,056.00 FS	*26,644.80 FS
243	5	*DUAL CLUTCH TRANSMISSION FLUID (Supplementary)	Not Necessary	630.00 FS	*- FS
244	4	*MTF TRANSMISSION FLUID (Supplementary)	Not Necessary	546.00 FS	*- FS
245	1	*SET GEARBOX BOLT (Supplementary)	Necessary	110.00 FS	*86.40 FS
246	1	*ENGINE MOUNTING - RH (Supplementary)	Damaged	370.00 FS	*335.60 FS
247	1	*ENGINE MOUNTING BOLT (6PCS)(Supplementary)	Necessary	114.00 FS	*90.64 FS
248	1	*FRONT RADIATOR - LOCK CARRIER	Cracked	1,400.00 FS	*1,120.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 206,126.31 111,085.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PLACE THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	800.00	800.00
2	TO PLACE THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
3	TO REMOVE CHECK TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
4	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
5	TO RENEW FRONT WINDSCREEN TO FACILITATE RENEWAL OF RHS A-PILLAR	New	480.00	480.00
6	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN AND ALL THE AFFECTED DOOR WINDOW GLASS	New	400.00	400.00
7	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
8	TO REMOVE AND REPLACE FRONT WINDSCREEN SENSOR FOIL AND RESET SYSTEM	New	300.00	300.00
9	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION WITH SUBFRAME	New	2,400.00	2,400.00
10	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGE	New	400.00	280.00
11	TO REMOVE CENTER CONSOLE, INSTRUMENTS PANELS AND CLUSTERS. RENEW DASHBOARD SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS	New	3,200.00	3,200.00
12	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. RENEW WHERE NECESSARY	New	1,800.00	1,800.00
13	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER, RHS FRONT DOOR AND HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD ROOFTOP PANEL, RHS A PILLAR, RHS UPPER A-PILLAR REINFORCEMENT, RHS SILL PANEL AND RHS B PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	16,800.00	8,500.00
14	TO RESPRAY FRONT BUMPER, BOTH FRONT LOWER SPOILERS BOTH FRONT FENDER, BONNET, HINGES, BOTH FRONT DOORS, DOOR COVER, DOOR HANDLE, RHS WING MIRROR COVER, RHS A-PILLAR, RHS SILL PANEL, RHS B-PILLAR, ROOFTOP PANEL, BOTH ROOF CHANNELS. DOOR ENTRANCES AND BOTH FRONT WHEEL ARCH TRIMS	New	12,400.00	7,200.00
15	TO CARRY OUT CLEANUP FOR WINDOW GLASSES IN THE INTERIOR	New	280.00	280.00
16	TO RENEW LHS FRONT RIM, RHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	600.00	600.00
17	TO REMOVE AND REINSTALL BOTH ROOFTOP RAIL. RENEW WHERE NECESSARY	New	280.00	140.00
18	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LIC KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
19	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
20	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
21	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY AND LUGGAGE COMPARTMENT TRIMS	New	1,200.00	1,200.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
22	TO REMOVE AND TRANSFER RHS REAR DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
23	TO DISMANTLE AND RENEW REAR BUMPER AND BOTH REAR DOORS. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	4,000.00
24	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, RHS REAR FENDER, DRAIN CHANEL, DOOR ENTRANCES, REAR END PANELLING, RHS REAR DOOR, LHS REAR DOOR, DOOR COVERS, DOOR HANDLE, FUEL FILLER CAP AND BOTH REAR WHEEL ARCH TRIMS	New	8,300.00	4,575.00
25	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
26	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE.	New	800.00	250.00
27	TO RENEW AND REINSTALL AIRCON CONDENSER ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,700.00	0.00
28	TO REPAIR LHS FRONT LOWER A-PILLAR (Supplementary)	New	400.00	250.00
29	TO RESPRAY LHS FRONT LOWER A-PILLAR (Supplementary)	New	800.00	550.00
30	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT A/C VACUUM AND REGAS (R1324YF) (Supplementary)	New	2,000.00	2,000.00
31	TO SUSPEND ENGINE ASSY, REMOVE AND REINSTALL CARDAN SHAFT. TO DISMANTLE AND RENEW GEARBOX ASSY. REINSTALL ALL PARTS REMOVED (Supplementary)	New	2,800.00	2,800.00
Gross Labour Cost (S\$)			72,144.00	48,519.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >