

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009913/AVCE2

Date: 18/11/2021

REFERENCE

Insured/Claimant: TEY KHANG WEEI (ZHENG KANGWEI)
Date of Loss: 20/09/2021

Policy No: 7210081490
Nature of Claim: OD Claim No: 6439157695SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH6068T**
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZDC40473
Reg. Date: 29/07/2021 (Man. Year: 2021) Chassis No: WAUZZZF33M1120276
Colour: Grey Odometer: 1275 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$160,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,306.00	2,654.80	15,651.20	85.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,672.00	2,122.00	3,550.00	62.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,978.00	4,776.80	19,201.20	80.08
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	23,578.00	4,376.80	19,201.20	81.44
+ GST 7.00/7.00% (S\$)	1,650.46	306.38	1,344.08	81.44
Nett Amount (S\$)	25,228.46	4,683.18	20,545.28	81.44

INSPECTION

Date of Assignment: 23/09/2021

Date Inspected: 22/09/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,815.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	118.00 FS	*- FS
4	1		*FRONT BUMPER LOWER TRIM (GREY)	Not Necessary	356.00 FS	*- FS
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	217.00 FS	*- FS
6	2		*FRONT BUMPER GRILLE SENSOR SUPPORT - LH / RH	Not Necessary	50.00 FS	*- FS
7	1		*FRONT BUMPER LOWER GRILLE CENTER COVER	Not Necessary	51.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	190.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Not Necessary	763.00 FS	*- FS
10	2		*FRONT BUMPER AIR GRILLE - LH / RH	Not Necessary	306.00 FS	*- FS
11	2		*FRONT BUMPER AIR GRILLE TRIM (GREY) - LH / RH	Not Necessary	328.00 FS	*- FS
12	2		*FRONT BUMPER SENSOR SUPPORT - LH / RH	Not Necessary	50.00 FS	*- FS
13	1		*RADIATOR GRILLE	Cut	1,928.00 FS	*1,542.40 FS
14	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	244.00 FS	*- FS
15	1		*FRONT CAMERA CAP	Not Necessary	56.00 FS	*- FS
16	1		*FRONT CAMERA BRACKET	Not Necessary	41.00 FS	*- FS
17	1		*RADIATOR GRILLE INNER COVER	Cut	244.00 FS	*194.80 FS
18	1		*FRONT CAMERA	Not Necessary	1,141.00 FS	*- FS
19	1		*FRONT BUMPER CARRIER FOAM	Not Necessary	102.00 FS	*- FS
20	1		*FRONT BUMPER CARRIER	Not Necessary	916.00 FS	*- FS
21	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
22	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
23	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
24	2		*FRONT PARKING AID SENSOR - LH / RH (NPA)	Not Necessary	0.00 FS	*- FS
25	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
26	1		*HORN - RH	Not Necessary	130.00 FS	*- FS
27	1		*HORN BRACKET - RH	Not Necessary	22.00 FS	*- FS
28	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	236.00 FS	*- FS
29	1		*HEADLIGHT - RH	Not Necessary	5,589.00 FS	*- FS
30	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	210.00 FS	*- FS
31	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	80.00 FS	*- FS
32	3		*RADIATOR AIR GRILLE - LH / RH / UPPER	Not Necessary	118.00 FS	*- FS
33	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,072.00 FS	*857.60 FS
34	1		*FRONT NO. PLATE	Dented	60.00 FS	*60.00 FS
35	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 18,306.00 2,654.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH WHEEL ARCH TRIMS	New	3,000.00	950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,672.00	2,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >