

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009914/AQCN2**Date:** 28/01/2022**REFERENCE**

Insured/Claimant:	THAM WAI LEONG	Policy No:	1800079954	
Date of Loss:	18/09/2021	Nature of Claim:	OD	Claim No: 9447368537SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC5466L		
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Engine No:	CYG023417
Reg. Date:	07/07/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ4GXJN039737
Colour:	White	Odometer:	77223 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$137,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,597.00	816.00	29,781.00	97.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	2,502.00	2,250.00	47.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,349.00	3,318.00	32,031.00	90.61
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	34,949.00	2,918.00	32,031.00	91.65
+ GST 7.00/7.00% (S\$)	2,446.43	204.26	2,242.17	91.65
Nett Amount (S\$)	37,395.43	3,122.26	34,273.17	91.65

INSPECTION

Date of Assignment:	23/09/2021		
Date Inspected:	22/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,268.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	543.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE-LOWER CENTER	Not Necessary	128.00 FS	*- FS
4	14		*FRONT BUMPER LOCKING CLIP	Not Necessary	55.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	219.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Deformed	945.00 FS	*756.00 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,934.00 FS	*- FS
8	1		*RADIATOR GRILLE COVER	Not Necessary	36.00 FS	*- FS
9	2		*RADIATOR GRILLE PARKING AID SUPPORT-LH/RH	Not Necessary	132.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	1,144.00 FS	*- FS
11	2		*FRONT BUMPER LOWER COVER-LH/RH	Not Necessary	102.00 FS	*- FS
12	1		*FOAM FILLER PIECE	Not Necessary	237.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	872.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
15	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
16	2		*FRONT BUMPER PARKING AID (Npa)	Not Necessary	0.00 FS	*- FS
17	2		*FRONT WHEEL SPOILER-LH/RH	Not Necessary	528.00 FS	*- FS
18	2		*HEADLIGHT MOUNTING-LH/RH	Not Necessary	236.00 FS	*- FS
19	2		*LED HEADLIGHT-LH/RH	Not Necessary	19,080.00 FS	*- FS
20	1		*HEADLIGHT HOSE	Not Necessary	478.00 FS	*- FS
21	1		*HORN-RH	Not Necessary	47.00 FS	*- FS
22	1		*HORN BRACKET-RH	Not Necessary	29.00 FS	*- FS
23	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	58.00 FS	*- FS
24	1		*RADIATOR AIR GUIDE-CENTER	Not Necessary	29.00 FS	*- FS
25	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
26	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **30,597.00** **816.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER	New	1,600.00	850.00
5	TO CARRY OUT CALIBRATION SETTING FOR FRONT RADAR SENSOR AND DISTANCE REGULATION	New	480.00	480.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,752.00	2,502.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >