

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009916/AVCN2**Date:** 12/11/2021**REFERENCE****Insured/Claimant:** KOO CHONG EN, JOEL (QIU CHONG'EN)**Policy No:** 1900114974**Date of Loss:** 26/08/2021**Nature of Claim:** OD**Claim No:** 0631445626SG**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SMN8800C**Make & Model:** AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)**Engine No:** DAX056215**Reg. Date:** 28/06/2019 (Man. Year: 2019)**Chassis No:** WAUZZZF1K2091752**Colour:** Blue**Odometer:** 20278 km**Engine Capacity:** 1984 cc**Market Value/New Car Price:** S\$170,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes **Engine Modification:**

No

Pre-accident Condition:**CONDITION OF TYRES****Front Tyre Size:** 235/55R19**Rear Tyre Size:** 235/55R19**Front Left Side:** Michelin 6 mm**Rear Left Side:** Michelin 6 mm**Front Right Side:** Michelin 6 mm**Rear Right Side:** Michelin 6 mm*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,603.00	2,279.44	19,323.56	89.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,152.00	3,722.00	7,430.00	66.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,755.00	6,001.44	26,753.56	81.68
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	32,255.00	5,501.44	26,753.56	82.94
+ GST 7.00/7.00% (S\$)	2,257.85	385.10	1,872.75	82.94
Nett Amount (S\$)	34,512.85	5,886.54	28,626.31	82.94

INSPECTION**Date of Assignment:** 23/09/2021**Date Inspected:** 22/09/2021 **Inspected At:**

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,362.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	293.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	113.00 FS	*- FS
4	1		*FRONT BUMPER SECURING STRIP-RH	Not Necessary	38.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	581.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE END CAP-RH	Not Necessary	92.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	39.00 FS	*- FS
8	1		*FRONT FENDER-RH	Dented	1,427.00 FS	*1,141.60 FS
9	1		*FRONT FENDER BRACE-RH	Not Necessary	225.00 FS	*- FS
10	1		*FRONT FENDER BRACKET-RH	Not Necessary	18.00 FS	*- FS
11	1		*FRONT FENDER FLEDGE COVER SHORT-RH	Deformed	31.00 FS	*24.64 FS
12	1		*FRONT FENDER FLEDGE COVER LONG-RH	Not Necessary	40.00 FS	*- FS
13	1		*S-LINE EMBLEM	Necessary	128.00 FS	*102.00 FS
14	1		*HEADLIGHT MOUNTING-RH	Not Necessary	118.00 FS	*- FS
15	1		*LED HEADLIGHT-RH	Not Necessary	8,191.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	278.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH	Not Necessary	38.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER-RH	Not Necessary	155.00 FS	*- FS
19	2		*FRONT WHEEL ARCH COVER-LH/RH	N/s Necessary/O/s Deformed	1,264.00 FS	*1,011.20 FS
20	1		*FRONT WING MIRROR MOUNTING-RH	Not Necessary	1,749.00 FS	*- FS
21	1		*FRONT DOOR COVER-RH	Not Necessary	790.00 FS	*- FS
22	1		*BONNET	Repair	4,058.00 FS	*- FS
23	1		*BONNET ATTACHMENT PARTS	Not Necessary	141.00 FS	*- FS
24	2		*BONNET IMPACT PROTECTION-LH/RH	Not Necessary	56.00 FS	*- FS
25	1		*BONNET IMPACT PROTECTION-CENTER	Not Necessary	28.00 FS	*- FS
26	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 21,603.00 2,279.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM TO FACILITATE THE RENEWAL OF RHS WING MIRROR ASSY	New	280.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER BONNET AND RHS HEADLIGHT.TO REPAIR RHS FRONT DOOR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,600.00	1,000.00
5	TO RESPRAY FRONT BUMPER,FRONT LOWER SPOILER,RHS FRONT FENDER,BONNET,RHS FRONT DOOR,RHS WING COVER,DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS	New	6,200.00	2,050.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			11,152.00	3,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >