

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21009917/BVF3N2**Date:** 01/06/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001889662
Claimant Vehicle No :	SMS2958U	Insured Vehicle No :	SLH4260E
Date of Loss:	19/09/2021	Nature of Claim:	TP
		Claim No:	262941

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS2958U	Engine No:	1NZR785472
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Chassis No:	NHP1707173524
Reg. Date:	20/02/2020 (Man. Year: 2019)	Odometer:	118835 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	KAPSEN 4 mm	Rear Left Side:	Firenza 4 mm
Front Right Side:	KAPSEN 4 mm	Rear Right Side:	Firenza 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,149.75	3,317.02	5,832.73	63.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,280.00	1,350.00	51.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,779.75	4,597.02	7,182.73	60.98
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	11,779.75	3,650.00	8,129.75	69.01
+ GST 7.00/7.00% (S\$)	824.58	255.50	569.08	69.01
Nett Amount (S\$)	12,604.33	3,905.50	8,698.83	69.01

INSPECTION

Date of Assignment:	23/09/2021	
Date Inspected:	24/09/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2022)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS2958U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	581.90 FL	*581.90 FL
2	1		*FRONT BUMPER TOP RUBBER SEAL	No such part	55.00 FL	*- FL
3	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	67.20 FL	*67.20 FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	67.20 FL	*67.20 FL
5	1		*FRONT BUMPER RH SIDE GARNISH	Necessary	156.70 FL	*90.40 FL
6	1		*RH HEADLAMP ASSY	Broken	987.00 FL	*727.20 FL
7	1		*FRONT RH FENDER	Dented	551.00 FL	*551.00 FL
8	1		*FRONT RH FENDER HYBRID EMBLEM	Necessary	59.00 FL	*42.10 FL
9	1		*FRONT RH FENDER SPLASH SHIELD	Torn	176.00 FL	*153.20 FL
10	1		*FRONT RH DOOR	Dented	1,112.00 FL	*1,112.00 FL
11	1		*FRONT RH DOOR FRAME BLACK TAPE	Necessary	51.00 FL	*51.00 FL
12	1		*FRONT RH DOOR INNER TRIM BOARD	Not Damaged	1,077.00 FL	*- FL
13	1		*FRONT RH SIDE MIRROR ASSY	Broken	1,157.80 FL	*866.10 FL
14	1		*FRONT RH SIDE MIRROR COVER	Missing	105.70 FL	*73.40 FL
15	1		*FRONT RH DOOR LOCK	Not Damaged	657.00 FL	*- FL
16	1		*FRONT RH RIM CAP	No such part	174.80 FL	*- FL
17	1		*FRONT RH STEEL RIM	Not Damaged	280.00 FL	*- FL
18	1		*FRONT RH WHEEL BEARING	Not Damaged	109.00 FL	*- FL
19	1		*FRONT RH LOWER ARM	Not Damaged	497.00 FL	*- FL
20	1		*FRONT RH KNUCKLE ARM	Not Damaged	593.80 FL	*- FL
21	1		*FRONT RH SHOCK ABSORBER	Not Damaged	457.00 FL	*- FL
22	1		*FRONT RH TIE ROD END	Not Damaged	109.00 FL	*- FL
23	1		*FRONT RH DRIVE SHAFT	Not Damaged	1,099.80 FL	*- FL
24	1		*STEERING RACK AND PINION	Not Damaged	1,331.10 FL	*- FL
25	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
26	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*FRONT RH TYRE	Not Damaged	280.00 FS	*- FS
28	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
29	1		*BRAKE FLUID	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,028.00	4,412.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,878.25	1,095.68
Total Parts (\$\$)	9,149.75	3,317.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	70.00	0.00
5	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	280.00	0.00
6	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
7	REMOVE AND REINSTALL FRONT RH DOOR INNER MECHANISM TO NEW DOOR	New	100.00	80.00
Gross Labour Cost (\$\$)			2,630.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >