



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 8552L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DRIVER SEAT (NPA)	BURNT	-	-
1	FRONT ROOF PANEL AND UPHOLSTERY (NPA)	BURNT	-	-
1	REAR PANEL GLASS (NPA)	BURNT	-	-
1	BED FRAME (NPA)	BURNT	-	-
1	BED FRAME CHECKERED PLATE (NPA)	BURNT	-	-
1	CHECKERED PLATE RH SIDE GATE (NPA)	BURNT	-	-
1	CARGO FLOOR PANEL (NPA)	BURNT	-	-
1	WOODEN RAILING (NPA)	BURNT	-	-
			-	-
	<u>LABOUR</u>			
	LABOUR. (NPA)		-	-
	SPRAY PAINTING. (NPA)		-	-
	LUMP SUM.		4,000.00	4,000.00
			4,000.00	4,000.00
	GRAND TOTAL		4,000.00	4,000.00
	RECOMMENDED COST OF REPAIRS			4,000.00

Report Ref No. CS4/ASM21009921/Etce2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.