

SSA File No: Steve

File: C S4/ASM 21009921/ETC

ASSIGNMENT

24/11/04

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No: S1M03IBE

Sum Insured: Excess: 0

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3-Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

YL 8552L

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Capstar

c.c

2953

Colour:

Gold

NC: Insured / Std / NI / NA

Sp. Reading

45979

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM1SF4F 232 085 3148

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rm or

Tyre Size: F:

F:

R:

11

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

17/9/21

connect 3

D.O.I.

27/9/21

Survey held at

Des. of Damagos: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-19K

lump sum @ \$4000
red:0;0%

Date/Time File Pass to?

☐ : Procl. Report

1)

☐ : Final Report

Date/Time File Return to?

2)

Request Form:

Living Sign / U.C.:

Days Of Repair: 10

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp \$

☐ : Interview \$

☐ : Tech. Insp \$

☐ : Wash and

Survey Fee:

Transportation:

\$ - RS - \$

Fluorid

Obser

Test

fire report:170
investigaton \$500

CONNECT 3

566 Woodlands Road (Manda Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

Steve (LKK)

27/9/21, 11.00am

00-MAL

L'scan - ?

L/S

QT21/YL8552L/ODC

AXA Insurance Singapore Pte Ltd

8 Shenton Way, #27-01 AXA Tower

Singapore 068811

QUOTATION

10 dys

My AL My

Dear Sir,

Cost of Repair to Vehicle YL8552L

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Driver seat / Bunt	1		
2.	Front roof panel and upholstery / Bunt	1		
3.	Rear panel glass / Bunt	1		
4.	Bed frame / Bunt	1		
5.	Bed frame Checkered plate / Bunt	1		
6.	Checkered plate rh side gate / Bunt	1		
7.	Cargo floor panel / Bunt	1		
8.	Wooden railing / Bunt	1		
9.	Labour	1		
10.	Spray painting	1		
11.	Lump sum			\$4,000.00
SUB-TOTAL				S\$4,000.00

• Price before 7% gst

Thank you.

Yours faithfully,

Winnie Chai
HP: 9850-9666

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: