

SSS File No: Steve

File: C S4/ASM 21009921/ETC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3-Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YL 8552L

Yr Regn: 24/11/04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Capstar

c.c. 2953

Colour: Gold

NC: Insured / Std / NI / NA

Sp. Reading: 45979

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM1SF4F 23L 085 J148

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rm or

Tyre Size: F: 195R15C

R: 11

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4

mm

R/Bal. 4

mm

L/Bal. 4

mm

L/Bal. 4

mm

D.O.A. 17/9/21

connect 3

D.O.I. 27/9/21

Survey held at

Des. of Damagos: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-19K

Date/Time File Pass to?

☐ : Procl. Report

1)

☐ : Final Report

Date/Time File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp \$

☐ : Interview \$

☐ : Tech. Invs \$

☐ : Wash and

Survey Fee:

Transportation

Planks

Offset

Total

CONNECT 3

566 Woodlands Road (Manda Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

Steve (LKK)

27/9/21, 11.00am

00-MAL

L'scan - ?

L/S

QT21/YL8552L/ODC

AXA Insurance Singapore Pte Ltd

8 Shenton Way, #27-01 AXA Tower

Singapore 068811

QUOTATION

10 dys

My AL My

Dear Sir,

Cost of Repair to Vehicle YL8552L


With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Driver seat / Bunt	1		
2.	Front roof panel and upholstery / Bunt	1		
3.	Rear panel glass / Bunt	1		
4.	Bed frame / Bunt	1		
5.	Bed frame Checkered plate / Bunt	1		
6.	Checkered plate rh side gate / Bunt	1		
7.	Cargo floor panel / Bunt	1		
8.	Wooden railing / Bunt	1		
9.	Labour	1		
10.	Spray painting	1		
11.	Lump sum			\$4,000.00
SUB-TOTAL				S\$4,000.00

• Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: