LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21009922/UQF3E2

Date: 03/11/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001622139

Claimant Vehicle No: SLM8774L

Date of Loss: 21/09/2021 Nature of Claim: TP Claim No: 263026

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK747S

 Make & Model:
 MERCEDES-BENZ A200, 1.3 AMG LINE (A)
 Engine No:
 28291480091670

 Reg. Date:
 24/04/2019 (Man. Year: 2019)
 Chassis No:
 WDD1770872J077561

Colour: Blue Odometer: 30238 km

Engine Capacity: 1332 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R19 Rear Tyre Size: 245/35Z R19
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,834.40	1,209.60	6,624.80	84.56
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,000.00	420.00	2,580.00	86.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,834.40	1,629.60	9,204.80	84.96
	Approved Total (Overridden) (S\$)		1,300.00		
	Nett Amount (S\$)	10,834.40	1,300.00	9,534.40	88.00

INSPECTION

Date of Assignment: 23/09/2021

Date Inspected: 23/09/2021 Inspected At: 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53

Repairer: Zoom Autowerks Pte Ltd

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Oct 2021)

Parts: 144 MERCEDES-BENZ A200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK747S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Dented / Deformed	1,284.00 FL	*1,284.00 FL
1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	98.00 FL	*- FL
1		*FRONT BUMPER CENTRE BRACKET	Not Necessary	286.00 FL	*- FL
1		*FRONT BUMPER MOUNT RH	Not Necessary	197.00 FL	*- FL
1		*FRONT BUMPER TOW GARNISH	Not Necessary	78.00 FL	*- FL
1		*FRONT BUMPER AIR-GARNISH TOP RH	Not Necessary	108.00 FL	*- FL
1		*FRONT BUMPER AIR-GARNISH LOWER RH	Not Necessary	105.00 FL	*- FL
1		*FRONT BUMPER ANGLE SENSOR RH	Not Necessary	275.00 FL	*- FL
1		*SET FRONT BUMPER SENSOR BRACKET	Not Necessary	97.00 FL	*- FL
1		*FRONT BUMPER SPONGE	Not Necessary	286.00 FL	*- FL
1		*FRONT BUMPER REINFORCEMENT	Not Necessary	496.00 FL	*- FL
1		*FRONT BUMPER BADGE	Not Necessary	118.00 FL	*- FL
1		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
1		*RADIATOR GRILLE ASSY	Not Necessary	986.00 FL	*- FL
1		*FRONT HEADLAMP ASSY	Not Necessary	3,886.00 FL	*- FL
1		*FRONT HEADLAMP BRACKET RH	Not Necessary	256.00 FL	*- FL
1		*FRONT NUMBER PLATE W/GARNISH	Not Necessary	80.00 FS	*-FS
nchise	part. S=SpcN	lett. L=ListItemDisc.	-		
			Sub Total (S\$)	8,696.00	1,344.00
- List Item Discount on L Items 10.00/10.00% (S\$)				861.60	134.40
			Total Parts (S\$)	7,834.40	1,209.60
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 *FRONT BUMPER SIDE RETAINER RH 1 *FRONT BUMPER CENTRE BRACKET 1 *FRONT BUMPER MOUNT RH 1 *FRONT BUMPER TOW GARNISH 1 *FRONT BUMPER AIR-GARNISH TOP RH 1 *FRONT BUMPER AIR-GARNISH LOWER RH 1 *FRONT BUMPER ANGLE SENSOR RH 1 *SET FRONT BUMPER SENSOR BRACKET 1 *FRONT BUMPER SPONGE 1 *FRONT BUMPER REINFORCEMENT 1 *FRONT BUMPER BADGE 1 *FRONT BUMPER CLIPS 1 *RADIATOR GRILLE ASSY 1 *FRONT HEADLAMP ASSY 1 *FRONT HEADLAMP BRACKET RH 1 *FRONT NUMBER PLATE W/GARNISH nchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER SIDE RETAINER RH Not Necessary 1 *FRONT BUMPER CENTRE BRACKET Not Necessary 1 *FRONT BUMPER MOUNT RH Not Necessary 1 *FRONT BUMPER TOW GARNISH Not Necessary 1 *FRONT BUMPER AIR-GARNISH TOP RH Not Necessary 1 *FRONT BUMPER AIR-GARNISH LOWER RH Not Necessary 1 *FRONT BUMPER AIR-GARNISH LOWER RH Not Necessary 1 *FRONT BUMPER ANGLE SENSOR RH Not Necessary 1 *SET FRONT BUMPER SENSOR BRACKET Not Necessary 1 *FRONT BUMPER SENSOR BRACKET Not Necessary 1 *FRONT BUMPER REINFORCEMENT Not Necessary 1 *FRONT BUMPER BADGE Not Necessary 1 *FRONT BUMPER BADGE Not Necessary 1 *FRONT BUMPER CLIPS Necessary 1 *FRONT BUMPER CLIPS Necessary 1 *FRONT HEADLAMP ASSY Not Necessary 1 *FRONT HEADLAMP BRACKET RH Not Necessary 1 *FRONT HEADLAMP BRACKET RH Not Necessary 1 *FRONT HEADLAMP BRACKET RH Not Necessary 1 *FRONT NUMBER PLATE W/GARNISH Not Necessary 1 *FRONT NUMBER PLATE W/GARNISH Not Necessary 1 *FRONT NUMBER PLATE W/GARNISH Not Necessary 1 *FRONT HEADLAMP BRACKET RH Not Necessary 1 *FRONT NUMBER PLATE W/GARNISH Not Necessary	1 *FRONT BUMPER Dented / Deformed 1,284.00 FL 1 *FRONT BUMPER SIDE RETAINER RH Not Necessary 98.00 FL 1 *FRONT BUMPER CENTRE BRACKET Not Necessary 286.00 FL 1 *FRONT BUMPER CENTRE BRACKET Not Necessary 197.00 FL 1 *FRONT BUMPER MOUNT RH Not Necessary 78.00 FL 1 *FRONT BUMPER TOW GARNISH Not Necessary 78.00 FL 1 *FRONT BUMPER AIR-GARNISH LOWER RH Not Necessary 108.00 FL 1 *FRONT BUMPER AIR-GARNISH LOWER RH Not Necessary 275.00 FL 1 *FRONT BUMPER ANGLE SENSOR BRACKET Not Necessary 97.00 FL 1 *SET FRONT BUMPER SENSOR BRACKET Not Necessary 286.00 FL 1 *FRONT BUMPER SENSOR BRACKET Not Necessary 286.00 FL 1 *FRONT BUMPER REINFORCEMENT Not Necessary 496.00 FL 1 *FRONT BUMPER BADGE Not Necessary 60.00 FL 1 *FRONT BUMPER CLIPS Necessary 60.00 FL 1 *FRONT HEADLAMP ASSY N

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REPAIR & RENEW FRONT AFFECTED ACCID AREAS	ENT New	1,400.00	200.00
2	TO PUTTY, SPRAY PAINT ON AFFECTED ACCIDENT AREA	S New	1,200.00	200.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO RE-POSITION, DRILL & INSTALL ANGLE SENSOR	New	150.00	0.00
5	TO RUST PROOF AFFECTED AREAS	New	200.00	0.00
	Gr	oss Labour Cost (S\$)	3,000.00	420.00
	Report was unsubmitted	during this print-out.		

< END OF ESTIMATES >