

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21009924/UTF3N2**Date:** 04/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	GBH2284T	Insured Vehicle No :	SLP8842H
Date of Loss:	21/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004117

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH2284T	Engine No:	K9KE628D422742
Make & Model:	NISSAN NV200, 1.5 (A)	Chassis No:	VSKYBAM20Z0156943
Reg. Date:	21/03/2018 (Man. Year: 2017)	Odometer:	75175 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,781.08	4,948.96	3,832.12	43.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,930.00	1,580.00	45.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,291.08	6,878.96	5,412.12	44.03
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	12,291.08	5,500.00	6,791.08	55.25

INSPECTION

Date of Assignment:	23/09/2021	Automobile Hub Enterprise
Date Inspected:	23/09/2021 Inspected At:	1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Oct 2021)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2284T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE-RH	Badly Dented	1,053.70 FL	*1,053.70 FL
2	1		*TAILGATE INNER TRIM RH	Not Necessary	138.10 FL	*- FL
3	1		*TAILGATE SEAL	Twisted	88.60 FL	*88.60 FL
4	1		*TAILGATE INNER LOCK-LOWER	Twisted/Shorted	180.90 FL	*115.00 FL
5	1		*TAILGATE-LH	Badly Dented	1,560.90 FL	*1,469.50 FL
6	1		*TAILGATE LOGO	Necessary	79.90 FL	*79.90 FL
7	1		*TAILGATE EMBLEM NV200	Necessary	145.20 FL	*145.20 FL
8	1		*TAILGATE OUTER GARNISH	Not Necessary	351.50 FL	*- FL
9	1		*TAILGATE WIPER ARM	Not Necessary	110.20 FL	*- FL
10	1		*TAILGATE WIPER ARM COVER	Not Necessary	18.60 FL	*- FL
11	1		*TAILGATE WIPER MOTOR	Not Necessary	431.20 FL	*- FL
12	1		*TAILGATE INNER LOCK-LOWER	Twisted/Shorted	180.90 FL	*115.00 FL
13	1		*TAILGATE INNER LOCK ACTUATOR	Not Necessary	281.30 FL	*- FL
14	1		*TAILGATE INNER TRIM N/S	Deformed/Torn	216.60 FL	*216.60 FL
15	1		*TAILGATE CHECKER	Not Necessary	86.90 FL	*- FL
16	1		*TAILGATE OPENING W/STRIP	Twisted	211.20 FL	*211.20 FL
17	1		*TAILLAMPS-L/R	N/s Cracked	566.40 FL	*283.20 FL
18	1		*REAR BUMPER	Dented	632.70 FL	*485.90 FL
19	2		*REAR BUMPER REFLECTORS-L/R	Cracked	137.20 FL	*137.20 FL
20	1		*REAR BUMPER INNER FOAM	Torn	194.70 FL	*94.00 FL
21	2		*REAR BUMPER SIDE RETAINERS-L/R	Necessary	85.80 FL	*85.80 FL
22	1		*REAR END PANEL	Dented	411.50 FL	*345.00 FL
23	1		*REAR END PANEL INNER MEMBER	Repair	841.80 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	128.60 FL	*128.60 FL
25	1		*REAR EXHAUST PIPE	Not Necessary	274.60 FL	*- FL
26	1		*REAR SPARE WHEEL CARRIER	Not Necessary	311.20 FL	*- FL
27	1		*REAR SPARE WHEEL LOCK CATCH	Not Necessary	110.60 FL	*- FL
28	2		*TAILGATE HINGES-LOWER-L/R	Not Necessary	220.40 FL	*- FL
29	2		*SET TAILGATE GLASS SEALANT-L/R	Necessary	120.00 FS	*80.00 FS
30	2		*SET TAILGATE GLASS FOAM TAPES-L/R	Necessary	90.00 FS	*70.00 FS
31	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
32	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
33	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
35	1		*REAR STICKER 6 PAX	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,686.20	5,454.40
- List Item Discount on L Items 10.00/10.00% (S\$)	905.12	505.44
Total Parts (S\$)	8,781.08	4,948.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	60.00	20.00
2	TO REMOVE,REFIX TAILGATE GLASS-L/R	New	300.00	200.00
3	TO REMOVE,REFIX INTERIOR TRIMS DOOR MECHANISM	New	120.00	100.00
4	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	100.00	0.00
5	TO REMOVE,REFIX REAR REVERSE SENSOR	New	80.00	50.00
6	TO RESPRAY UNDERCOATING	New	150.00	80.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
8	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	680.00
Gross Labour Cost (\$\$)			3,510.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >